Submit 1 Copy To Appropriate District Office	State of New N	· ·		Form C-103	
District I	Energy, Minerals and Natural Resources		October 13, 2009 WELL API NO.		
1625 N. French Dr., Hobbs, NM 88240 District II	OIL CONSERVATION DIVISION 1220 South St. Francis Dr.		30-025-41268		
1301 W. Grand Ave., Artesia, NM 88210 District III				5. Indicate Type of Lease	
1000 Rio Brazos Rd., Aztec, NM 87410			STATE	FEE 🖳	
<u>District IV</u> 1220 S. St. Francis Dr., Santa Fe, NM	Santa Fe, NM 87505			6. State Oil & Gas Lease No.	
87505					
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH			7. Lease Name of	7. Lease Name or Unit Agreement Name Bertha J Barber	
			Rertha I Barber		
PROPOSALS.) 1. Type of Well: Oil Well Gas Well Injection well		8. Well Number			
1. Type of Well. On Well Oas Well I injection well		9. OGRID Number 873			
Apache Corp.					
3. Address of Operator	ldress of Operator		10. Pool name or Wildcat		
	O box Drawer D Monument NM 88265		Eunice Monument G/SA		
4. Well Location					
Unit Letter D :	820feet from the	N line and	415f	eet from the	
Eline	m 11 200				
Section 8	Township 20S 11. Elevation (Show whether L	Range 37I		Lea County	
	11. Elevation (Snow whether L)K, KKD, K1, GK, eu			
The state of the s			perfusion a	de 200 de la company de la com	
12. Check A	ppropriate Box to Indicate	Nature of Notice	Report or Other	· Data	
•			· •		
NOTICE OF INT			BSEQUENT RE		
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WO		ALTERING CASING DAND A	
TEMPORARILY ABANDON PULL OR ALTER CASING	CHANGE PLANS MULTIPLE COMPL	CASING/CEMEI	RILLING OPNS.□ NT JOB □	P AND A	
PULL OR ALTER CASING DOWNHOLE COMMINGLE	MOLTIPLE COMPL []	CASING/CEME	1130p 🖂		
BOWNITOLE COMMINGLE	· ·				
OTHER:	2.		TA wellbore	. 🔲 .	
13. Describe proposed or comple					
of starting any proposed wor	rk). SEE RULE 19.15.7.14 NM	AC. For Multiple C	ompletions: Attach	wellbore diagram of	
proposed completion of reco	implection.	•			
Perfs 3385-3657					
Move in Weatherford to set CIBP @ $\!$		Pressure test to 680 a	# and chart for 32 mi	nutes with a 5#	
Loss during test. Apache requests a T	A status for this well.				
			. 1		
		r Tamporary A	111/2017		
•	This Approval C	tunires	1114/20		
	This Approval of Abandonment	EXPILES	7 1		
		-	•	INC Now Well	
			E-PERIVITI I	ING New Well P&A TA 7- M	
			CSNG &	Loc Chng	
Spud Date:	Rig Release	Date:	ReComp	Add New Well	
			Recomp Cancl Well	Add New Well	
			Carier vveii_	Create Pool	
I hereby certify that the information a	above is true and complete to the	e best of my knowled	lge and belief.	DROWN VAID	
\bigcirc	\mathcal{M}			K 13 B 11 A S	
SIGNATURE	TITLE	Instrument Tech	D	DATE 7.15-14	
DIGITATORE .	111111	monument reen	D	7.13 /	
Type or print name Jim Ellison	E-mail add	ress: _JD.Ellison@a	pacheccorp.com_PI	HONE:	
For State Use Only			•	1 1	
APPROVED BY: YVIAIA	LANGUM TITLE D	UT SO	011/11/11/11/11/11/11/11/11/11/11/11/11/	ATE 2/14/7015	
APPROVED BY: Conditions of Approval (if any):	VAID WILLE	me. Sup	D.	ALE ~ 1 LU 5	
Conditions of Experoval (if any).)	*	E =	B 1 7 2015 / A	
•			rc	DE LEVIS LAND	
				A NIN I	

