Form 3160-5 (August 2007)

UNITED STATES DEPARTMENT OF THE INTERIOR

BUREAU OF LAND MANAGEMENT

FORM APPROVED OMB NO. 1004-0135 Expires: July 31, 2010

	Expires:	July
Lease Ser	ial No.	
NATE COR	รกรกร	

SUNDRY NOTICES AND REPORTS ON WELLS	
Do not use this form for proposals to drill or to re-enter a	an
abandoned well. Use form 3160-3 (APD) for such proposa	als.

abandoned we	6. If Indian, Allottee of	or Tribe Name				
SUBMIT IN TRI	7. If Unit or CA/Agreement, Name and/or No. 8910086380					
Type of Well ☐ Gas Well ☐ Oth	8. Well Name and No. PEARSALL QN SAND UT 13					
Name of Operator LEGACY RESERVES OPERA	Contact: ATING LÆ-Mail: blewis@le	BLAIN LEWIS gacylp.com		9. API Well No. 30-025-00833-00-S1		
3a. Address 303 W WALL SUITE 1600 MIDLAND, TX 79702	3b. Phone No. (include area code) Ph: 432-689-424005600		10. Field and Pool, or Exploratory PEARSALL			
4. Location of Well (Footage, Sec., T	FEB 2 3 2015		11. County or Parish, and State			
Sec 4 T18S R32E SENW 165			LEA COUNTY, NM			
	·		n —	<u> </u>		
12. CHECK APPI	ROPRIATE BOX(ES) TO	O INDICATE NATURE OF	NOTICE, R	EPORT, OR OTHE	R DATA	
TYPE OF SUBMISSION	TYPE OF ACTION					
☑ Notice of Intent	☐ Acidize	□ Deepen	☐ Produc	tion (Start/Resume)	☐ Water Shut-Off	
	☐ Alter Casing	☐ Fracture Treat	☐ Reclam	ation	■ Well Integrity	
☐ Subsequent Report	Casing Repair	■ New Construction	□ Recom	plete	☐ Other	
☐ Final Abandonment Notice	Change Plans	R-Plug-and-Abandon	T Tempo	rarily Abandon		
·	☐ Convert to Injection	☐ Plug Back	□ Water I	Disposal		
13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.)						
BLM approval is respectfully requested to lay down all the current rods, pump and tubing equipment; install a cast iron bridge plug (CIBP)on wireline at 3660' above the current Queen Sand perforations from 3712'-3744'; dump 35' of cement on top of the CIBP using a dump bailer for PBTD 3625'; and perform a mechanical integrity test (MIT) to 500 psig for 30 minutes on the 5 1/2" production casing. If a successful MIT is obtained, we propose that the well be temporarily abandoned pending the evaluation of possible recompletion or a proposal to plug and abandon the wellbore. If the well fails the MIT test, a proposal to plug and abandon the wellbore will be promptly submitted for BLM approval.						
			SE	E ATTACHED	FOR	
			CC	ONDITIONS O	F APPROVAL	

•			CONDITIO	JN3 OF A	IPPRUVAL		
Asseval.	Subject to Successful A	177					
14. I hereby certify	that the foregoing is true and correct. Electronic Submission #269573 verific For LEGACY RESERVES OPE Committed to AFMSS for processing by	d by the	BLM Well Information System				
Name (Printed/Ty	ped) BLAIN LEWIS	Title	SENIOR ENGINEER				
Signature	(Electronic Submission)	Date	10/09/2014				
THIS SPACE FOR FEDERAL OR STATE OFFICE USE							
Approved By	James a. Omo	Title	SAET		2-8-15 Date		
Conditions of approval certify that the applican	, if any, are attached. Approval of this notice does not warrant or at holds legal or equitable title to those rights in the subject lease applicant to conduct operations thereon.	ı	CFO	Kg			
7:/ 10110.0/0	1001 1771 1011 0 0 0 1 1010 1 1 1			<u> </u>	Col. III is 1		

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

BUREAU OF LAND MANAGEMENT Carlsbad Field Office 620 East Greene Street Carlsbad, New Mexico 88220 575-234-5972

Temporary Abandonment of Wells on Federal Lands Conditions of Approval

A temporarily abandoned well is defined as a completion that is not capable of production in paying quantities but which may have value as a service well. Pursuant to 43 CFR 3162.3-4 (c), no well may be temporarily abandoned for more than 30 days without the prior approval of the authorized officer.

Temporary Abandonment (TA) status approval requires a successful mechanical or casing integrity test as follows:

- 1. A Notice of Intent (NOI) Sundry Notice (Form 3160-5) requesting approval to run a mechanical integrity test (MIT) or casing integrity test (CIT).
- 2. A description of the temporary abandonment procedure.
 - a. A bridge plug or packer must be installed as close to 50 feet above any open perforations or open hole as possible. If a cement plug is used, the top of the cement must be verified by tagging.
 - b. The wellbore must be filled with corrosion inhibited fluid and pressure tested to 500 psi. The casing shall be capable of holding this pressure for at least 30 minutes with a 10% allowable leakoff.
 - c. All downhole production/injection equipment (tubing, rods, etc.) shall be removed from the casing if they are not isolated by a packer.
 - d. A bradenhead test must be conducted. If the test indicates a problem exists, a remedial plan and time frame for remediation shall be submitted within ninety (90) days of the test.
 - e. Contact the appropriate BLM office at least 24 hours prior to the scheduled Casing Integrity. Test. For wells in Eddy County, 575-361-2822; Lea County 575-393-3612.
- 3. Provides justification why the well should be temporarily abandoned rather than permanently plugged and abandoned and an estimated date that the well will be returned to beneficial use or plugged and abandoned.

Wells that successfully pass the casing integrity test may be approved for Temporary Abandonment (TA) status provided that the operator:

- Submits a subsequent Sundry Notice (Form 3160-5) requesting TA approval with well bore diagram with all perforations and CIBP's and tops of cement on CIBP's.
- 2. Describes the temporary abandonment procedure.
- Attaches a clear copy or the original of the pressure test chart.
- Give justification to allow well to be place in TA status and plan for future use of well with time frame that well will be place back on line or plans to P&A well will be submitted.

If the well does not pass the casing integrity test, then the operator shall within 30 days submit to BLM for approval one of the following:

- 1. A procedure to repair the casing so that a TA approval can be granted.
- 2. A procedure to plug and abandon the well.