Form 3160-5 (March 2012)

## UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

| OCD | Hobbs |
|-----|-------|
|-----|-------|

FORM APPROVED OMB No. 1004-0137 Expires: October 31, 2014

5. Lease Serial No. NMLC 032581B

6. If Indian, Allottee or Tribe Name

## SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to re-enter an

ge 2.
HOBBS OCH. If Unit of CA/Agreement, Name and/or No. abandoned well. Use Form 3160-3 (APD) for such proposals. SUBMIT IN TRIPLICATE - Other instructions on page 2. 1. Type of Well AR 09 20 Maralo Sholes B #2 Oil Well Gas Well Other SWD (SWD-1127) 2. Name of Operator OWL SWD Operating, LLC 3b. Phone No. (include are part) 10. Field and Pool or Exploratory Area 3a. Address 8214 Westchester Drive .lalmat 214-292-2011 Dallas, TX 75225 4. Location of Well (Footage, Sec., T.,R.,M., or Survey Description) 660 FSL & 660 FEL, Section 25, 125S, R36E 11. County or Parish, State Lea County, NM 12. CHECK THE APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT OR OTHER DATA TYPE OF SUBMISSION TYPE OF ACTION ☐ Deepen Water Shut-Off Acidize Production (Start/Resume) ✓ Notice of Intent Alter Casing Fracture Treat Well Integrity Reclamation Other Change of Operator Casing Repair New Construction Recomplete Subsequent Report Change Plans Plug and Abandon Temporarily Abandon Plug Back Final Abandonment Notice Convert to Injection Water Disposal 13. Describe Proposed or Completed Operation: Clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection.) As required by 43 CFR 3100.0-5(a) and 43 CFR 3162.3 we are notifying you of a change of operator on the referenced Well. OWL SWD Operating, LLC, as new operator, accepts all applicable terms, conditions, stipulations and restrictions concerning operations conducted on the lease portion of lease described. OWL SWD Operating, LLC meets federal bonding requirements: OPER. OGRID NO. 2 BLM Bond File No: NMB001181 Effective Date: July 1, 2014 SEE ATTACHED FOR CONDITIONS OF A SWD-1127 14. I hereby certify that the foregoing is true and correct. Name (Printed/Typed) Title Signature Date THIS SPACE FOR FEDERAL OR STATE OFFICE USE Approved by Title Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would Office

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false,

(Instructions on page 2)

entitle the applicant to conduct operations thereon.

fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

## BUREAU OF LAND MANAGEMENT CARLSBAD FIELD OFFICE

620 E. Greene St Carlsbad, NM 88220 Ph: (575) 234-5972

## **Conditions of Approval for Change of Operator**

- 1. Tank battery must be bermed/diked (must be able to contain 1 1/2 times the volume of the largest tank).
- 2. Submit for approval of water disposal method.
- 3. Submit updated facility diagrams as per Onshore Order #3
- 4. This agency shall be notified of any spill or discharge as required by NTL-3A.
- 5. All outstanding environmental issue must be addressed within 90 days. Contact Jim Amos for inspection and to resolve environmental issues. 575-234-5909
- 6. Install legible well sign on location with operator name, well name and number, lease number, unit number, 1/4 1/4, section, township, and range. NMOCD requires the API number on well signs.
- 7. Subject to like approval by NMOCD.
- 8. All Reporting to ONRR (OGOR Reports) must be brought current within 30 days of this approval including any past history.
- 9. If this well is incapable of producing in paying quantities submit NOI to plug and abandon this well or obtain approval to do otherwise within 90 days.
- 10. Submit plan for approval of well operations for all TA/SI wells within 30 days of this approval to change operator.
- 11. If not in place acquire operating rights on this lease within 30 days with BLM office in Santa Fe, NM.