Submit 1 Copy To Appropriate District Office	State of New Mexico		Form C-103	
District I	Energy, Minerals and Natural Resources		October 13, 2009	
1625 N. French Dr., Hobbs, NM 88240	Hobbs, NM 88240		WELL API NO.	
District II 1301 W. Grand Avc., Artesia, NM 88210	M 88210 OIL CONSERVATION DIVISION		30-025-04141	
District III	1220 South St. Francis Dr.		5. Indicate Type of L	
1000 Rio Brazos Rd., Aztec, NM 87410	Santa Fe, NM 87505		STATE 🗹	FEE
District IV 1220 S. St. Francis Dr., Santa Fe, NM	•		6. State Oil & Gas Le	ease No.
87505		•		
SUNDRY NOTICES AND REPORTS ON WELLS  (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)			7. Lease Name or Unit Agreement Name  North Monument G/SA Unit Blk. 19	
1. Type of Well: Oil Well Gas Well			8. Well Number 6	
				72
Apache Corp.	p. WAR U 9 (2015		9. OGRID Number 873	
3. Address of Operator		10. Pool name or Wildcat		
P O box Drawer D Monument NM 8	8265	RECEIVED	Eunice Monument G/	SA
4. Well Location	,			
Unit Letter F :	1980feet from theN	line and	1980 feet	from the
Wline				
Section 1	Township 20S	Range 36E		Lea County
	11. Elevation (Show whether DR	R, RKB, RT, GR, etc.	.)	
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data				
12. Check A	propriate Box to indicate is	valuic of fronce,	Report of Other Da	ıa
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:				
PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐ REMEDIAL WORK			RK 🔲 AL	TERING CASING
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐ COMMENCE DRILLING OPNS.☐ P AND A [				ND A
PULL OR ALTER CASING	MULTIPLE COMPL	CASING/CEMEN	IT JOB	
DOWNHOLE COMMINGLE				
	· _		,	_
OTHER:	(Classic et al.	OTHER:	. 4	
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of				
proposed completion or recompletion.  Perfs 3460' – 3615'				
Plan to miru & pooh with rods & tubing. MIRU wire line truck & set CIBP @ +- 3400'. Load the casing with packer fluid, Pressure test the casing to 500 psi,& chart the results for 30 minutes.				
Tressure test the earning to 500 poi, a chart the results for 50 minutes.				
Condition of Approval: notify				
C.O.ASUBMIT WELLBORE DIAGRAM  OCD Hobbs office 24 hours				
prior of running MIT Test & Chart				
		prior or ru	ining	_
<u> </u>			<u> </u>	
Spud Date:	Rig Release D	ate:		•
'				
I hereby certify that the information above is true and complete to the best of my knowledge and belief.				
SIGNATURE				
לבר נוונו הרד				
Type or print nameJim Ellison E-mail address: _JD.Ellison@apacheccorp.com_ PHONE: 575-441-7734				
For State Use Only  M 1 M R				
APPROVED BY: Makey & Brown TITLE Dist. Supervisor DATE 3/11/2015 Conditions of Approval (if any)				
Conditions of Approval (if any)				