Submit 1 Copy To Appropriate District	State of New Mexico	Form C-103	
Office <u>District I</u> – (575) 393-6161	Energy, Minerals and Natural Resources	Revised July 18, 2013	
1625 N. French Dr., Hobbs, NM 88240		WELL API NO.	
<u>District II</u> - (575) 748-1283 811 S. First St., Artesia, NM 88210	OIL CONSERVATION DIVISION	30-025-42142	
District III – (505) 334-6178	1220 South St. Francis Dr.	5. Indicate Type of Lease	
1000 Rio Brazos Rd., Aztec, NM 87410	Santa Fe, NM 87505	STATE STATE	
<u>District IV</u> – (505) 476-3460 1220 S. St. Francis Dr., Santa Fe, NM	5ana 1 e, 14141 67505	6. State Oil & Gas Lease No.	
87505	NOTE AND DEPONTS ON WEST A	V0-8658	
1	FICES AND REPORTS ON WELLS OSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A	7. Lease Name or Unit Agreement Name	
DIFFERENT RESERVOIR. USE "APPL	JICATION FOR PERMIT" (FORM C-101) FOR SUCH	Wool Head "20" State	
PROPOSALS.) 1. Type of Well: Oil Well	Gas Well Other	8. Well Number	
1. Type of wen. On wen	Gas well Other	3	
2. Name of Operator		9. OGRID Number	
1	Amtex Energy, Inc.	000785	
3. Address of Operator		10. Pool name or Wildcat	
1	P.O. Box 3418, Midland, Texas 79702	WC-025 G-10 S213328O: Wolfcamp	
4. Well Location		Working	
Unit Letter M: 330' feet from the S line and 330' feet from the W line			
Section 20	Township 21S Range 33E NMI		
	11. Elevation (Show whether DR, RKB, RT, GR, etc.		
	3739.5' GR		
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data			
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:			
PERFORM REMEDIAL WORK	_ , , , , , , , , , , , , , , , , , , ,		
TEMPORARILY ABANDON		RILLING OPNS. PAND A	
PULL OR ALTER CASING	=	_	
DOWNHOLE COMMINGLE			
CLOSED-LOOP SYSTEM	<u></u>		
OTHER:	- .	pletion Operations	
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date			
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of			
proposed completion or recompletion.			
1 MIDII Test Intermediate Coning to 2 500 msi for massaure test 72 agains to 5 000 msi			
 MIRU. Test Intermediate Casing to 2,500 psi & pressure test 7" casing to 5,000 psi. Perforate from 12,200' to 12,250', with 91 holes at 120° phasing, 3JSPF. 			
3. Acidize w/ 3,000 gal. 15% Hcl Acid. Fracture stimulate with 309,529 gal. fluid carrying 97,920 lbs. of 100 mesh			
sand and 189,980 lbs. of Premium 20/40 proppant.			
4. RIH w/ packer on Wireline and set packer at 12,170' (bottom of packer).			
5. RIH w/ 2.875", 6.5#, L-80, 8rd tubing and connect to packer with the On/Off Tool.			
6. Nipple-up wellhead and tie in flowline and place well on production.			
o. Tupple up wellieut and the many will alle place well on procueus.			
Spud Date: 10-23-2014	Rig Release Date: 12-13-20	14	
I hereby certify that the information above is true and complete to the best of my knowledge and belief.			
Thereoff county and the interminant countries and compress of the countries and countr			
1. C. I. A.			
SIGNATURE WWW.	H. DWUSL TITLE President	DATE 07/17/15	
~ xxxxx.	I Savings Email address have a Company	DIJONE (423) 506 0047	
Type or print name William J. Savage E-mail address: bsavage@amtexenergy.com PHONE: (432) 686-0847			
For State Use Only			
APPROVED BY:	TITLE Petroleum Eng	ineer DATE 07/17/15	
Conditions of Approval if any).			