Office Office	State of New Mo	exico	Form C-103				
District 1 – (575) 393-6161	Energy, Minerals and Nati	ural Resources	Revised July 18, 2013				
1625 N. French Dr., Hobbs, NM 88240		:	WELL API NO.				
<u>District II</u> – (575) 748-1283 811 S. First St., Artesia, NM 88210	OIL CONSERVATION	JDIVISION	30-025-25207				
District III – (505) 334-6178	1220 South St. Fra		5. Indicate Type of Lease				
1000 Rio Brazos Rd., Aztec, NM 87410			STATE STATE FEE				
District IV - (505) 476-3460	Santa Fe, NM 8	7303	6. State Oil & Gas Lease No.				
1220 S. St. Francis Dr., Santa Fe, NM 87505			B-2244				
	ICES AND REPORTS ON WELLS	S	7. Lease Name or Unit Agreement Name				
(DO NOT USE THIS FORM FOR PROPO	OSALS TO DRILL OR TO DEEPEN OR PL ICATION FOR PERMIT" (FORM C-101) F	UG BACK TO A OR SUCH	NORTH VACUUM ABO NORTH UNIT				
1. Type of Well: Oil Well	Gas Well Other	HOBBS OCD\	8. Well Number #3				
2. Name of Operator		JUL 2 7 2015	9. OGRID Number 277558				
LIME ROCK RESOURCES II-	A, L.P. /	JUL 27 ZUID	10 D 1 W'11				
3. Address of Operator	Himma Paranta and NBA 07401		10. Pool name or Wildcat				
c/o Mike Pippin LLC, 3104 N. Su	llivan, Farmington, NM 8/401	RECEIVED	North Vacuum Abo (61760)				
4. Well Location							
	: 2180 feet from the North		_feet from the <u>West</u> line				
Section 12	Township 17-S	Range 34-E	NMPM Lea County				
	11. Elevation (Show whether DR 4030' GL	R, RKB, RT, GR, etc.)					
12. Check	Appropriate Box to Indicate N	Vature of Notice,	Report or Other Data				
NOTICE OF II	NTENTION TO:						
PERFORM REMEDIAL WORK			IITTING <swdinjection></swdinjection>				
		REI CONVE	RSION RBDMS				
		CO RETUR	N TO TA				
PULL OR ALTER CASING	- -	CSNG	CHG LOC				
DOWNHOLE COMMINGLE		INT TO					
CLOSED-LOOP SYSTEM ○ OTHER: P&A		OThen.					
	nerations (Clearly state all pertinent details		including estimated date of starting any proposed work).				
	For Multiple Completions: Attach wellbore						
INTERCOR LIFE CRACK			6.00				
LIME ROCK would like to P&A th	is North Vacuum Abo well as follo	ws: MIRUSU. TIH	w/2-3/8" rental tbg & tag cmt @ ~8472'.				
			subsequent plugs as appropriate. Circ hole				
			Spot 25 sx cmt (330') on bottom (~8472').				
			5 sx cmt (330') & spot a balanced plug inside				
	sg to cover Glorieta top. WOC. Tag cmt. PUH to 5105'. Plug #3 (5105'-4975'), Sq'ed Csg Split @ 5025'-55'. Mix 25 sx cmt (330')						
k spot a batanceu piug mside esg ti	Secure and could WOC Tax and D						
5 ex cont (2201) & cost a balanced	cover csg split. WOC. Tag cmt. F	PUH to 3268'. Plug	#4 (3268'-3168'), 8-5/8" shoe @ 3218'. Mix				
	plug inside csg to cover 8-5/8" csg :	PUH to 3268'. Plug: shoe. WOC. Tag cm	#4 (3268'-3168'), 8-5/8" shoe @ 3218'. Mix t. TOH. Plug #5 (1910'-Surface), Top Salt				
@ 1860' & 12-3/4" shoe @ 390'.	plug inside csg to cover 8-5/8" csg : Perf 3 SQ holes @ 1910'. Establish	PUH to 3268'. Plug: shoe. WOC. Tag cm circ down 5-1/2" cs	#4 (3268'-3168'), 8-5/8" shoe @ 3218'. Mix t. TOH. Plug #5 (1910'-Surface), Top Salt g & out bradenhead w/water. Pump cmt down				
@ 1860' & 12-3/4" shoe @ 390'. 5-1/2" csg & circ cmt out bradenhe	plug inside csg to cover 8-5/8" csg s Perf 3 SQ holes @ 1910'. Establish ad, (~520 sx). Cut off csg below sur	PUH to 3268'. Plug: shoe. WOC. Tag cm circ down 5-1/2" csg rface csg flange. Top	#4 (3268'-3168'), 8-5/8" shoe @ 3218'. Mix t. TOH. Plug #5 (1910'-Surface), Top Salt g & out bradenhead w/water. Pump cmt down of csgs w/cmt. Install P&A marker with				
@ 1860' & 12-3/4" shoe @ 390'. 5-1/2" csg & circ cmt out bradenhe	plug inside csg to cover 8-5/8" csg : Perf 3 SQ holes @ 1910'. Establish	PUH to 3268'. Plug: shoe. WOC. Tag cm circ down 5-1/2" csg rface csg flange. Top	#4 (3268'-3168'), 8-5/8" shoe @ 3218'. Mix t. TOH. Plug #5 (1910'-Surface), Top Salt g & out bradenhead w/water. Pump cmt down of csgs w/cmt. Install P&A marker with				
@ 1860' & 12-3/4" shoe @ 390'. 5-1/2" csg & circ cmt out bradenhe	plug inside csg to cover 8-5/8" csg s Perf 3 SQ holes @ 1910'. Establish ad, (~520 sx). Cut off csg below sur ecs. RD move off location, cut off a	PUH to 3268'. Plug: shoe. WOC. Tag cm circ down 5-1/2" csg rface csg flange. Top	#4 (3268'-3168'), 8-5/8" shoe @ 3218'. Mix t. TOH. Plug #5 (1910'-Surface), Top Salt g & out bradenhead w/water. Pump cmt down off csgs w/cmt. Install P&A marker with cation.				
© 1860' & 12-3/4" shoe @ 390'. 5-1/2" csg & circ cmt out bradenhe cmt to comply with government specific pud Date: 1/6/76	plug inside csg to cover 8-5/8" csg s Perf 3 SQ holes @ 1910'. Establish ad, (~520 sx). Cut off csg below sur ecs. RD move off location, cut off a	PUH to 3268'. Plug is shoe. WOC. Tag cm circ down 5-1/2" csg rface csg flange. Tog inchors and restore located as a page 1/30/76.	#4 (3268'-3168'), 8-5/8" shoe @ 3218'. Mix t. TOH. Plug #5 (1910'-Surface), Top Salt g & out bradenhead w/water. Pump cmt down off csgs w/cmt. Install P&A marker with cation.				
20. 1860' & 12-3/4" shoe @ 390'. 3-1/2" csg & circ cmt out bradenhe cmt to comply with government sports pud Date: 1/6/76 Thereby certify that the information	plug inside csg to cover 8-5/8" csg seperf 3 SQ holes @ 1910'. Establish ad, (~520 sx). Cut off csg below suress. RD move off location, cut off a Drilling Rig Right above is true and complete to the b	PUH to 3268'. Plug a shoe. WOC. Tag cm circ down 5-1/2" csg rface csg flange. Top nichors and restore lowest of my knowledge.	#4 (3268'-3168'), 8-5/8" shoe @ 3218'. Mix t. TOH. Plug #5 (1910'-Surface), Top Salt g & out bradenhead w/water. Pump cmt down off csgs w/cmt. Install P&A marker with cation.				
20. 1860' & 12-3/4" shoe @ 390'. 3-1/2" csg & circ cmt out bradenhe cmt to comply with government sponsor broaden and the comply with government sponsor broaden and the complex sponsor broa	plug inside csg to cover 8-5/8" csg seperf 3 SQ holes @ 1910'. Establish ad, (~520 sx). Cut off csg below sures. RD move off location, cut off a Drilling Rig Rig Right above is true and complete to the best of the best of the seperior.	PUH to 3268'. Plug a shoe. WOC. Tag cm circ down 5-1/2" csg rface csg flange. Top inchors and restore to Release Date: 1/30/76 pest of my knowledge bleum Engineer - Age	#4 (3268'-3168'), 8-5/8" shoe @ 3218'. Mix t. TOH. Plug #5 (1910'-Surface), Top Salt g & out bradenhead w/water. Pump cmt down off csgs w/cmt. Install P&A marker with cation. 6 and belief.				
20. 1860' & 12-3/4" shoe @ 390'. 20-1/2" csg & circ cmt out bradenhe cmt to comply with government specific properties and the comply with government specific properties and the complex specific properties are complex specific properties. 2. **Complex specific properties are complex specific properties and the complex specific properties are complex specific properties and the complex specific properties are complex specific properties. 2. **Complex specific properties are complex specific properties are complex specific properties and the complex specific properties are complex specific properties. 2. **Complex specific properties are complex specific properties are complex specific properties and the complex specific properties are complex specific properties. 2. **Complex specific properties are complex specific properties are com	plug inside csg to cover 8-5/8" csg seperf 3 SQ holes @ 1910'. Establish ad, (~520 sx). Cut off csg below sures. RD move off location, cut off a Drilling Rig Rig Right above is true and complete to the best of the best of the seperior.	PUH to 3268'. Plug a shoe. WOC. Tag cm circ down 5-1/2" csg rface csg flange. Top inchors and restore to Release Date: 1/30/76 rest of my knowledge bleum Engineer - Age	#4 (3268'-3168'), 8-5/8" shoe @ 3218'. Mix t. TOH. Plug #5 (1910'-Surface), Top Salt g & out bradenhead w/water. Pump cmt down off csgs w/cmt. Install P&A marker with cation. 6 and belief.				
20. 1860' & 12-3/4" shoe @ 390'. 20-1/2" csg & circ cmt out bradenhe cmt to comply with government specific process. 20. 1/2" csg & circ cmt out bradenhe cmt to comply with government specific process. 20. 1860' & 12-3/4" shoe @ 390'. 20. 18-18-18-18-18-18-18-18-18-18-18-18-18-1	plug inside csg to cover 8-5/8" csg seperf 3 SQ holes @ 1910'. Establish ad, (~520 sx). Cut off csg below sures. RD move off location, cut off a Drilling Rig Rig Right above is true and complete to the best of the best of the seperior.	PUH to 3268'. Plug a shoe. WOC. Tag cm circ down 5-1/2" csg rface csg flange. Top inchors and restore to Release Date: 1/30/76 pest of my knowledge bleum Engineer - Age	#4 (3268'-3168'), 8-5/8" shoe @ 3218'. Mix t. TOH. Plug #5 (1910'-Surface), Top Salt g & out bradenhead w/water. Pump cmt down off csgs w/cmt. Install P&A marker with cation. 6 and belief.				
20. 1860' & 12-3/4" shoe @ 390'. 20-1/2" csg & circ cmt out bradenhe cmt to comply with government specific process. 20. Spud Date: 1/6/76 20. hereby certify that the information of the second process. 20. Signature	plug inside csg to cover 8-5/8" csg seperf 3 SQ holes @ 1910'. Establish ad, (~520 sx). Cut off csg below sures. RD move off location, cut off a Drilling Rig Rig Right above is true and complete to the best of the best of the seperior.	PUH to 3268'. Plug a shoe. WOC. Tag cm circ down 5-1/2" csg rface csg flange. Top inchors and restore to Release Date: 1/30/76 pest of my knowledge bleum Engineer - Age	#4 (3268'-3168'), 8-5/8" shoe @ 3218'. Mix t. TOH. Plug #5 (1910'-Surface), Top Salt g & out bradenhead w/water. Pump cmt down off csgs w/cmt. Install P&A marker with cation. 6 and belief.				
20. 1860' & 12-3/4" shoe @ 390'. 20-1/2" csg & circ cmt out bradenhe cmt to comply with government specific process. 20. 1/2" csg & circ cmt out bradenhe cmt to comply with government specific process. 20. 1860' & 12-3/4" shoe @ 390'. 20. 18-18-18-18-18-18-18-18-18-18-18-18-18-1	plug inside csg to cover 8-5/8" csg seperf 3 SQ holes @ 1910'. Establish ad, (~520 sx). Cut off csg below sures. RD move off location, cut off a Drilling Rig Rig Right above is true and complete to the best of the best of the seperior.	PUH to 3268'. Plug a shoe. WOC. Tag cm circ down 5-1/2" csg rface csg flange. Top inchors and restore to Release Date: 1/30/76 pest of my knowledge bleum Engineer - Age	#4 (3268'-3168'), 8-5/8" shoe @ 3218'. Mix t. TOH. Plug #5 (1910'-Surface), Top Salt g & out bradenhead w/water. Pump cmt down off csgs w/cmt. Install P&A marker with cation. 6 and belief.				

The Oil Conservation Division
MUST BE NOTIFIED 24 Hours
Prior to the beginning of operations

JUI 28 2015



		1		
	OPERATOR:	LEASE / WELL:	SURVEY:	Property No.
	Lime Rock Resources	NVANU 14-3	Sec 12, T17S, R34E	
		COUNTY / STATE:	SURFACE LOCATION:	FIELD:
	COMPLETION RIG:	Lea County, NM	2180' FNL & 660' FWL	North Vacuum
L	DIRECTIONAL DATA		TUBULAR DATA	WELLHEAD DATA

STRAIGHT HOL	LE MD
	MD
deg 🗗	MD
deg @	MO
deg @	MD
	UID
OMPLETION FL	.טוט.
ppg -	

Tubulare	Size	Weight	Grade	Thread	Тор	MD	SKS
DRIVE PIPE							
CONDUCTOR							
SURFACE	12-3/4"	40.50#	H-40	STC	O'	390'	450
INTERMEDIATE	8-5/8"	24/32#	J-55	STC	o	3218'	1,000
PRODUCTION	4-1/2"	10.5/11/6#	K-55	LTC	0,	8750'	1,050
PROD TIEBACK							
PROD LINER							
PROD LINER							
TUBING		1					
		1				•	
COILED TUBING							7

WELLHEAD DATA					
TYPE					
WP					
T C	FLANGE:				
E P	THREAD:				
TUBING	HANGER:				
ВТ					
BP\					
ELEVA	GROUND				
RKB-DF:		ELEVATION			
RKB-ELEV:		4030'			

	3 / COMPLETION	FLUID	Р
DRILLING FLUID:	ppg -		Р
DRILLING FLUID: DRILLING FLUID:	ppg -		P
COMPLETION FLUID:	ppg -		Ή.
PACKER FLUID:	ID: ppg - ppg -		-
	h.a.		L.
	WELLBORE SKE	rch	
7.0	DRAWING NOT TO S	CALE	
		\vdash	4
368		368	4
		國	1
→			~
100			
NA SEE		28 3	
		36 E.	
		83	
32			
1 25		133	
		22	
1 3		36	
		23	
1 533	•	160	
		33	
		133	
33.		200	
1 21		S	
医		231	
39		32	
<u> </u>		133	
製料			
		鼷	
提			
		礟	
26			
30	\$8.847.8-58.2		
學的		133	
		48	
		75	
		32.3	
38			
		際	
) 经别		183	
	PBTD 8,724'		
533	SEPTEMBER OF THE		
	DI (不知的) 10.000 (10.000 P)	la aca	
L	TD 8,750'		

	T	I	DEPTH	DEPTH
EQUIPMENT DESCRIPTION	ID	OĐ	TVD	MD
Replaced 3 jts csg (July-93)				
	Į į			
12-3/4" 40.5# H-40 csg @ 390' - cmt'd w/450 sx to surface (17-1/2" hole)				
Top Salt @ 1860'				
TOC @ 2840' @ 75% eff.				
			<u> </u>	
8-5/8" 24&32# J-55 csg @ 3218' - cmt'd w/1000 sx (12-1/4" hole)	 _			
			<u> </u>	

			<u> </u>	
			<u> </u>	
			ļ	
Csg split @ 5025'-55' (Feb-76); sqz twice w/100 sxs each; test to 3000 psi			ļ	<u> </u>
				<u> </u>
	<u> </u>			
Top of Glorieta @ 6059'			ļ	
			<u> </u>	
			ļ	L
				<u> </u>
				
				<u> </u>
Plug #1 (8472'-8372'), Spot 25 sx cmt @ 8472'.	ļ			——
OIDD @ 04001 + 4014				
CIBP @ 8482' + 10' cmt Top ABO @ 8542'			ļ	
	ļ		 	
Abo perfs @ 8542'-84' (sqz'd Aug-08)			ļ	
Abo perfs @ 8610'-16', 8620'-25', 8630'-35', 8640'-44', 8652'-60', 8672'-78', &	 			
		ļ		
8706'-10' (perf'd & acidized Aug-08)		 -	 	
		ļ		
A 4100 40 F0 44 CH V FF (2) 07501 and 4 w/4050 av (7 7/00 hala)			 	
4-1/2" 10.5&11.6# K-55 csg @ 8750', cmt'd w/1050 sx (7-7/8" hole)	DITIO BYCK	OSDTU:		
COMMENTS: Working Interest:	PLUG BACK			
API# 30-025-25207 Net Revenue Interest: Property#	TOTAL WELL	RED OR	DATE:	L
Spud Date:	Į.	ED BY:		
Completed in	i	np	112.	3/2015

OPERATOR:	LEASE / WELL:	SURVEY:	Property No.
Lime Rock Resources NVANU 14-3		Sec 12, T17S, R34E	ŀ
	COUNTY/STATE:	SURFACE LOCATION:	FIELD:
COMPLETION RIG:	Lea County, NM	2180' FNL & 660' FWL	North Vacuum

KOP:	STRAIGHT HO	DLE
MAX DEV:	deg ℚ	MD
DEV @ PERFS:	deg 🕢	MD
DEV @ PERFS:	deg @	MD
DEV @ PERFS:	deg @	MD

DRILLING / CO	OMPLETION FLUID
DRILLING FLUID:	ppg -
DRILLING FLUID:	ppg -
DRILLING FLUID:	ppg -
COMPLETION FLUID:	ppg -

PACKER FLUID:

	· · ·		TUBULA	R DATA	7	Part of the second	
Tubulars	Size	Weight	Grade	Thread	Тор	MD	SKS
DRIVE PIPE		T I					
CONDUCTOR							
SURFACE	12-3/4"	40.50#	H-40	STC	0'	390'	450
INTERMEDIATE	8-5/8"	24/32#	J-55	STC	0'	3218'	1,000
PRODUCTION	4-1/2"	10.5/11/6#	K-55	LTC	0'	8750'	1,050
PROD TIEBACK							
PROD LINER		1					
PROD LINER							
TUBING		1					
COILED TUBING							

WE	WELLHEAD DATA						
TYPE							
WP							
T C	FLANGE:						
E P	THREAD:						
TUBING							
BTM							
BPV							
ELEVATIONS:		GROUND					
RKB-DF:	ELEVATION						
RKB-ELEV:		4030'					

