

Submit 1 Copy To Appropriate District
Office
District I - (575) 393-6161
1625 N. French Dr., Hobbs, NM 88240
District II - (575) 748-1283
811 S. First St., Artesia, NM 88210
District III - (505) 334-6178
1000 Rio Brazos Rd., Aztec, NM 87410
District IV - (505) 476-3460
1220 S. St. Francis Dr., Santa Fe, NM
87505

State of New Mexico
Energy, Minerals and Natural Resources

Form C-103
Revised July 18, 2013

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

WELL API NO.
30-025-29067

5. Indicate Type of Lease

STATE ☒ FEE ☐

6. State Oil & Gas Lease No.
State Land 76

7. Lease Name or Unit Agreement Name

8. Well Number 004

9. OGRID Number 12627

10. Pool name or Wildcat
Anderson Ranch; Cisco-Canyon, North

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH
PROPOSALS.)

1. Type of Well: Oil Well ☒ Gas Well ☐ Other

2. Name of Operator
Kevin O Butler & Associates, Inc

3. Address of Operator
PO Box 1171, Midland, TX 79702

4. Well Location

Unit Letter E : 2323 feet from the North line and 330 feet from the West line

Section 1 Township 16S Range 32E NMPM County Lea

11. Elevation (Show whether DR, RKB, RT, GR, etc.)
4278.2' GR

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☒ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐
DOWNHOLE COMMINGLE ☐
CLOSED-LOOP SYSTEM ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ P AND A ☐
CASING/CEMENT JOB ☐
OTHER: ☐

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of
proposed completion or recompletion.

Test anchors

RU workover rig. Pull rods & pump.

NU BOP. Tag bottom & tally tubing out of hole (anchor ?)

TIH w/ pkr & plug (if no anchor in hole, may want to run casing scraper)

Locate and squeeze bad casing, if any above perfs (10,462'-10,476')

Drill out & test same

Acidize oil perfs w/ 3000 gal 15% + Petroplex product.

Return well to production. Replace rods, pump, tubing, flow line, as needed

Spud Date:

Rig Release Date:

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE [Signature] TITLE Agent DATE 07/28/2015

Type or print name M.Y. (Merch) Merchant E-mail address: mymerch@penrocoil.com PHONE: 575-492-1236

For State Use Only

APPROVED BY: [Signature] TITLE Petroleum Engineer

Conditions of Approval (if any):

DATE 07/28/15

JUL 30 2015