



Submit One Copy To Appropriate District Office

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-103
Revised November 3, 2011

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		WELL API NO. 30-025-27380																		
1. Type of Well: <input checked="" type="checkbox"/> Oil Well <input type="checkbox"/> Gas Well <input type="checkbox"/> Other		5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>																		
2. Name of Operator OXY USA WTP LP		6. State Oil & Gas Lease No.																		
3. Address of Operator PO Box 4294; Houston TX 77210		7. Lease Name or Unit Agreement Name Myers Langlie Mattix Unit																		
4. Well Location Unit Letter N : 660 feet from the S line and 2000 feet from the W line Section 30 Township 83S Range 37E NMPM Lea County NM		8. Well Number 40																		
11. Elevation (Show whether DR, RKB, RT, GR, etc.)		9. OGRID Number																		
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data		10. Pool name or Wildcat Langlie Mattix 7AURS-QN-G																		
<table border="0"><tr><td colspan="2">NOTICE OF INTENTION TO:</td><td>SUBSEQUENT REPORT OF:</td></tr><tr><td>PERFORM REMEDIAL WORK <input type="checkbox"/></td><td>PLUG AND ABANDON <input type="checkbox"/></td><td>REMEDIAL WORK <input type="checkbox"/></td></tr><tr><td>TEMPORARILY ABANDON <input type="checkbox"/></td><td>CHANGE PLANS <input type="checkbox"/></td><td>ALTERING CASING <input type="checkbox"/></td></tr><tr><td>PULL OR ALTER CASING <input type="checkbox"/></td><td>MULTIPLE COMPL <input type="checkbox"/></td><td>COMMENCE DRILLING OPNS. <input type="checkbox"/></td></tr><tr><td colspan="2"></td><td>P AND A <input type="checkbox"/></td></tr><tr><td colspan="2"></td><td>CASING/CEMENT JOB <input type="checkbox"/></td></tr></table>			NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>	PULL OR ALTER CASING <input type="checkbox"/>	MULTIPLE COMPL <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>			P AND A <input type="checkbox"/>			CASING/CEMENT JOB <input type="checkbox"/>
NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:																		
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>																		
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>																		
PULL OR ALTER CASING <input type="checkbox"/>	MULTIPLE COMPL <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>																		
		P AND A <input type="checkbox"/>																		
		CASING/CEMENT JOB <input type="checkbox"/>																		
OTHER: <input type="checkbox"/> <input checked="" type="checkbox"/> Location is ready for OCD inspection after P&A																				

- ☒ All pits have been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan.
☒ Rat hole and cellar have been filled and leveled. Cathodic protection holes have been properly abandoned.
☒ A steel marker at least 4" in diameter and at least 4' above ground level has been set in concrete. It shows the

OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, QUARTER/QUARTER LOCATION OR UNIT LETTER, SECTION, TOWNSHIP, AND RANGE. ALL INFORMATION HAS BEEN WELDED OR PERMANENTLY STAMPED ON THE MARKER'S SURFACE.

- ☒ The location has been leveled as nearly as possible to original ground contour and has been cleared of all junk, trash, flow lines and other production equipment.
☒ Anchors, dead men, tie downs and risers have been cut off at least two feet below ground level.
☒ If this is a one-well lease or last remaining well on lease, the battery and pit location(s) have been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, production equipment and junk have been removed from lease and well location.
☒ All metal bolts and other materials have been removed. Portable bases have been removed. (Poured onsite concrete bases do not have to be removed.)
☒ All other environmental concerns have been addressed as per OCD rules.
☒ Pipelines and flow lines have been abandoned in accordance with 19.15.35.10 NMAC. All fluids have been removed from non-retrieved flow lines and pipelines.
☒ If this is a one-well lease or last remaining well on lease: all electrical service poles and lines have been removed from lease and well location, except for utility's distribution infrastructure.

When all work has been completed, return this form to the appropriate District office to schedule an inspection.

SIGNATURE [Signature] TITLE NM Advisor DATE 12/30/15
TYPE OR PRINT NAME Casey Summers E-MAIL: Casey_Summers@nrm.com PHONE: 515-513-8289
For State Use Only
APPROVED BY: [Signature] TITLE Petroleum Specialist DATE 01/06/2016

JAN 07 2016

ay