

SPILL PREVENTION, CONTROL, AND COUNTERMEASURE PLAN

Kaiser-Francis Oil Company P.O. Box 21468 Tulsa, Oklahoma 74121-1468

North Bell Lake Unit 6 2BSS Production Facility

**November 4, 2015** 

## **Table of Contents**

	Page
Cross-Reference with SPCC Rule	4
ntroduction	5
Management Approval	6
Professional Engineer Certification	6
Plan Review	7
ocation of SPCC Plan	7
Certification of Substantial Harm Determination	. 8
Part I – General Facility Information	
1.1 Company Information	· 9
1.2 Contact Information	9
1.3 Facility Layout Diagram	10
1.4 Facility Location and Operations	10
1.5 Oil Storage and Handling	<b>11</b>
1.6 Conformance w/Applicable State and Local Requirements	12
Part II – Spill Response and Reporting	
2.1 Discharge Discovery and Reporting	13
2.2 Spill Mitigation Procedures	14
2.3 Disposal Plan	15
Part III – Spill Prevention, Control, and Countermeasure Provisions	
3.1 Potential Discharge Volume and Direction of Flow	. 16
3.2 Containment and Diversionary Structures	17
3.3 Other Spill Prevention Measures	18
3.4 Inspections, Tests, and Records	19
3.5 Personnel, Training, and Discharge Prevention Procedures	20
Appendix A – Facility Diagrams	21
Appendix B – Monthly Inspection Report	23
Appendix C – Record of Dike Drainage	25
Appendix D – Discharge Notification Procedures	26
Appendix E – Equipment Shut off Procedures	31
Annendix E - Written Commitment of Mannower, Equipment, and Materials	32

Facility: North Bell Lake 2BSS Page 2 of 32

## Spill Prevention, Control, and Countermeasure (SPCC) Plan

### Kaiser-Francis Oil Company

	Page
<u>List of Tables</u>	
Table 0-1: Record of plan review and changes	7
Table 1-1: Facility contact information	10
Table 1-2: Characteristics of oil containers	11
Table 3-1: Potential discharge volume and direction of flow	16
Table 3-2: Berm capacity calculations	17
List of Figures	
Figure A-1: Production facility diagrams	21

Facility: North Bell Lake 2BSS Page 3 of 32

## **Cross-Reference with SPCC Rule**

Provision*	Plan Section	Page(s)
112.3(d)	Professional Engineer Certification	6
112.3(e)	Location of SPCC Plan	7
112.5	Plan Review	7
112.7	Management Approval	6
112.7	Cross-Reference with SPCC Rule	4
112.7(a)(3)	Part I – General Information and Facility Diagram Appendix A: Facility Diagrams	9-12 Appendix A
112.4 and 112.7(a)(3)	<ul><li>2.1 Discharge Discovery and Reporting</li><li>Appendix D: Discharge Notification</li></ul>	13-14 Appendix D
112.7(b)	3.1 Potential Discharge Volume and Direction of Flow	. 16
112.7(c)	3.2 Containment and Diversionary Structures	17
112.7(d)	3.2.3 Practicability of Secondary Containment Appendix F: Written Commitment of manpower, equipment and materials.	18 Appendix F
112.7(e)	3.4 Inspections, Tests, and Records Appendix B: Facility Inspection Checklists	19 Appendix B
112.7(f)	3.5 Personnel, Training, & Discharge Prevention Procedures Appendix D: Discharge Notification	20 Appendix D
112.7(g)	Security – N/A (does not apply to production facilities)	N/A
112.7(h)	Loading/Unloading Rack - N/A (no rack at this facility)	N/A
112.7(i)	3.4.3 Brittle Fracture Evaluation – N/A (no field-erected above-ground tank at this facility)	19
112.7(j)	1.6 Conformance with Applicable State and Local Requirements	12
112.9(b)	3.2.1 Oil Production Facility Drainage Appendix C: Record of Dike Drainage	17 Appendix C
112.9(c)(1)	1.5.1 Production Equipment	11
112.9(c)(2)	3.2.2 Secondary Containment for Bulk Storage Containers	17
112.9(c)(3)	3.4 Inspections, Tests, and Records	. 19
112.9(c)(4)	Appendix B: Monthly Inspection Report 3.3.1 Bulk Storage Containers Overflow Prevention	Appendix B 18
112.9(d)(1)	3.3.2 Transfer Operations and Saltwater Disposal System	18
112.9(d)(2)	3.3.2 Transfer Operations and Saltwater Disposal System	18
112.9(d)(3)	3.4.4 Flowline Maintenance Program	20

<sup>\*</sup>Only relevant rule provisions are indicated. For a complete list of SPCC requirements, refer to the full text of 40 CFR part 112.

Facility: North Bell Lake 2BSS

Page 4 of 32

#### Introduction

The purpose of this Spill Prevention Control and Countermeasure (SPCC) Plan is to describe measures implemented by Kaiser-Francis Oil Company "KFOC" to prevent oil discharges from occurring, and to prepare KFOC to respond in a safe, effective, and timely manner to mitigate the impacts of a discharge from the North Bell Lake 2BSS production facility. This SPCC Plan has been prepared and implemented in accordance with the SPCC requirements contained in 40 CFR part 112.

In addition to fulfilling requirements of 40 CFR 112, this SPCC Plan is used as a reference for oil storage information and testing records, as a tool to communicate practices on preventing and responding to discharges with KFOC employees and contractors, as a guide on facility inspections, and as a resource during emergency response.

Facility: North Bell Lake 2BSS

Page 5 of 32

Page 6 of 32

### **Management Approval**

#### 40 CFR 112.7

Kaiser-Francis Oil Company ("KFOC") is committed to maintaining the highest standards for preventing discharges of oil to navigable waters and the environment through the implementation of this SPCC Plan. This SPCC Plan has the full approval of KFOC management. KFOC's management has committed the necessary resources to implement the measures described in this Plan.

The Production Superintendent is the Designated Person Accountable for Oil Spill Prevention at this KFOC facility and has the authority to commit the necessary resources to implement the Plan as described.

•	•
Authorized Facility Representative:	David Zerger
Signature:	
Title:	Operations Engineer
Date:	
Professional Engineer Certification 40 CFR 112.3(d)	
The undersigned Registered Professional Engine Part 112 of Title 40 of the Code of Federal Revisited and examined the facility, or has superappropriately qualified personnel. The undersignattests that this Spill Prevention, Control and Codin accordance with good engineering practice, industry standards and the requirements of 40 required inspections have been established; ar facility. [112.3(d)]	gulations (40 CFR part 112) and has ervised examination of the facility by ned Registered Professional Engineer untermeasure Plan has been prepared including consideration of applicable CFR part 112; that procedures for
This certification in no way relieves the owner or oprepare and fully implement this SPCC Plan in a CFR part 112.	
·	
Signature	
Date	
Charles W. Lock Name of Professional Engineer	
16241 - OK	
Registration Number/Issuing State	
Facility: North Bell Lake 2BSS	

## Plan Review 40 CFR 112.5

In accordance with 40 CFR 112.5, Kaiser-Francis Oil Company periodically reviews and evaluates this SPCC Plan for any change in the facility design, construction, operation, or maintenance that materially affects the facility's potential for an oil discharge. KFOC reviews this SPCC Plan at least once every five years. Revisions to the Plan, if any are needed, are made within six months of this five-year review. KFOC will implement any amendment as soon as possible, but not later than six months following preparation of any amendment. A registered PE certifies any technical amendment to the Plan, as described above, in accordance with 40 CFR (112.3(3).

Table 0-1: Record of Plan Review and Changes

#### MANAGEMENT REVIEW

 Management will review this SPCC Plan at least each five (5) years and document the review on the form below.

Review/ Signature Amend Date		end (will/will not)		Affected Page(s)	P.E. Certification (Y/N)
					·
*		,			
			•		
		·		_	
· · · · · · · · · · · · · · · · · · ·					

### Location of SPCC Plan 40 CFR 112.3(e)

In accordance with 40 CFR 112.3(e), and because the facility is normally unmanned, a complete copy of this SPCC Plan is maintained at the Corporate Office, which is located at 6733 S. Yale Avenue, Tulsa, OK.

Facility: North Bell Lake 2BSS

Page 7 of 32

# Certification of Substantial Harm Determination 40 CFR 112.20(e), 40 CFR 112.20(f)(1)

Facility Name:	Kaiser-Francis O	il Company, North Bell Lake 2BSS
1. Does the facility transf total oil storage capacity Yes□		or from vessels and does the facility have a al to 42,000 gallons?
gallons and does the fa	icility lack seconda e largest abovegro	capacity greater than or equal to 1 million ary containment that is sufficiently large to und oil tank plus sufficient freeboard to allow rage tank area?
gallons and is the facilit	ty located at a dis	e capacity greater than or equal to 1 million stance (as calculated using the appropriate lity could cause injury to fish and wildlife and
gallons and is the facility formula) such that a discintake?	ty located at a dis harge from the fac	e capacity greater than or equal to 1 million stance (as calculated using the appropriate ility would shut down a public drinking water
Yes□	No 🗖	
	ty experienced a re	capacity greater than or equal to 1 million portable oil spill in an amount greater than or rs?
information submitted in	n this document, for obtaining this	ersonally examined and am familiar with the and that based on my inquiry of those information, I believe that the submitted
	<u> </u>	Safety and Environmental Coordinator
Signature		Title
Charles W. Look		
Charles W. Lock Name (type or print)		Date

Facility: North Bell Lake 2BSS

Page 8 of 32

### PART I – GENERAL FACILITY INFORMATION 40 CFR 112.7(a)(3)

#### 1.1 Company Information

Name of Facility: Kaiser-Francis Oil Company

North Bell Lake 2BSS

Type Onshore oil production facility

Location 30-22S-34E

Lea County, NM

Name and Address of Owner Kaiser-Francis Oil Company

Ardmore District Office Box 197 (Dillard Route) Wilson, OK 73643

Corporate Office 6733 S. Yale Avenue Tulsa, OK 74133

#### 1.2 Contact Information

The designated person accountable for overall oil spill prevention and response at the facility, also referred to as the "Response Coordinator" (RC), is the Production Superintendent, Bill Wilkinson. 24 hour contact information is provided in Table 1-1.

The pumper/gauger provides operation support activities for KFOC, including performing informal daily examinations of the facility equipment, as described in Section 3.4 of this SPCC Plan. The pumper regularly visits the facility to record production levels and perform other maintenance/inspection activities as requested by the Kaiser-Francis Operations Engineer. Pumper phone numbers are included in Table 1-1.

Facility: North Bell Lake 2BSS

Page 9 of 32

Table 1-1: Facility contact information

Name	Title	Telephone	
Kelly Roach	Pumper *	432/238-6996	
Bill Wilkinson	Production Superintendent	580/668-2335 (office)	
	Kaiser-Francis Oil Company Ardmore District	580/221-4637 (cell)	
David Zerger	Operations Engineer Kaiser-Francis Oil Company Tulsa, OK	918/491-4350 (office)	
Charles Lock	Safety & Environmental	918/491-4337 (office)	
	Kaiser-Francis Oil Company Tulsa, OK	918/671-6510 (cell)	

#### 1.3 Facility Layout Diagram

Appendix A, at the end of this Plan, shows a general site plan for the facility. The site plan shows the site topography and the location of the facility relative to waterways, roads, and inhabited areas. Appendix A will also include a detailed facility diagram that shows the wells, tank battery, and transfer areas for the facility. The diagram will show the location, capacity, and contents of all oil storage containers greater than 55 gallons in capacity.

#### 1.4 Facility Location and Operations

KFOC operates the North Bell Lake Unit 6 2BSS production facility; directions to the lease are as follows:

From the intersection of E21 (Delaware Basin) and Antelope Ridge, go West 1.75 miles, turn right and go North 0.4 miles, turn left follow road West approximately 100' to the location.

The production facility is generally unmanned. Field operations personnel from KFOC, or pumpers acting as contractors to KFOC visit the facility daily to record production rates and ensure the proper functioning of wellhead equipment and pumpjacks, storage tanks, flowlines, and separation vessels. This includes performing equipment inspection and maintenance as needed.

The produced water tank may contain an oil/produced water mixture making it subject to 40 CFR part 112 and is covered by this SPCC Plan.

#### 1.5 Oil Storage and Handling

Facility: North Bell Lake 2BSS

Page 10 of 32

#### 1.5.1 Production Equipment

All oil storage tanks are shop-built and meet the American Petroleum Institute (API) tank construction standard. Their design and construction are compatible with the oil they contain and the temperature and pressure conditions of storage.

Lubricating oil and other substances, such as solvents and chemicals for downhole treatment, are also sometimes stored at the facility, but in quantities below the 55-gallon threshold for SPCC applicability. Table 1-2 lists all oil containers present at the facility with capacity of 55 gallons or more.

	Table 1-2: Characteristics of oil containers							
ID	Construction	Primary Content	Capacity (barrels)	Capacity (gallons)				
				· · · · · · · · · · · · · · · · · · ·				
		TOTAL						

#### 1.5.2 Transfer Activities

Wells produce crude oil, produced water (saltwater), and natural gas. Well liquids are then routed via steel flowlines to a separation vessel. Produced saltwater is routed from the separator to the saltwater storage tank. The crude oil is sent to the oil storage tanks.

Crude oil from the lease is purchased by a crude oil purchaser and transported from the facility by the purchaser's tanker truck. Tanker trucks come to the facility to transfer crude oil and produced water, but do not remain at the facility. Sorbent materials in conjunction with drip pans are used to contain spills. All transfer operations are attended by the trucker and meet the minimum requirements of the US Department of Transportation Hazardous Materials Regulations.

Facility: North Bell Lake 2BSS

Page 11 of 32

### 1.6 Conformance w/Applicable State and Local Requirements [112.7(j)]

The SPCC regulation of 40 CFR part 112 is more stringent than requirements from the state for this type of facility. This SPCC Plan was written to conform to 40 CFR part 112 requirements. The facility thereby conforms to general requirements for oil pollution facilities in the state. All discharge notifications are made in compliance with local, state, and federal requirements.

Facility: North Bell Lake 2BSS

Page 12 of 32

## PART II. SPILL RESPONSE AND REPORTING 40 CFR 112.7

#### 2.1 Discharge Discovery and Reporting [112.7(a)(3)]

Several individuals and organizations must be contacted in the event of an oil discharge. The Production Superintendent is responsible for ensuring that all required discharge notifications have been made. All discharges should be reported to the Production Superintendent. The summary table included in Appendix D to this SPCC Plan provides a list of agencies to be contacted under different circumstances. Discharges would typically be discovered during the inspections conducted at the facility in accordance with procedures set forth in Section 3.4.1 of this SPCC Plan, and on the checklist of Appendix B. The Form included in Appendix D of this Plan summarizes the information that must be provided when reporting a discharge, including contact lists and phone numbers.

## 2.1.1 Verbal Notification Requirements (Local, State, and Federal (40 CFR part 110))

For any discharge that reaches navigable waters, or threatens to reach navigable waters, *immediate* notification must be made to the National Response Center Hotline (800-424-8802) and to the Environmental Protection Agency.

In the event of a discharge that threatens to result in an emergency condition, facility field personnel must verbally notify the appropriate state agency immediately, and in no case later than within one (1) hour of the discovery of the discharge. An emergency condition is any condition that could reasonably be expected to endanger the health and safety of the public; cause significant adverse impact to the land, water, or air environment; or cause severe damage to property. This notification must be made regardless of the amount of the discharge.

In the event of a discharge that does not present an emergency situation, verbal notification must be made to the appropriate state agency within twenty-four hours of the discharge.

#### 2.1.2 Written Notification Requirements (State and Federal (40 CFR part 112))

A written notification will be made to EPA for any single discharge of oil to a navigable water or adjoining shoreline waterway of more than 1,000 gallons, or for two discharges of 1 bbl (42 gallons) of oil to a waterway in any 12-month period. This written notification must be made within 60 days of the qualifying discharge, and a copy will be sent to the appropriate state agency in charge of oil production control activities. This reporting requirement is separate and in addition to reporting under 40 CFR part 110 discussed above.

Facility: North Bell Lake 2BSS

Page 13 of 32

#### 2.1.3 Submission of SPCC Information

Whenever the facility experiences a discharge into navigable waters of more than 1,000 gallons, or two discharges of 42 gallons or more within a 12-month period, KFOC will provide information in writing to the EPA Region office within 60 days of a qualifying discharge as described above. The required information is described in Appendix D of this SPCC Plan.

#### 2.2 Spill Mitigation Procedures [112.7(a)(5)]

The following is a summary of actions that must be taken in the event of a discharge. It summarizes the distribution of responsibilities among individuals and describes procedures to follow in the event of a discharge.

In the event of a discharge, KFOC or contract field personnel and the Production Superintendent shall be responsible for the following:

#### 2.2.1 Shut off Ignition Sources

Field personnel must shut off all ignition sources, including motors, electrical circuits, and open flames. See Appendix E for more information about shut-off procedures.

#### 2.2.2 Stop Oil Flow

Field personnel should determine the source of the discharge, and if safe to do so, immediately shut off the source of the discharge. Shut in the well(s) if necessary.

#### 2.2.3 Stop Spread of Oil and Call the Production Superintendent

If safe to do so, field personnel must use resources available at the facility to stop the spilled material from spreading. Measures that may be implemented, depending on the location and size of the discharge, include placing sorbent material or other barriers in the path of the discharge (e.g., sand bags), or constructing earthen berms or trenches.

In the event of a significant discharge, field personnel must immediately contact the Production Superintendent, who may obtain assistance from authorized company contractors and direct the response and cleanup activities. Should a discharge reach navigable waters, only physical response and countermeasures should be employed, such as the construction of underflow dams, installation of hard boom and sorbent boom, use of sorbent pads, and use of vacuum trucks to recover oil and oily water from the water. If water flow is low, construction of any underflow dam downstream and ahead of the spill flow may be advantageous. Sorbent material and/or boom should be placed immediately downstream of the dam to recover any sheen from the water. If water flow is normal, floating booms and sorbent boom will be deployed. Vacuum trucks will then be utilized to remove oil and oily water at dams and other access points. At no time shall any surfactants, dispersants, or other chemicals be used to remove oil when the spill is in water.

Facility: North Bell Lake 2BSS

Page 14 of 32

#### 2.2.4 Gather Spill Information

The Production Superintendent will ensure that the *Discharge Notification Form* is filled out and that notifications have been made to the appropriate authorities. The Production Superintendent may ask for assistance in gathering the spill information on the *Spill Report Form* (Appendix D) of this Plan.

#### 2.2.5 Notify Agencies Verbally

Some notifications must be completed *immediately* upon discovering the discharge. It is important to immediately contact the Production Superintendent so that timely notifications can be made. If the Production Superintendent is not available, or the Production Superintendent requests it, field personnel must designate one person to begin notification. Section 2.1 of this Plan describes the required notifications to government agencies. The Notification List is included in Appendix D of this SPCC Plan. The Production Superintendent must also ensure that written notifications, if needed, are submitted to the appropriate agencies.

#### 2.3 Disposal Plan

The cleanup contractor will handle the disposal of any recovered product, contaminated soil, contaminated materials and equipment, decontamination solutions, sorbents, and spent chemicals collected during a response to a discharge incident.

Facility: North Bell Lake 2BSS Page 15 of 32

# PART III. SPILL PREVENTION, CONTROL, AND COUNTERMEASURE PROVISIONS

40 CFR 112.7 and 112.9

- 3.1 Potential Discharge Volume and Direction of Flow [112.7(b)] and Containment [112.7(a)(3)(iii)]
- The potential spills sources at the Facility are summarized in the following table:

Container ID	Substance Stored (0il)	Shell Capacity (Bbls)	Potential Failure	Rate of Flow (Bbls/hr)	Direction of Flow	Containment System(s)
Bulk Sto	rage Contai	ners		ľ	Barriera de la companya della companya della companya de la companya de la companya della compan	
				:		
					•	
Operatio	nal Equipm	ent	I	T		
Truck or	Rail Loadin	g/Unloadir	ng Rack	l .		
Other Po	tential Spill	Sources	l.	L		

- The material and construction of bulk storage containers are compatible with the material stored and conditions of storage such as pressure and temperature.
- All bulk storage container installations, if required, are constructed so that a
  means of secondary containment is provided for the entire capacity of the largest
  single container plus sufficient freeboard to contain precipitation.
- Diked areas are sufficiently impervious to contain discharged oil.

Facility: North Bell Lake 2BSS

Page 16 of 32

#### 3.2 Containment and Diversionary Structures [112.7(c)]

The facility is configured to minimize the likelihood of a discharge reaching navigable waters. The following measures are provided:

Secondary containment for the oil storage tanks, saltwater tank (which
may have small amounts of oil), is provided by an earthen berm or metal
containment ring, as described in Section 3.2.2 below. The earthen berm
is constructed of native soils and then covered with gravel.

#### 3.2.1 Oil Production Facility Drainage [112.9(b)]

Facility drainage areas in the production/separation area, but outside containment berms, are visually examined by facility personnel on a daily basis during routine facility rounds to detect any discoloration or staining that would indicate the presence of oil from small leaks within the facility. Any accumulation of oil is promptly removed and disposed off site.

#### 3.2.2 Secondary Containment for Bulk Storage Containers [112.9(c)(2)]

In order to further minimize the potential for a discharge to navigable waters, bulk storage containers such as all tank battery, separation, and treating equipment are placed inside a berm (fire wall). It provides secondary containment sufficient for the size of the largest tank, plus enough freeboard to contain precipitation. Per example below: This secondary containment capacity is equivalent to approximately 905 percent of the capacity of the largest tank within the containment area and exceeds the 10 percent freeboard recommended by API for firewalls around production tanks (API-12R1). An example of the berm capacity calculations is provided in Table 3-2.

### **EXAMPLE** Table 3-2: BERM CAPACITY CALCULATIONS

BERM CAPACITY	
Berm height	3 ft
Berm dimensions	186 ft x 39 ft = 7,254 ft <sup>2</sup>
Tank footprint	4 tanks @ 12 ft dia. each & 1 tank @ 6 ft dia = 4 x ( $\pi$ 12 <sup>2</sup> /4) + ( $\pi$ 6 <sup>2</sup> /4) = 480.66 ft <sup>2</sup>
Net volume	3 ft x (7254-480.66) = 20,320.02 ft <sup>3</sup>
Ratio to largest tank	20,320.02 /2245.84= 904.78 %
CORRESPONDING AMOUNT OF FREEBOARD	
100% volume of largest tank	16,800 gal = 2,245.84 ft <sup>3</sup>
Net area	7,254 - 480.66= 6,773.34 ft <sup>2</sup>
Minimum berm height for 100% of tank volume	2,245.84 / 6,773.34 ft = .33 ft
Freeboard	333 = 2.67 ft

Facility personnel inspect the berm daily for the presence of oil. The sides of the earthen berms are capped with gravel to minimize erosion.

Facility: North Bell Lake 2BSS

Page 17 of 32

#### 3.2.3 Practicability of Secondary Containment [112.7(d)]

Flowlines adjacent to the production equipment and storage tanks are located within the berm, and therefore have secondary containment. Flowlines that go from the wells to the production equipment as well as the tank truck loading area are inspected daily by the pumper, as described in section 3.4 of this Plan. The installation of double-wall piping, berms, or other permanent structures (e.g., remote impoundment) around flowlines and tank truck loading area are impracticable at this facility due to the long distances involved and physical and road/fenceline right-of-way constraints. Sorbent materials in conjunction with drip pans provide adequate secondary containment for equipment and piping outside of the berm. Therefore, sorbent materials will be used when necessary.

#### 3.3 Other Spill Prevention Measures

#### 3.3.1 Bulk Storage Containers Overflow Prevention [112.9(c)(4)]

The tank battery is designed with a fail-safety system to prevent discharge, as follows:

- The capacity of the oil storage tanks is sufficient to ensure that oil storage is adequate in the event where facility personnel are unable to perform the daily visit to unload the tanks or the pumper is delayed in stopping production. The oil tanks are sized to provide sufficient storage for at least two days.
- Where applicable when multiple oil tanks are present the tanks are connected with overflow equalizing lines to ensure the full tank can overflow to an adjacent tank.

#### 3.3.2 Transfer Operations and Saltwater Disposal System [112.9(d)]

All aboveground valves and piping associated with transfer operations are inspected daily by the pumper and/or truck driver, as described in Section 3.4 of this Plan. The inspection procedure includes observing flange joints, valve glands and bodies, drip pans, and pipe supports.

Facility: North Bell Lake 2BSS

Page 18 of 32

#### 3.4 Inspections, Tests, and Records [112.7(e)]

This Plan outlines procedures for inspecting the facility equipment in accordance with SPCC requirements. Records of inspections performed as described in this Plan and signed by the appropriate supervisor are maintained at the Tulsa Corporate Office for a minimum of three years. The reports include a description of the inspection procedure, date of inspection and the inspector's signature.

Each container is inspected monthly by field operation personnel as described in this Plan section and following the checklist provided in Appendix B of this SPCC Plan. The inspection is aimed at identifying signs of deterioration and maintenance needs.

The inspection program is comprised of informal daily examinations, monthly scheduled inspections, and periodic condition inspections. Additional inspections and/or examinations are performed whenever an operation alert, malfunction, shell or deck leak, or potential bottom leak is reported following a scheduled examination. Written examination/inspection procedures and monthly examination/inspection reports are signed by the field inspector and are maintained at the corporate office for a period of at least three years.

#### 3.4.1 Daily Examinations

The facility is visited daily by field operations personnel. The daily visual examination consists of a walk through of the tank battery and around the well. Field operations personnel check the wells and production equipment for leaks and proper operation. They examine all aboveground valves, polished rod stuffing boxes, wellheads, fittings, gauges, and flowline piping at the wellhead. Personnel inspect pumps to verify proper function and check for damage and leakage. They look for accumulation of water within the tank battery berms. The storage tanks are gauged every day. A daily production report is maintained. All malfunctions, improper operation of equipment, evidence of leakage, stained or discolored soil, etc. are logged and communicated to the KFOC Production Superintendent.

#### 3.4.2 Monthly Reports

Leases and equipment are inspected daily. Any problems with the lease or equipment are recorded on the Monthly Inspection Report (Appendix B) and submitted with the gauge report for each month.

#### 3.4.3 Brittle Fracture Evaluation [112.7(i)]

At the present time, none of the bulk storage containers at this site are field-erected, and therefore no brittle fracture evaluation is required.

Facility: North Bell Lake 2BSS

Page 19 of 32

#### 3.4.4 Flowline Maintenance Program [112.9(d)(3)]

The facility is relying on sorbent materials to address discharges from flowlines. The flowline maintenance program is specifically implemented to maintain the integrity of the primary container (in this case piping) to minimize releases of oil from this part of the production facility. The facility's gathering lines and flowlines are inspected for leaks at connections and on each joint, corrosion (pitting, flaking), and maintained to minimize the potential for a discharge.

## 3.5 Personnel Training, and Discharge Prevention Procedures [112.7(f)]

The Production Superintendent has been designated as the point of contact for all oil discharge prevention and response at this facility.

All KFOC field personnel receive training on proper handling of oil products and procedures to respond to an oil discharge. The training ensures that all facility personnel understand the procedures described in the SPCC Plan and are informed of the requirements under applicable pollution control laws, rules and regulations. The training also covers risks associated with potential exposure to hydrogen sulfide (H2S) gas.

KFOC ensures that all contractor personnel are familiar with the facility operations, and spill prevention and control procedures described in this Plan.

KFOC management holds briefings with company field operations personnel at least once a year, as described below.

#### 3.5.1 Spill Prevention Briefing


The Safety & Environmental Coordinator conducts Spill Prevention Briefings annually to ensure adequate understanding and effective implementation of this SPCC Plan. These briefings highlight and describe known events or failures, malfunctioning components, and recently developed precautionary measures. The briefings are conducted in conjunction with the company safety meetings. Sign-in sheets, which include the topics of discussion at each meeting, are maintained in the Safety Department at KFOC's Corporate Office. The scheduled annual briefing includes a review of KFOC policies and procedures for SPCC inspections and spill prevention procedures; spill reporting procedures; spill response; and recovery, disposal, and treatment of spilled material.

Personnel are instructed in applicable federal, state, and local pollution laws, rules, and regulations. Facility operators and other personnel have an opportunity during the briefings to share recommendations concerning health, safety, and environmental issues encountered during facility operations.

Facility: North Bell Lake 2BSS

Page 20 of 32

## **APPENDIX A: Facility Diagrams**



Facility: North Bell Lake 2BSS Page 21 of 32

## SITE DIAGRAM FOR COMPLETED TANK BATTERY

Facility: North Bell Lake 2BSS Page 22 of 32

#### **APPENDIX B: Monthly Inspection Report**

A record of the completed checklists, with signatures, is maintained at the Tulsa KFOC office. Inspections are conducted using the following checklist in accordance with section 3.4 of this SPCC plan.

SPCC Inspection Checklist					
	<b>,</b>		· · · · · · · · · · · · · · · · · · ·		
Pumper: District:					
Facility ID:			·		
<u>-</u>					
Storage Areas and Separation Equipment	Y	Ņ	Description & Comments (Note tank/equipment ID)		
Tank surfaces showing signs of leakage					
Tanks showing signs of damage, rust or deterioration					
Damaged bolts, rivets or seams					
Deteriorated or buckled aboveground tank supports					
Eroded or settled Aboveground tank foundations					
Leaking gaskets					
Level gauges or alarms that are inoperative					
Obstructed vents					
Thief hatch and vent valve does not seal air tight					
Damaged or missing nets on open top vessels					
Containment berm showing discoloration or stains					
Berm that is breached or eroded or has vegetation	,				
Trash or vegetation inside of berm area					
Missing equipment guards, labels or signs					
Piping/Flowlines and Related Equipment					
Leaking valve seals or gaskets					
Damaged or deteriorated Pipelines or supports					
Buried pipelines that are exposed					
Visible line leaks			·		
Transfer Equipment					
Damaged or deteriorated loading/unloading lines			·		
Connections are not capped or blank-flanged					
Secondary Containment is damaged or stained					
Field drainage systems					
Accumulation of oil in drainage ditches or road ditches					
Accumulation of oil in oil traps, sumps, or skimmers					
If yes, you must promptly remove any accumulations of oil					
Response Kit Inventory:					
Discharge response material is missing or damaged or					
needs replaced					
Signature:	Da	ite:			

Facility: North Bell Lake 2BSS

Page 23 of 32

## **Monthly Inspection Report**

A detailed description of what to inspect is provided on page one of the Checklist										
District:						Pumper:				
Facility ID	Problems with Storage tanks & Separation Equipment		Problems with Piping/Flowlines & Related Equipment				Description & Comments (Note tank/equipment ID)			
	Υ	N	Y	N	Υ	N	,			
						<u> </u>				
,				•						
				· ·						
Pleas make sure all open top vessels are properly netted and the net is not damaged or deteriorated.  Further descriptions and comments, if needed, should be provided on the empty space at the bottom of this page or on a separate sheet of paper and attached to this page. Any item answered "Yes" needs to be promptly reported, repaired, or replaced as it may result in noncompliance with regulatory requirements.  Note: Leases and equipment should be inspected daily. Record any problems on this form and submit it monthly with your gauge report.										
Dat	e:				•	Signatı	ure:			

Facility: North Bell Lake 2BSS Page 24 of 32

#### **APPENDIX C: Record of Dike Drainage**

This record must be completed when rainwater from diked areas is drained into a storm drain or into an open watercourse, lake, or pond, and bypasses the water treatment system. The facility is not equipped with a manual valve of open-and-closed design. All water accumulated within the berm is closely inspected by field operations personnel (who are the persons providing "responsible supervision") to ensure that no free oil is present (i.e. there is no sheen or discoloration upon the surface, or a sludge or emulsion deposit beneath the surface of the water). Free oil is promptly removed and disposed of in accordance with waste regulations.

Date	Area	Presence of oil (y/n)	Time started	Time Finished	Signature
				•	

Facility: North Bell Lake 2BSS

Page 25 of 32

#### **APPENDIX D: Discharge Notification Procedures**

 WHEN REPORTING A DISCHARGE PROVIDE THE FOLLOWING INFORMATION:

Exact location;
Material involved;
Quantity involved;
Topographical and environmental conditions;
Circumstances that may hinder response; and Injuries, if any.

- WARN PERSONNEL. All personnel on facility will be verbally warned of the oil spill. If an explosion or fire occurs, evacuate personnel from the area until the danger is over.
- REQUEST ADDITIONAL RESOURCES. If oil has reached water or could reach water, facility personnel will decide whether the available onsite containment materials are sufficient to contain the spill. If it is estimated that additional materials will be necessary, an Oil Spill Removal Organization will be contacted at this time. An estimate of the amount of oil released shall be relayed to the Oil Spill Removal Organization.
- CONTAIN THE SPILLED OIL. Facility personnel will attempt to prevent the spilled oil from spreading. Available containment material will be deployed.
- **GATHER INFORMATION.** Information on the spill will be collected and the "Spill Notification Form" will be completed.
- MAKE NOTIFICATIONS. Facility personnel will contact Company Management. Information on the spill along with actions taken will be relayed to Company Management and Company Management will make all necessary notifications. If Company Management is not available facility personnel will make the notifications.
- CLEAN UP THE SPILLED OIL. Once the spill is contained to the maximum extent possible, available supplies will be used to proceed with cleanup of the spill. An Oil Spill Removal Organization will be mobilized as required.
- SPILL RESPONSE. If immediate cleanup is not considered to be an appropriate remedial measure, the operator will notify the proper agency and give an alternative remedial plan and will promptly implement said plan upon approval.

Facility: North Bell Lake 2BSS

Page 26 of 32

## **Spill Report Form**

Description of Discharge		
Date/time	Release date: Release time: Duration:	Discovery date: Discovery time:
Reporting Individual	Name:	Tel. #:
Location of discharge (Quarter, Block, Section, Survey, etc.)	County: State:	Description:
Surface Owner	Description of area: ☐ Farming ☐ Grazing ☐ Urban	
Equipment Sources	□ Piping □ Flowline □ Well □ Stock, flare □ Unknown	Description:  Equipment ID:
Product	□ Crude oil □ Saltwater □ Other*	*Description other:
Appearance and description of area	□ Sandy □ Sandy Loam □ Clay □ Rocky □ Wet □ Dry □ Snow	
Environmental conditions	Wind Direction: Wind Speed:	Rainfall: Current:
Site Drainage direction  Distance to nearest navigable water	·	

Facility: North Bell Lake 2BSS Page 27 of 32

### Kaiser-Francis Oil Company

## Spill Prevention, Control, and Countermeasure (SPCC) Plan

Impacts		
Quantity	Released:	Recovered:
Receiving Medium	□ Water** □ Land □ Other (describe):	□ Release confined to company property. □ Release outside company property  ** if water, indicate extent and body of water:
Describe Circumstances of the Release		
Assessment of impacts and remedial actions		
Disposal method for recovered material		
Action taken to prevent incident from reoccurring		
Safety Issues	☐ Fire ☐ Explosion ☐ Injuries ☐ Fatalities ☐ Evacuation ☐ *Other	*Description of other:
Notifications		
Agency Company Spill Response Coordinator	Name Charles W. Lock (918)491-4337	Date/time reported & Comments
National Response Center 1-800-424-8802		
OSRO/cleanup contractor		

Facility: North Bell Lake 2BSS Page 28 of 32

#### **Contact List and Phone Numbers**

Contact information for reporting a discharge to the National Response Center and other federal, state, and local agencies, and to other affected parties, is provided below. Note that any discharge to water must be reported immediately to the National Response Center.

The following is a contact list and phone number reference for the Facility:

Contacts	Primary	Alternate
Designated Person Accountable For Oil Spill Prevention and/or Facility Response Coordinator		
Name/Title: Kelly Roach/Pumper	432/238-6996	
Name/Title: Kenneth Wyatt/Prod. Foreman	432/563-2992	432/238-6986
Name/Title: Jeremy Parent/Prod. Foreman	580/504-2593	
Name/Title: Bill Wilkinson/Prod. Superintendent	580/221-4637	580/668-2334
Name/Title: David Zerger/Operations Engineer	918/491-4350	
Name/Title: Charles Lock/Safety & Envir.	918/491-4337	918/671-6510

Facility: North Bell Lake 2BSS

Page 29 of 32

### **Contact List and Phone Numbers**

The following is a contact list and phone number reference for the Facility:

Contacts	Primary	Alternate (Cell)
Cleanup Contractors (as necessary):	36	
Dozers – B&B Oilfield Service – Lovington	505/396-2177	
Vacuum & Tank Trucks – Clay Tank Trucks – Denver City	806/592-2087	
Misc. Trucks & Labor – Forklift Enter. – Hobbs	575/397-6431	
Pump Trucks – Halliburton – Hobbs	505/392-6531	
Frac Tanks – Stearns – Crossroads	505/675-2356	
Welder – Chuck's Welding – Hobbs	505/393-3316	
Federal, State and local agencies (as necessary)	Sec. Co.	
National Response Center	(800) 424-8802	(202) 267-2675
NMOCC - Hobbs	505/393-6161	
EPA Region 6	866/372-7745	,
OSHA – Lubbock	806/472-7681	800/321-OSHA
Other contact references:		
Fire Fighting – Hobbs	505/397-9308	
Police – Hobbs	505/397-9265	
Ambulance – Hobbs	505/397-2801	
Sheriff – Hobbs	505/393-2515	
Highway Patrol – Hobbs	505/392-5588	

Facility: North Bell Lake 2BSS Page 30 of 32

## APPENDIX E: Equipment Shut-off Procedures

Source	Action
Manifold, transfer pumps or hose failure	Shut in the well supplying oil to the tank battery if appropriate. Immediately close the header/manifold or appropriate valve(s). Shut off transfer pumps.
Tank overflow	Shut in the well supplying oil to the tank battery. Close header/manifold or appropriate valve(s).
Tank failure	Shut in the well supplying oil to the tank battery. Close inlet valve to the storage tanks.
Flowline rupture	Shut in the well supplying oil to the flowline. Immediately close the nearest valve to stop the flow of oil to the leaking section.
Flowline leak	Shut in the well supplying oil to the flowline. Immediately close the nearest valve to stop the flow of oil to the leaking section.
Explosion or fire	Immediately evacuate personnel from the area until the danger is over. Immediately shut in both wells if safe to do so. If possible, close all manifold valves. If the fire is small enough such that it is safe to do so, attempt to extinguish if extinguisher is available.
Equipment failure	Immediately close the nearest valve to stop the flow of oil into the leaking area.

Facility: North Bell Lake 2BSS Page 31 of 32

## APPENDIX F: Written Commitment of Manpower, Equipment, and Materials

In addition to implementing the preventive measures described in this Plan, Kaiser-Francis Oil Company will also:

In the event of a discharge:

- Make available trained field personnel to perform response actions
- Obtain assistance from additional employees from its main operations contractor.
- Collaborate with local, state, and federal authorities on response and cleanup operations.

Maintain all on-site oil spill control equipment described in this Plan and in the attached Oil Spill Contingency Plan.

Maintain all communications equipment in operating condition at all times.

Ensure that staging areas are accessible by field vehicles.

Review the adequacy of on-site and third party response capacity with preestablished response/cleanup contractors.

Maintain formal agreements/contracts with response and cleanup contractors who will provide assistance in responding to an oil discharge and/or completing cleanup.

Facility: North Bell Lake 2BSS

Page 32 of 32