Form 3160-5 (April 2004)

(Instructions on page 2)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

NMOCD Hobbs

FORM APPROVED OM B No. 1004-0137 Expires: March 31, 2007

		Lapires.	IVIG
j.	Lease So	erial No.	


Э.	Lease	oci	Itti	INO.
	NM	NI	42	264

SUNDRY	NOTICES AND RE	PORTS ON WELL	S	NMNM22642	
Do not use th	nis form for proposals ell. Use Form 3160-3	to drill or to re-ent	er an	6. If Indian, Allottee or Tribe Name	
SUBMIT IN TR	7. If Unit or CA/Agreement, Name and/or No. 8910180420				
Type of Well Oil Well					
Name of Operator Matador Pro		Young Deep Unit #39 9. API Well No.			
Address PO BOX 1936 ~ ROSWELL	NM 88202-1936	3b. Phone No. (include are 575,623,6601	ne No. (tuchide area code) 23.66013 BS OCD	30-025-38179 10. Field and Pool, or Exploratory Area	
Location of Well (Footage, Sec.,	T., R., M., or Survey Description)	1800 0 -	Service Control	Young; Bone Spring North	
1980' FSL & 660' FEL, Sec. 10	JAN 2 5	1114551321	11. County or Parish, State Lea, New Mexico		
12. CHECK A	PPROPRIATE BOX(ES) TO	O INDICATE NATURE	OF NOTICE, R	REPORT, OR OTHER DATA	
TYPE OF SUBMISSION		TYPE	OF ACTION		
Notice of Intent Subsequent Report Final Abandonment Notice	Acidize Alter Casing Casing Repair Change Plans Convert to Injection	Deepen Fracture Treat New Construction Plug and Abandon Plug Back	Production (Standard Reclamation) Recomplete Temporarily Al Water Disposal	Well Integrity Other	
Attach the Bond under which the following completion of the investing has been completed. Find determined that the site is ready BLM Bond No. NMB0001	ectionally or recomplete horizontal he work will be performed or provolved operations. If the operation nal Abandonment Notices shall be of final inspection.)	vide the Bond No. on file with n results in a multiple completic e filed only after all requiremen	BLM/BIA. Required on or recompletion	ue vertical depths of all pertinent markers and zones. red subsequent reports shall be filed within 30 days in a new interval, a Form 3160-4 shall be filed once nation, have been completed, and the operator has	
If the proposal is to deepen dire Attach the Bond under which the following completion of the investing has been completed. Find determined that the site is ready BLM Bond No. NMB0001 Surety Bond No. RLB001: MIRU PU and POOH w/J MIRU WL and RIH to set RIH and perf 1st Bone Spr RIH w/ tubing and packer Acidize perfs @ 8206-8216 Swab test Frac perfs @ 8206-8216', 3	ectionally or recomplete horizontal he work will be performed or provolved operations. If the operation and Abandonment Notices shall be of for final inspection.) 1079 15172 1079 15172 1089 1099 1099 1099 1099 1099 1099 1099	vide the Bond No. on file with n results in a multiple completic e filed only after all requirement filed only after all requirement to the filed only after all requirement filed only after all requirement filed on \$1.00 filed on \$	BLM/BIA. Requirence or recompletion its, including reclamates the second	ed subsequent reports shall be filed within 30 days in a new interval, a Form 3160-4 shall be filed once nation, have been completed, and the operator has 8182-8191'	
If the proposal is to deepen dire Attach the Bond under which the following completion of the investing has been completed. Find determined that the site is ready BLM Bond No. NMB0001 Surety Bond No. RLB001: MIRU PU and POOH w/J MIRU WL and RIH to set RIH and perf 1st Bone Sp RIH w/ tubing and packer Acidize perfs @ 8206-8216 Swab test Frac perfs @ 8206-8216', 3	ectionally or recomplete horizontal he work will be performed or provolved operations. If the operation and Abandonment Notices shall be of final inspection.) 1079 15172 1079 15172 1079 15172 1079 15172 1079 15172 1079 15172 1079 15172 1079 15172 1517	vide the Bond No. on file with n results in a multiple completic e filed only after all requirement filed only after all requirement to the filed only after all requirement filed only after all requirement filed on \$1.00 filed on \$	BLM/BIA. Requirence or recompletion its, including reclamates the second	red subsequent reports shall be filed within 30 days in a new interval, a Form 3160-4 shall be filed once nation, have been completed, and the operator has 8182-8191' ENTERED AT MASS	
If the proposal is to deepen dire Attach the Bond under which the following completion of the investing has been completed. Find determined that the site is ready BLM Bond No. NMB0001 Surety Bond No. RLB001: MIRU PU and POOH w/MIRU WL and RIH to set RIH and perf 1st Bone Spring RIH w/tubing and packer Acidize perfs @ 8206-8216 Swab test Frac perfs @ 8206-8216', i POOH w/pkr, RIH w/pro	ectionally or recomplete horizontal he work will be performed or provolved operations. If the operation hal Abandonment Notices shall be of for final inspection.) 1079 15172 1079 15172 1079 15172 1079 15172 1079 15172 1079 15172 15174 1517	vide the Bond No. on file with n results in a multiple completic e filed only after all requirement filed only after all requirement to the filed only after all requirement filed only after all requirement filed on \$1.00 filed on \$	BLM/BIA. Required on or recompletion its, including reclamates, in	ed subsequent reports shall be filed within 30 days in a new interval, a Form 3160-4 shall be filed once nation, have been completed, and the operator has 8182-8191'	
If the proposal is to deepen dire Attach the Bond under which the following completion of the investing has been completed. Find determined that the site is ready BLM Bond No. NMB0001 Surety Bond No. RLB001: MIRU PU and POOH w/ MIRU WL and RIH to set RIH and perf 1st Bone Sp RIH w/ tubing and packer Acidize perfs @ 8206-8216 Swab test Frac perfs @ 8206-8216', POOH w/ pkr, RIH w/ proposed to the property of the	ectionally or recomplete horizontal he work will be performed or provolved operations. If the operation hal Abandonment Notices shall be of for final inspection.) 1079 15172 1079 15172 1079 15172 1079 15172 1079 15172 1079 15172 15174 1517	vide the Bond No. on file with n results in a multiple completic e filed only after all requirement is test casing to 500# 6', 8146-8152', 8162-8166', 174-8177', and 8182-8191' Put well on Production. Se	BLM/BIA. Requirence or recompletion its, including reclamates, inc	ed subsequent reports shall be filed within 30 days in a new interval, a Form 3160-4 shall be filed once nation, have been completed, and the operator has 8182-8191'	
If the proposal is to deepen dire Attach the Bond under which the following completion of the investing has been completed. Findetermined that the site is ready BLM Bond No. NMB0001 Surety Bond No. RLB001: MIRU PU and POOH w/MIRU WL and RIH to set RIH and perf 1st Bone Sp RIH w/ tubing and packer Acidize perfs @ 8206-8216 Swab test Frac perfs @ 8206-8216', i POOH w/ pkr, RIH w/ pro	ctionally or recomplete horizontal he work will be performed or provolved operations. If the operation and Abandonment Notices shall be of for final inspection.) 079 5172 079 5172 079 5172 079 5172 079 5172 079 5172 079 5172 079 5172 079 5172 079 180 18146-8152	vide the Bond No. on file with n results in a multiple completic e filed only after all requirement to the filed only after the filed only afte	BLM/BIA. Requirence or recompletion its, including reclamates, inc	ed subsequent reports shall be filed within 30 days in a new interval, a Form 3160-4 shall be filed once nation, have been completed, and the operator has a state of the complete of the comp	
If the proposal is to deepen dire Attach the Bond under which the following completion of the investing has been completed. Findetermined that the site is ready BLM Bond No. NMB0001 Surety Bond No. RLB001: MIRU PU and POOH w/ MIRU WL and RIH to set RIH and perf 1st Bone Sp RIH w/ tubing and packer Acidize perfs @ 8206-8216 Swab test Frac perfs @ 8206-8216', i POOH w/ pkr, RIH w/ pro	ctionally or recomplete horizontal he work will be performed or provolved operations. If the operation and Abandonment Notices shall be of for final inspection.) 079 5172 079 5172 079 5172 079 5172 079 5172 079 5172 079 5172 079 5172 079 5172 079 180 18146-8152	vide the Bond No. on file with n results in a multiple completic e filed only after all requirement filed only after all requirement for the filed only after all requirement for the filed only after all requirement filed only after all requirement for the filed only after all requirement for the filed only after all requirement for the filed only after the filed o	BLM/BIA. Requirence or recompletion its, including reclamates, inc	ed subsequent reports shall be filed within 30 days in a new interval, a Form 3160-4 shall be filed once nation, have been completed, and the operator has a state of the complete of the comp	

MUB/OCD 2/3/2016

FEB 0 3 2016

on



Young Deep Unit 39 Young Field API #30-025-38179 UL-I-10-18S-32E Lea County 1980' FSL & 660' FEL

GL: 3.830.2' KB-3849.7' **Matador Resources**

prepared by T. Goodwin

DRAWING NOT TO SCALE.

TOPS Morrow

12,495 Wolfcamp 9,825 6,515 Bonespring

Wellbore Status as of:

10/07/15

Spud: TD:

1/29/2007 4/7/2007 13039'

Completed: 5/25/2007

PBTD:

4/7/2007 12973'


Set @

1418

10273

13039

Actual



PBTD: 12973' TD: 13039'

Young Deep Unit 39 30-025-38179 Matador Production Company January 19, 2016 Conditions of Approval

Notify BLM at 575-393-3612 a minimum of 24 hours prior to commencing work.

Work to be completed by April 19, 2016.

- 1. Operator shall place and additional 75' Class H cement on top of CIBP at 12,600' to properly seal the Morrow formation.
- 2. Operator shall place a balanced class H cement plug from 9,925'-9,649' to seal the top of the Wolfcamp formation and DV tool. WOC and tag required.
- 3. Must conduct a casing integrity test before perforating and fracturing. Submit results to BLM. The CIT is to be performed on the production casing to max treating pressure. Notify BLM if test fails
- **4.** Before casing or a liner is added or replaced, prior BLM approval of the design is required. Use notice of intent Form 3160-5.
- 5. Surface disturbance beyond the originally approved pad must have prior approval.
- 6. Closed loop system required.
- 7. All waste (i.e. drilling fluids, trash, salts, chemicals, sewage, gray water, etc.) created as a result of work over operations shall be safely contained and disposed of properly at a waste disposal facility. No waste material or fluid shall be disposed of on the well location or surrounding area. Porto-johns and trash containers will be on-location during fracturing operations or any other crew-intensive operations.
- 8. Operator to have H2S monitoring equipment on location.
- 9. A minimum of a 3000 (3M) BOP to be used. All blowout preventer (BOP) and related equipment (BOPE) shall comply with reasonable well control requirements. A two ram system with a blind ram and a pipe ram designed for the size of the work string shall be adequate. Tapered work strings will require an additional pipe ram. The manifold shall comply with Onshore Oil and Gas Order #2 Attachment I (3M Diagrams of Choke Manifold Equipment). The accumulator system shall have an immediately available power source to close the rams and retain 200 psi above pre-charge. The pre-charge test shall follow requirements in Onshore Order #2.

- 10. Subsequent sundry required detailing work done, C-102 form, and completion report with the new formation. Operator to include well bore schematic of current well condition when work is complete.
- 11. See attached for general requirements.

JAM 011916

BUREAU OF LAND MANAGEMENT Carlsbad Field Office 620 East Greene Street Carlsbad, New Mexico 88220 575-234-5972

Permanent Abandonment of Production Zone Conditions of Approval

Failure to comply with the following Conditions of Approval may result in a Notice of Incidents of Noncompliance (INC) in accordance with 43 CFR 3163.1.

1. Plugging operations shall commence within ninety (90) days from this approval.

If you are unable to plug back the well by the 90th day provide this office, prior to the 90th day, with the reason for not meeting the deadline and a date when we can expect the well to be plugged back. Failure to do so will result in enforcement action.

- 2. <u>Notification:</u> Contact the appropriate BLM office at least 24 hours prior to the commencing of any plug back operations. For wells in Eddy County, call 575-361-2822. For wells in Lea County, call 575-393-3612
- 3. <u>Blowout Preventers</u>: A blowout preventer (BOP), as appropriate, shall be installed before commencing any plugging operation. The BOP must be installed and maintained as per API and manufacturer recommendations. The minimum BOP requirement is a 2M system for a well not deeper than 9,090 feet; a 3M system for a well not deeper than 13,636 feet; and a 5M system for a well not deeper than 22,727 feet.
- 4. <u>Mud Requirement:</u> Mud shall be placed between all plugs. Minimum consistency of plugging mud shall be obtained by mixing at the rate of 25 sacks (50 pounds each) of gel per 100 barrels of **brine** water. Minimum nine (9) pounds per gallon.
- 5. <u>Cement Requirement</u>: Sufficient cement shall be used to bring any required plug to the specified depth and length. Any given cement volumes on the proposed plugging procedure are merely estimates and are not final. Unless specific approval is received, no plug except the surface plug shall be less than 25 sacks of cement. Any plug that requires a tag will have a minimum WOC time of 4 hours.

In lieu of a cement plug across perforations in a cased hole (not for any other plugs), a bridge plug set within 50 feet to 100 feet above the perforations shall be capped with 25 sacks of cement. If a bailer is used to cap this plug, 35 feet of cement shall be sufficient. **Before pumping or bailing cement on top of CIBP, tag will be required to verify depth.**

Unless otherwise specified in the approved procedure, the cement plug shall consist of either **Neat** Class "C", for up to 7,500 feet of depth or **Neat** Class "H", for deeper than 7,500 feet plugs.

6. <u>Subsequent Plug back Reporting:</u> Within 30 days after plug back work is completed, file one original and three copies of the Subsequent Report, Form 3160-5 to BLM. The report should give in detail the manner in which the plug back work was carried out, the extent (by depths) of cement plugs placed, and the size and location (by depths) of casing left in the well. <u>Show date work was completed.</u>

