Office	State of New Mexico	Form C-103
	CErergy, Minerals and Natural Resource	S May 27, 2004
1625 N. French Dr., Hobbs, NM 88240 District II		WELL API NO. 30-025-39448
1301 W. Grand Ave., Artesia, NM 882 00 2	OIL CONSERVATION DIVISION	5. Indicate Type of Lease
DISTRICT III	1220 South St. Francis Dr.	STATE S FEE
District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505	Santa Fe, NM 87505	6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM 87505		
SUNDRY NOTIC	ES AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name
	LLS TO DRILL OR TO DEEPEN OR PLUG BACK TO A TION FOR PERMIT" (FORM C-101) FOR SUCH	Moore Bailout "11" St
PROPOSALS.)	/ —	8. Well Number
	as Well Other	1 H
2. Name of Operator Caza Operating, LLC		9. OGRID Number 249099
3. Address of Operator		10. Pool name or Wildcat
200 N. Loraine, Ste. 1550 Midland,	TX 79701	Wildcat Wolfcamp
4. Well Location		
Unit Letter A: 660 fee	et from theNline and_990feet from the	E line
	ownship 11S Range 32E	NMPM County LEA
	11. Elevation (Show whether DR, RKB, RT, GR	
Pit or Below-grade Tank Application or o		
	erDistance from nearest fresh water well	
Pit Liner Thickness: mil	Below-Grade Tank: Volumebbl	s; Construction Material
12. Check Ap	opropriate Box to Indicate Nature of No	tice, Report or Other Data
NOTICE OF INT		SUBSEQUENT REPORT OF:
	INTIUFA	
TEMPORARILY ABANDON	CI P&A NR COMMENC	E DRILLING OPNS. □ P AND A
	M P&A R CASING/CE	
		-
OTHER:	OTHER:	
13. Describe proposed or comple	ted operations. (Clearly state all pertinent detail	Ils, and give pertinent dates, including estimated date
13. Describe proposed or comple of starting any proposed world	ted operations. (Clearly state all pertinent detail	lls, and give pertinent dates, including estimated date as: Attach wellbore diagram of proposed completion
13. Describe proposed or comple	ted operations. (Clearly state all pertinent detail	
13. Describe proposed or comple of starting any proposed work or recompletion. 5/16/16 – RIH w/7" C/R to 7700' – RI	ted operations. (Clearly state all pertinent details). SEE RULE 1103. For Multiple Completion	
13. Describe proposed or comple of starting any proposed work or recompletion. 5/16/16 – RIH w/7" C/R to 7700' – RI 5/17/16 – Circ salt gel mud 75sx.	ted operations. (Clearly state all pertinent details). SEE RULE 1103. For Multiple Completion IH w/7" CIBP to 7700' & set.	
13. Describe proposed or comple of starting any proposed work or recompletion. 5/16/16 – RIH w/7" C/R to 7700' – RI 5/17/16 – Circ salt gel mud 75sx. 5/18/16 – Circ salt gel mud 30sx. Pres	ted operations. (Clearly state all pertinent details). SEE RULE 1103. For Multiple Completion IH w/7" CIBP to 7700' & set.	
13. Describe proposed or comple of starting any proposed work or recompletion. 5/16/16 – RIH w/7" C/R to 7700' – RI 5/17/16 – Circ salt gel mud 75sx. 5/18/16 – Circ salt gel mud 30sx. Pres 5/18/16 – Spot 25sx class H on CIBP.	ted operations. (Clearly state all pertinent details). SEE RULE 1103. For Multiple Completion IH w/7" CIBP to 7700' & set.	
13. Describe proposed or comple of starting any proposed work or recompletion. 5/16/16 – RIH w/7" C/R to 7700' – RI 5/17/16 – Circ salt gel mud 75sx. 5/18/16 – Circ salt gel mud 30sx. Pres 5/18/16 – Spot 25sx class H on CIBP. 5/18/16 – Spot 35sx class C @ 4798'	ted operations. (Clearly state all pertinent details). SEE RULE 1103. For Multiple Completion IH w/7" CIBP to 7700' & set. Is test 7" csg. Hold good @ 500psi for 30min. — WOC. Tag @ 4663'.	
13. Describe proposed or comple of starting any proposed work or recompletion. 5/16/16 – RIH w/7" C/R to 7700' – RI 5/17/16 – Circ salt gel mud 75sx. 5/18/16 – Circ salt gel mud 30sx. Pres 5/18/16 – Spot 25sx class H on CIBP. 5/18/16 – Spot 35sx class C @ 4798' 5/20/16 – Perf 7" csg @ 2275'. Was n 30sx @ 2325' & WOC. Tag @ 2237'.	ted operations. (Clearly state all pertinent details). SEE RULE 1103. For Multiple Completion IH w/7" CIBP to 7700' & set. st test 7" csg. Hold good @ 500psi for 30min. WOC. Tag @ 4663'. tot able to get inj. rate 1300-1500psi. Advised be	s: Attach wellbore diagram of proposed completion
13. Describe proposed or comple of starting any proposed work or recompletion. 5/16/16 – RIH w/7" C/R to 7700' – RI 5/17/16 – Circ salt gel mud 75sx. 5/18/16 – Circ salt gel mud 30sx. Pres 5/18/16 – Spot 25sx class H on CIBP. 5/18/16 – Spot 35sx class C @ 4798' - 5/20/16 – Perf 7" csg @ 2275'. Was n 30sx @ 2325' & WOC. Tag @ 2237'. 5/23/16 – Perf @ 1380'. Sqz 50sx cmt	ted operations. (Clearly state all pertinent details). SEE RULE 1103. For Multiple Completion IH w/7" CIBP to 7700' & set. Is test 7" csg. Hold good @ 500psi for 30min. WOC. Tag @ 4663'. Into table to get inj. rate 1300-1500psi. Advised bot. It. WOC Tag @ 1218'.	s: Attach wellbore diagram of proposed completion y Mark W (OCD) to spot 30sx 50' below perf. Spot
13. Describe proposed or comple of starting any proposed work or recompletion. 5/16/16 – RIH w/7" C/R to 7700' – RI 5/17/16 – Circ salt gel mud 75sx. 5/18/16 – Circ salt gel mud 30sx. Pres 5/18/16 – Spot 25sx class H on CIBP. 5/18/16 – Spot 35sx class C @ 4798' - 5/20/16 – Perf 7" csg @ 2275'. Was n 30sx @ 2325' & WOC. Tag @ 2237'. 5/23/16 – Perf @ 1380'. Sqz 50sx cmt 5/23/16 – Perf @ 602' sqz 240sx to su	ted operations. (Clearly state all pertinent details). SEE RULE 1103. For Multiple Completion IH w/7" CIBP to 7700' & set. Is test 7" csg. Hold good @ 500psi for 30min. WOC. Tag @ 4663'. Into table to get inj. rate 1300-1500psi. Advised bot. It. WOC Tag @ 1218'.	s: Attach wellbore diagram of proposed completion
13. Describe proposed or comple of starting any proposed work or recompletion. 5/16/16 – RIH w/7" C/R to 7700' – RI 5/17/16 – Circ salt gel mud 75sx. 5/18/16 – Circ salt gel mud 30sx. Pres 5/18/16 – Spot 25sx class H on CIBP. 5/18/16 – Spot 35sx class C @ 4798' 5/20/16 – Perf 7" csg @ 2275'. Was n 30sx @ 2325' & WOC. Tag @ 2237'. 5/23/16 – Perf @ 1380'. Sqz 50sx cmt 5/23/16 – Perf @ 602' sqz 240sx to su 602)	ted operations. (Clearly state all pertinent details). SEE RULE 1103. For Multiple Completion IH w/7" CIBP to 7700' & set. It stest 7" csg. Hold good @ 500psi for 30min. WOC. Tag @ 4663'. It is a set of the s	y Mark W (OCD) to spot 30sx 50' below perf. Spot was okayed by Mark W to circ cmt to surf. from
13. Describe proposed or comple of starting any proposed work or recompletion. 5/16/16 – RIH w/7" C/R to 7700' – RI 5/17/16 – Circ salt gel mud 75sx. 5/18/16 – Circ salt gel mud 30sx. Pres 5/18/16 – Spot 25sx class H on CIBP. 5/18/16 – Spot 35sx class C @ 4798' 5/20/16 – Perf 7" csg @ 2275'. Was n 30sx @ 2325' & WOC. Tag @ 2237'. 5/23/16 – Perf @ 1380'. Sqz 50sx cmt 5/23/16 – Perf @ 602' sqz 240sx to su 602)	ted operations. (Clearly state all pertinent details). SEE RULE 1103. For Multiple Completion IH w/7" CIBP to 7700' & set. Is test 7" csg. Hold good @ 500psi for 30min. WOC. Tag @ 4663'. Into table to get inj. rate 1300-1500psi. Advised bot. It. WOC Tag @ 1218'.	y Mark W (OCD) to spot 30sx 50' below perf. Spot was okayed by Mark W to circ cmt to surf. from
13. Describe proposed or comple of starting any proposed work or recompletion. 5/16/16 – RIH w/7" C/R to 7700' – RI 5/17/16 – Circ salt gel mud 75sx. 5/18/16 – Circ salt gel mud 30sx. Pres 5/18/16 – Spot 25sx class H on CIBP. 5/18/16 – Spot 35sx class C @ 4798' 5/20/16 – Perf 7" csg @ 2275'. Was n 30sx @ 2325' & WOC. Tag @ 2237'. 5/23/16 – Perf @ 1380'. Sqz 50sx cmt 5/23/16 – Perf @ 602' sqz 240sx to su 602)	ted operations. (Clearly state all pertinent details). SEE RULE 1103. For Multiple Completion IH w/7" CIBP to 7700' & set. It stest 7" csg. Hold good @ 500psi for 30min. WOC. Tag @ 4663'. It is a set of the s	y Mark W (OCD) to spot 30sx 50' below perf. Spot was okayed by Mark W to circ cmt to surf. from
13. Describe proposed or comple of starting any proposed work or recompletion. 5/16/16 – RIH w/7" C/R to 7700' – RI 5/17/16 – Circ salt gel mud 75sx. 5/18/16 – Circ salt gel mud 30sx. Pres 5/18/16 – Spot 25sx class H on CIBP. 5/18/16 – Spot 35sx class C @ 4798' 5/20/16 – Perf 7" csg @ 2275'. Was n 30sx @ 2325' & WOC. Tag @ 2237'. 5/23/16 – Perf @ 1380'. Sqz 50sx cmt 5/23/16 – Perf @ 602' sqz 240sx to su 602)	ted operations. (Clearly state all pertinent details). SEE RULE 1103. For Multiple Completion IH w/7" CIBP to 7700' & set. It stest 7" csg. Hold good @ 500psi for 30min. WOC. Tag @ 4663'. It is a set of the s	y Mark W (OCD) to spot 30sx 50' below perf. Spot was okayed by Mark W to circ cmt to surf. from
13. Describe proposed or comple of starting any proposed work or recompletion. 5/16/16 – RIH w/7" C/R to 7700' – RI 5/17/16 – Circ salt gel mud 75sx. 5/18/16 – Circ salt gel mud 30sx. Pres 5/18/16 – Spot 25sx class H on CIBP. 5/18/16 – Spot 35sx class C @ 4798' 5/20/16 – Perf 7" csg @ 2275'. Was n 30sx @ 2325' & WOC. Tag @ 2237'. 5/23/16 – Perf @ 1380'. Sqz 50sx cmt 5/23/16 – Perf @ 602' sqz 240sx to su 602)	ted operations. (Clearly state all pertinent details). SEE RULE 1103. For Multiple Completion IH w/7" CIBP to 7700' & set. It stest 7" csg. Hold good @ 500psi for 30min. WOC. Tag @ 4663'. It is a set of the s	y Mark W (OCD) to spot 30sx 50' below perf. Spot was okayed by Mark W to circ cmt to surf. from
13. Describe proposed or comple of starting any proposed work or recompletion. 5/16/16 – RIH w/7" C/R to 7700' – RI 5/17/16 – Circ salt gel mud 75sx. 5/18/16 – Circ salt gel mud 30sx. Pres 5/18/16 – Spot 25sx class H on CIBP. 5/18/16 – Spot 35sx class C @ 4798' - 5/20/16 – Perf 7" csg @ 2275'. Was n 30sx @ 2325' & WOC. Tag @ 2237'. 5/23/16 – Perf @ 1380'. Sqz 50sx cmt 5/23/16 – Perf @ 602' sqz 240sx to su 602) 5/24/16 – Tag plug @ 43'. Top off w/9	ted operations. (Clearly state all pertinent details). SEE RULE 1103. For Multiple Completion IH w/7" CIBP to 7700' & set. It sets 7" csg. Hold good @ 500psi for 30min. WOC. Tag @ 4663'. It is at a 1300-1500psi. Advised by the word of the set of the word of	y Mark W (OCD) to spot 30sx 50° below perf. Spot was okayed by Mark W to circ cmt to surf. from PLETE.
13. Describe proposed or comple of starting any proposed work or recompletion. 5/16/16 – RIH w/7" C/R to 7700' – RI 5/17/16 – Circ salt gel mud 75sx. 5/18/16 – Circ salt gel mud 30sx. Pres 5/18/16 – Spot 25sx class H on CIBP. 5/18/16 – Spot 35sx class C @ 4798' 5/20/16 – Perf 7" csg @ 2275'. Was n 30sx @ 2325' & WOC. Tag @ 2237'. 5/23/16 – Perf @ 1380'. Sqz 50sx cmt 5/23/16 – Perf @ 602' sqz 240sx to su 602) 5/24/16 – Tag plug @ 43'. Top off w/s	ted operations. (Clearly state all pertinent details). SEE RULE 1103. For Multiple Completion IH w/7" CIBP to 7700' & set. It sets 7" csg. Hold good @ 500psi for 30min. WOC. Tag @ 4663'. It is a late to get inj. rate 1300-1500psi. Advised by the work of the	y Mark W (OCD) to spot 30sx 50' below perf. Spot was okayed by Mark W to circ cmt to surf. from
13. Describe proposed or comple of starting any proposed work or recompletion. 5/16/16 – RIH w/7" C/R to 7700' – RI 5/17/16 – Circ salt gel mud 75sx. 5/18/16 – Circ salt gel mud 30sx. Pres 5/18/16 – Spot 25sx class H on CIBP. 5/18/16 – Spot 35sx class C @ 4798' 5/20/16 – Perf 7" csg @ 2275'. Was n 30sx @ 2325' & WOC. Tag @ 2237'. 5/23/16 – Perf @ 1380'. Sqz 50sx cm 5/23/16 – Perf @ 602' sqz 240sx to su 602) 5/24/16 – Tag plug @ 43'. Top off w/2	ted operations. (Clearly state all pertinent details). SEE RULE 1103. For Multiple Completion III w/7" CIBP to 7700' & set. Is test 7" csg. Hold good @ 500psi for 30min. — WOC. Tag @ 4663'. Into the able to get inj. rate 1300-1500psi. Advised by the set. It. WOC Tag @ 1218'. Into Had good cmt circ to pit. Ouf of 9 5/8 csg. (20sx cmt. Add on dry hole marker. JOB COMF	y Mark W (OCD) to spot 30sx 50° below perf. Spot was okayed by Mark W to circ cmt to surf. from PLETE. wledge and belief. I further certify that any pit or belowmit or an (attached) alternative OCD-approved plan
13. Describe proposed or comple of starting any proposed work or recompletion. 5/16/16 – RIH w/7" C/R to 7700' – RI 5/17/16 – Circ salt gel mud 75sx. 5/18/16 – Circ salt gel mud 30sx. Pres 5/18/16 – Spot 25sx class H on CIBP. 5/18/16 – Spot 35sx class C @ 4798' 5/20/16 – Perf 7" csg @ 2275'. Was n 30sx @ 2325' & WOC. Tag @ 2237'. 5/23/16 – Perf @ 1380'. Sqz 50sx cmt 5/23/16 – Perf @ 602' sqz 240sx to su 602) 5/24/16 – Tag plug @ 43'. Top off w/s	ted operations. (Clearly state all pertinent details). SEE RULE 1103. For Multiple Completion IH w/7" CIBP to 7700' & set. Is test 7" csg. Hold good @ 500psi for 30min. WOC. Tag @ 4663'. Not able to get inj. rate 1300-1500psi. Advised by the completion of the completion of the completion of the complete to pit. Ouf of 9 5/8 csg. (20sx cmt. Add on dry hole marker. JOB COMF	y Mark W (OCD) to spot 30sx 50° below perf. Spot was okayed by Mark W to circ cmt to surf. from PLETE.
13. Describe proposed or comple of starting any proposed work or recompletion. 5/16/16 – RIH w/7" C/R to 7700' – RI 5/17/16 – Circ salt gel mud 75sx. 5/18/16 – Circ salt gel mud 30sx. Pres 5/18/16 – Spot 25sx class H on CIBP. 5/18/16 – Spot 35sx class C @ 4798' 5/20/16 – Perf 7" csg @ 2275'. Was n 30sx @ 2325' & WOC. Tag @ 2237'. 5/23/16 – Perf @ 1380'. Sqz 50sx cm 5/23/16 – Perf @ 602' sqz 240sx to su 602) 5/24/16 – Tag plug @ 43'. Top off w/s 1 hereby certify that the information al grade tank has been/will be constructed or classification.	ted operations. (Clearly state all pertinent details). SEE RULE 1103. For Multiple Completion III w/7" CIBP to 7700' & set. Is test 7" csg. Hold good @ 500psi for 30min. — WOC. Tag @ 4663'. Into the able to get inj. rate 1300-1500psi. Advised by the set. It. WOC Tag @ 1218'. Into Had good cmt circ to pit. Ouf of 9 5/8 csg. (20sx cmt. Add on dry hole marker. JOB COMF	y Mark W (OCD) to spot 30sx 50° below perf. Spot was okayed by Mark W to circ cmt to surf. from PLETE. wledge and belief. I further certify that any pit or belowmit or an (attached) alternative OCD-approved plan
13. Describe proposed or comple of starting any proposed work or recompletion. 5/16/16 – RIH w/7" C/R to 7700' – RI 5/17/16 – Circ salt gel mud 75sx. 5/18/16 – Circ salt gel mud 30sx. Pres 5/18/16 – Spot 25sx class H on CIBP. 5/18/16 – Spot 35sx class C @ 4798' 5/20/16 – Perf 7" csg @ 2275'. Was n 30sx @ 2325' & WOC. Tag @ 2237'. 5/23/16 – Perf @ 1380'. Sqz 50sx cm 5/23/16 – Perf @ 602' sqz 240sx to su 602) 5/24/16 – Tag plug @ 43'. Top off w/2	ted operations. (Clearly state all pertinent details). SEE RULE 1103. For Multiple Completion IH w/7" CIBP to 7700' & set. Is test 7" csg. Hold good @ 500psi for 30min. — WOC. Tag @ 4663'. Into the able to get inj. rate 1300-1500psi. Advised by the set. Into the set of the best of my known is true and complete to the best of my kn	y Mark W (OCD) to spot 30sx 50' below perf. Spot was okayed by Mark W to circ cmt to surf. from PLETE. wledge and belief. I further certify that any pit or belowmit or an (attached) alternative OCD-approved plan .
13. Describe proposed or comple of starting any proposed work or recompletion. 5/16/16 – RIH w/7" C/R to 7700' – RI 5/17/16 – Circ salt gel mud 75sx. 5/18/16 – Circ salt gel mud 30sx. Pres 5/18/16 – Spot 25sx class H on CIBP. 5/18/16 – Spot 35sx class C @ 4798' 5/20/16 – Perf 7" csg @ 2275'. Was n 30sx @ 2325' & WOC. Tag @ 2237'. 5/23/16 – Perf @ 1380'. Sqz 50sx cm 5/23/16 – Perf @ 602' sqz 240sx to su 602) 5/24/16 – Tag plug @ 43'. Top off w/s I hereby certify that the information al grade tank has been/will be constructed or classification. Type or print name For State Use Only	ted operations. (Clearly state all pertinent details). SEE RULE 1103. For Multiple Completion IH w/7" CIBP to 7700' & set. Is test 7" csg. Hold good @ 500psi for 30min. — WOC. Tag @ 4663'. Into the able to get inj. rate 1300-1500psi. Advised by the set. Into the set of the best of my known is true and complete to the best of my kn	y Mark W (OCD) to spot 30sx 50' below perf. Spot was okayed by Mark W to circ cmt to surf. from PLETE. wledge and belief. I further certify that any pit or belowmit or an (attached) alternative OCD-approved plan .
13. Describe proposed or comple of starting any proposed work or recompletion. 5/16/16 – RIH w/7" C/R to 7700' – RI 5/17/16 – Circ salt gel mud 75sx. 5/18/16 – Circ salt gel mud 30sx. Pres 5/18/16 – Spot 25sx class H on CIBP. 5/18/16 – Spot 35sx class C @ 4798' 5/20/16 – Perf 7" csg @ 2275'. Was n 30sx @ 2325' & WOC. Tag @ 2237'. 5/23/16 – Perf @ 1380'. Sqz 50sx cm 5/23/16 – Perf @ 602' sqz 240sx to su 602) 5/24/16 – Tag plug @ 43'. Top off w/s 1 hereby certify that the information al grade tank has been/will be constructed or classification.	ted operations. (Clearly state all pertinent details). SEE RULE 1103. For Multiple Completion IH w/7" CIBP to 7700' & set. Is test 7" csg. Hold good @ 500psi for 30min. — WOC. Tag @ 4663'. Into the able to get inj. rate 1300-1500psi. Advised by the set. Into the set of the best of my known is true and complete to the best of my kn	y Mark W (OCD) to spot 30sx 50' below perf. Spot was okayed by Mark W to circ cmt to surf. from PLETE. wledge and belief. I further certify that any pit or belowmit or an (attached) alternative OCD-approved plan . Managar DATE 6.1.16