Submit 3 Copies To Appropriate District	Chaha af l	Navias		Form C-103
Office District.	State of New Mexico		WELL API NO.	October 25, 2005
1625 N. French Dr., Hobbs, NM 88240	Energy, Minerals and Natural Resources			005 00004
District II 1301 W. Grand Ave., Artesia, NM 88210	HOBBSICONSERVATION DIVISION		5. Indicate Type of L	-025-06021 /
Disrtict III	JUN 3 0 2016 220 South	St Francia Dr	STAT	
1000 Rio Brazos Rd. Aztec, NM 87410 District IV	Santa Ea	5t. Francis Dr. , NM 87505	6. State Oil & Gas Le	
1220 S. St. Francis Dr., Santa Fe, NM 87505	RECEIVED	,		
SUNDRY NOTICES AND REPORTS ON WELLS			7. Lease Name or Unit Agreement Name	
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR DEEPEN OR PLUG BACK TO A DIFFERENT RESERVIOR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH				
PROPOSALS.)  1. Type of Well: Oil Well ☑ Gas Well ☐ Other			8. Well Number	4
2. Name of Operator			9. OGRID Number	
	pache Corporation		10.5.111	873
3. Address of Operator 303 Veterans Airpa	ark Ln., Ste. 3000, Midland,	TX. 79705	10. Pool Name <b>Eunice N</b>	Monument G/SA
4. Well Location			•	4
Unit Letter D Section 8	: 330 feet from the Township 20S		990 feet from NMPM	
Section 8	Township <b>20S</b> 11. Elevation (Show whether		NMPM	County Lea
	The state of the s	3566' GR		
12. Check Appropriate Box To In	dicate Nature of Notice, Repo	ort, or Other Data		
NOTICE OF INTENTION TO:  PERFORM REMEDIAL WORK  PLUG AND ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PAND A PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMENT JOB				
DOWNHOLE COMMINGLE				Dany
OTHER:			ready for OCD inspection	on after P&A
All pits have been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan.  Rat hole and cellar have been filled and leveled. Cathodic protection holes have been properly abandoned.  A steel marker at least 4" in diameter and at least 4' above ground level has been set in concrete. It shows the				
OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, QUARTER / QUARTER LOCATION OR UNIT LETTER, SECTION, TOWNSHIP, AND RANGE. ALL INFORMATION HAS BEEN WELDED OR				
PERMANENTLY STAMPED ON THE MARKER'S SURFACE.				
The location has been leveled as nearly as possible to the original ground contour and has been cleared of all junk, trash, flow lines and other production equipment.				
Anchors, dead men, tie downs and risers have been cut off at least two feet below ground level.				
If this is a one-well lease or last remaining well on lease, the battery and pit location(s) have been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, production equipment and junk have been removed				
from the lease and well location.				
All metal bolts and other materials have been removed. Portable bases have been removed. (Poured onsite concrete bases do not have				
to be removed.)  All other environmental concrens have been addressed as per OCD rules.				
Pipelines and flow lines have been abandoned in accordance with 19.15.9.714.B(4)(b) NMAC. All fluids have been removed from non-retrieved flow lines and pipelines.				
When all work has been completed, return this form to the appropriate District office to schedule an inspection. If more than one inspection has to be made to a P&A location because it does not meet the criteria above, a penalty may be assessed.				
	. ()			0/07/40
SIGNATURE	TITLE	P&A Technic		6/27/16
TYPE OR PRINT NAME  For State Use Only	eon Sellers	leon.sellers@apache	ecorp.com PHONE	432-208-0349
APPROVED BY: Conditions of Approval (if any):	Whitaba TITLE	P.E.S.	DATE	7/5-12016