Submit 1 Copy To Appropriate District Office	State of New Mexico	Form C-103	
District I – (575) 393-6161 1625 N. French Dr., Hobbs, NM 88240	Energy, Minerals and Natural Resources	Revised July 18, 2013	
District II - (575) 748-1283	OCD OUL CONSERVATION DIVISION	30-025-34239	
811 S. First St., Artesia, NM 88210	1220 Genth St. Francis D	5. Indicate Type of Lease	
1000  Rio Brazos Rd., Aztec, NM 87410 11	2016 1220 South St. Francis Dr.	STATE FEE	
<u>District IV</u> – (505) 476-3460	Santa Fe, NM 87505	6. State Oil & Gas Lease No.	
1220 S. St. Francis Dr., Santa Fe, NM 87505	IVED	E-8176	
	CES AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name	
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		State C	
	Gas Well 🛛 Other SWD	8. Well Number 3	
2. Name of Operator		9. OGRID Number 164070	
3. Address of Operator	ladin Energy Corp.	10. Deal arms on Wildret	
10290 Monroe Dr., Ste. 301, Dallas, Texas 75229		10. Pool name or Wildcat SWD (96101)	
4. Well Location	, 10/10/15/22/	5WD (90101)	
Unit Letter E: 1550 _feet from the North line and 10 _feet from theWest line			
Section 36	Township 13S Range 37E		
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3845' GR			
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data			
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:			
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING F			
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. P AND A			
PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMENT JOB			

 Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

 $\boxtimes$ 

OTHER:

Suspect leak in plastic coated tubing.

Repair tubing leak.

DOWNHOLE COMMINGLE

**CLOSED-LOOP SYSTEM** 

OTHER:

<u>PROPOSED:</u> Pull plastic coated 5-1/2" Packer and 3-1/2" tubing. Inspect and test tubing on the way out of hole. Change out suspected bad tubing and redress packer. RIH with tubing and re-set packer within 100' of upper perforations from 11,920' - 11,980'. (present packer setting at 11,839'.) N/U wellhead. Test annulus and chart test. Submit test to OCD. Resume SWD operations. <u>Order Number: SWD -1112</u>.

Spud Date:	Rig Release Date:	Condition of Approval: notify OCD Hobbs office 24 hours		
		prior of running MIT Test & Chart		
I hereby certify that the information above is true and complete to the best of my knowledge and belief.   SIGNATURE				
Type or print name <u>David Plaisance</u> E-mail address: <u>dplaisance@paladinenergy.com</u> PHONE: <u>214-654-0132</u> For State Use Only Approved BY: <u>Approved Conditions of Approved (if any)</u> :				