## State of New Mexico Energy, Minerals and Natural Resources Department

Susana Martinez

Governor

**David Martin** 


Cabinet Secretary

**Tony Delfin** 

Deputy Cabinet Secretary

David Catanach, Director

Oil Conservation Division



Field Inspection Program "Preserving the Integrity of Our Environment"

JUL 1 9 2016

RECEIVED

19-Jul-16

## DAVID H ARRINGTON OIL & GAS INC

500 WEST WALL ST, SUITE 300 MIDLAND TX 79701

**LETTER OF VIOLATION - Inspection** 

Dear Operator:

The following inspection(s) indicate that the well, equipment, location or operational status of the well(s) failed to meet standards of the New Mexico Oil Conservation Division as described in the detail section below. To comply with standards imposed by Rules and Regulations of the Division, corrective action must be taken immediately and the situation brought into compliance. The detail section indicates preliminary findings and/or probable nature of the violation. This determination is based on an inspection of your well or facility by an inspector employed by the Oil Conservation Division on the date(s) indicated.

Please notify the proper district office of the Division, in writing, of the date corrective actions are scheduled to be made so that arrangements can be made to reinspect the well and/or facility.

## INSPECTION DETAIL SECTION

**ROYAL HUMPY** No.001 I-16-16S-36E 30-025-34607-00-00 Inspection \*Significant Corrective Type Inspection Inspector Violation? Inspection No. Date Non-Compliance? Action Due By: 07/19/2016 Routine/Periodic Mark Whitaker Yes No 8/26/2016 iMAW1620155832

Violations

Surface Damage/Restoration

Comments on Inspection: DO NOT RELEASE BONDS. Location is not ready to release. Operator has ripped location

exposing tubing and conduit west and north of P&A marker. Also noted 2 H-posts on northwest corner of location and barbed wire next to ripped road into location. NEED TO REMOVE ALL EXPOSED CONDUIT AND TUBING AND BARBED WIRE. NEED TO REMOVE H-POSTS

FROM NORTHWEST CORNER OF LOCATION, 1ST NOTICE.

LORD BALTIMORE 20 STATE

No.001

K-20-16S-35E

30-025-35172-00-00

Inspection

Date 07/19/2016

**Type Inspection** 

Inspector

Violation?

\*Significant Non-Compliance? Corrective Action Due By:

Inspection No.

Violatio

Routine/Periodic

Mark Whitaker

Yes

No.

8/26/2016

iMAW1620156192

Violations

Surface Damage/Restoration

Comments on Inspection:

DO NOT RELEASE BONDS. Location not ready to release. Conduit on west side of location. Contaminated soil on east side of location where battery was. Hole around P&A marker. Meter base south of location. NEED TO REMOVE CONDUIT. NEED TO BACKFILL IN AROUND P&A MARKER. NEED TO REMOVE CONTAMINATED SOIL EAST OF MARKER WHERE BATTERY WAS AND PROPERLY DISPOSE OF. NEED TO CONTACT GAS PURCHASER AND REQUEST METER BASE BE REMOVED AND SALES LINE BLIND FLANGED. ATTACH A COPY OF THIS CORRESPONDENCE TO THE C103 RELEASE FORM WHEN

WORK IN COMPLETE. 1ST NOTICE.

In the event that a satisfactory response is not received to this letter of direction by the "Corrective Action Due By:" date shown above, further enforcement will occur. Such enforcement may include this office applying to the Division for an order summoning you to a hearing before a Divison, Examiner in Santa Fe to show cause why you should not be ordered to permanently plug and abandon this well.

Sincerely,

tetroleum Engr. Speciali

Hobbs OCD District Office

Note: Information in Detail Section comes directly from field inspector data entries - not all blanks will contain data.

\*Significant Non-Compliance events are reported directly to the EPA, Region VI, Dallas, Texas.

**EMNRD OIL CONSERVATION DIVISION 1625 N FRENCH DRIVE HOBBS NM 88240** 



HASLER
FIRST-CLASS MAIL
\$000.67<sup>5</sup>
07/19/2016 ZIP 88240
012E14642224

**DAVID H ARRINGTON OIL & GAS INC 500 WEST WALL ST, SUITE 300** MIDLAND, TX 79701