

Submit 1 Copy To Appropriate District  
Office  
District I - (575) 393-6161  
1625 N. French Dr., Hobbs, NM 88240  
District II - (575) 748-1283  
811 S. First St., Artesia, NM 88210  
District III - (505) 334-6178  
1000 Rio Brazos Rd., Aztec, NM 87410  
District IV - (505) 476-3460  
1220 S. St. Francis Dr., Santa Fe, NM  
87505

State of New Mexico  
Energy, Minerals and Natural Resources

Form C-103  
Revised July 18, 2013

WELL API NO. 30-025-42471
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. 19552
7. Lease Name or Unit Agreement Name North Hobbs Unit (G/SA)
8. Well Number 957
9. OGRID Number 157984
10. Pool name or Wildcat Hobbs (G/SA)
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3656' GR

**OIL CONSERVATION DIVISION**  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

**SUNDRY NOTICES AND REPORTS ON WELLS**  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: Oil Well ☒ Gas Well ☐ Other ☐

2. Name of Operator  
Occidental Permian Ltd

3. Address of Operator  
P.O. Box 4294, Houston, TX 77210

4. Well Location  
Unit Letter P : 839 feet from the South line and 885 feet from the East line  
Section 18 Township 18S Range 38E NMPM County Lea

11. Elevation (Show whether DR, RKB, RT, GR, etc.)  
3656' GR

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐  
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐  
PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐  
DOWNHOLE COMMINGLE ☐  
CLOSED-LOOP SYSTEM ☐  
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☒ ALTERING CASING ☐  
COMMENCE DRILLING OPNS. ☐ P AND A ☐  
CASING/CEMENT JOB ☐  
OTHER: ☐

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

- MIRU x NDWH x NUBOP
- RU spooler x POOH ESP x 124 jts
- RIH 6 1/8" bit x clean well
- Move inj pkr to 4460'
- Scale squeeze x move pkr to 4390'
- Run acid job w/ 500 gals 15% acid
- Perf'd 4398' - 4456'
- Scale squeeze x move pkr to 4186
- RIH ESP x 124jts
- RD x NDBOP x NUWH x MO Location

Spud Date:

05/05/16

Rig Release Date:

05/19/16

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

*April Hood*

TITLE Regulatory Coordinator

DATE 08/09/2016

Type or print name April Hood

E-mail address: April\_Hood@Oxy.com

PHONE: 713-366-5771

For State Use Only

APPROVED BY:

*Mary Brown*

TITLE

*Dist Supervisor*

DATE

*8/15/2016*

Conditions of Approval (if any):