| Office | exico | Form C-103 |
|---|--|---|
| District 1 – (575) 393-6161 1625 N. French Dr., Hobbs, NM8249 S OCD | ural Resources | Revised July 18, 2013 WELL API NO. |
| District II - (575) 748-1283 OIL CONSERVATION | UDIVISION | 30-025-41649 |
| District III - (505) 334-6178 0 1 1 7 2016 1220 South St. Fra | ncis Dr. | 5. Indicate Type of Lease STATE FEE |
| District IV – (505) 476-3460 1220 S. St. Francis Dr., Santa F. ECEIVED | 7505 | 6. State Oil & Gas Lease No. |
| SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PL DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) F | UG BACK TO A | 7. Lease Name or Unit Agreement Name Nautilus 16 State Com |
| PROPOSALS.) 1. Type of Well: Oil Well Gas Well Other | | 8. Well Number 601H |
| 2. Name of Operator EOG Resources, Inc. | ~ | 9. OGRID Number 7377 |
| 3. Address of Operator P.O. Box 2267 Midland, TX 79702 | | 10. Pool name or Wildcat Red Hills; Upper Bone Spring Shale |
| 4. Well Location A 220 North | | D East |
| Unit Letter : 220 feet from the Mortin Section 16 Township 26S R | ange 34E | feet from the line |
| Section 16 Township 26S R 11. Elevation (Show whether DR | 0 | NMPM County Lea |
| 3312' GR | | |
| | | |
| 12. Check Appropriate Box to Indicate N | Nature of Notice, | Report or Other Data |
| NOTICE OF IN | SUB | SEQUENT REPORT OF: |
| | | |
| TEMPORARILY ABANDON P AND A P&A NR PM. K COMMENCE DRILLING OPNS. P AND A | | |
| PULL OR ALTER CASING P&A R | CASING/CEMEN | Т ЈОВ |
| | | |
| OTHER: | OTHER: P&A | |
| 13. Describe proposed or completed operations. (Clearly state all | | |
| of starting any proposed work). SEE RULE 19.15.7.14 NMA | C For Multiple Co. | |
| in the second strength of the second strengt | | mpletions: Attach wellbore diagram of |
| proposed completion or recompletion Capped w125 = | | mpletions: Attach wellbore diagram of |
| 09/28/16 MIRU to P&A. Tested casing to 1000 psi. 60 | s.~ | |
| 09/28/16 MIRU to P&A. Tested casing to 1000 psi. 60 09/29/16 RIH and tag fish at 12422'. Pump 25 sx Class H cel | s.~ | |
| 09/28/16 MIRU to P&A. Tested casing to 1000 psi. 60 | s.✓ ment plug at 11820'. | |
| 09/28/16 MIRU to P&A. Tested casing to 1000 psi. 60 09/29/16 RIH and tag fish at 12422'. Pump 25 sx Class H cel 09/30/16 RIH and tag plug at 10930'. 10/04/16 Cut 4-1/2" casing at 9850'. Attempted to pull casing Pumped 25 sx Class H cement plug at 9913'. | s.✓ ment plug at 11820'. I, unsuccessful. Not | ified NMOCD. |
| 09/28/16 MIRU to P&A. Tested casing to 1000 psi. 60 09/29/16 RIH and tag fish at 12422'. Pump 25 sx Class H cer 09/30/16 RIH and tag plug at 10930'. 10/04/16 Cut 4-1/2" casing at 9850'. Attempted to pull casing Pumped 25 sx Class H cement plug at 9913'. 10/05/16 RIH and tag plug at 9550'. Notified NMOCD. RIH to | ment plug at 11820'. , unsuccessful. Not o cut 4-1/2" casing a | ified NMOCD. t 7850'. Pull and lay down casing. |
| 09/28/16 MIRU to P&A. Tested casing to 1000 psi. 60 09/29/16 RIH and tag fish at 12422'. Pump 25 sx Class H cerolog/30/16 RIH and tag plug at 10930'. 10/04/16 Cut 4-1/2" casing at 9850'. Attempted to pull casing Pumped 25 sx Class H cement plug at 9913'. 10/05/16 RIH and tag plug at 9550'. Notified NMOCD. RIH to 10/07/16 Pump 40 sx Class H cement plug at 7916'. RIH and Notified NMOCD. Pump 60 sx Class C cement plug | ment plug at 11820'. , unsuccessful. Not o cut 4-1/2" casing a d tag plug at 7640'. | ified NMOCD. t 7850'. Pull and lay down casing. |
| 09/28/16 MIRU to P&A. Tested casing to 1000 psi. 60 09/29/16 RIH and tag fish at 12422'. Pump 25 sx Class H cereorem 109/30/16 RIH and tag plug at 10930'. 10/04/16 Cut 4-1/2" casing at 9850'. Attempted to pull casing Pumped 25 sx Class H cement plug at 9913'. 10/05/16 RIH and tag plug at 9550'. Notified NMOCD. RIH to 10/07/16 Pump 40 sx Class H cement plug at 7916'. RIH and Notified NMOCD. Pump 60 sx Class C cement plug at 5448'. | ment plug at 11820'. , unsuccessful. Not o cut 4-1/2" casing a d tag plug at 7640'. ↑ g at 5955'. | ified NMOCD. t 7850'. Pull and lay down casing. |
| 09/28/16 MIRU to P&A. Tested casing to 1000 psi. 60 09/29/16 RIH and tag fish at 12422'. Pump 25 sx Class H cereorem 109/30/16 RIH and tag plug at 10930'. 10/04/16 Cut 4-1/2" casing at 9850'. Attempted to pull casing Pumped 25 sx Class H cement plug at 9913'. 10/05/16 RIH and tag plug at 9550'. Notified NMOCD. RIH to 10/07/16 Pump 40 sx Class H cement plug at 7916'. RIH and Notified NMOCD. Pump 60 sx Class C cement plug Pumped 35 sx Class C cement plug at 5448'. 10/08/16 RIH and tag plug at 5040'. Pump 30 sx Class C cement Pump 55 sx Class C cement plug at 1186'. WOC 4 | ment plug at 11820'. , unsuccessful. Not o cut 4-1/2" casing a d tag plug at 7640'. g at 5955'. ment plug at 3113'. | ified NMOCD. t 7850'. Pull and lay down casing. Test casing to 500 psi. |
| 09/28/16 MIRU to P&A. Tested casing to 1000 psi. 60 09/29/16 RIH and tag fish at 12422'. Pump 25 sx Class H cerolog/30/16 RIH and tag plug at 10930'. 10/04/16 Cut 4-1/2" casing at 9850'. Attempted to pull casing Pumped 25 sx Class H cement plug at 9913'. 10/05/16 RIH and tag plug at 9550'. Notified NMOCD. RIH to 10/07/16 Pump 40 sx Class H cement plug at 7916'. RIH and Notified NMOCD. Pump 60 sx Class C cement plug Pumped 35 sx Class C cement plug at 5448'. 10/08/16 RIH and tag plug at 5040'. Pump 30 sx Class C cere Pump 55 sx Class C cement plug at 1186'. WOC 4 Pump Class C cement from 118' to surface. | ment plug at 11820'. n, unsuccessful. Not o cut 4-1/2" casing a d tag plug at 7640'. g at 5955'. ment plug at 3113'. Hrs. RIH and tag plu | ified NMOCD. t 7850'. Pull and lay down casing. Test casing to 500 psi. |
| 09/28/16 MIRU to P&A. Tested casing to 1000 psi. 60 09/29/16 RIH and tag fish at 12422'. Pump 25 sx Class H cereorem 109/30/16 RIH and tag plug at 10930'. 10/04/16 Cut 4-1/2" casing at 9850'. Attempted to pull casing Pumped 25 sx Class H cement plug at 9913'. 10/05/16 RIH and tag plug at 9550'. Notified NMOCD. RIH to 10/07/16 Pump 40 sx Class H cement plug at 7916'. RIH and Notified NMOCD. Pump 60 sx Class C cement plug Pumped 35 sx Class C cement plug at 5448'. 10/08/16 RIH and tag plug at 5040'. Pump 30 sx Class C cement Pump 55 sx Class C cement plug at 1186'. WOC 4 | ment plug at 11820'. , unsuccessful. Not o cut 4-1/2" casing a d tag plug at 7640'. g at 5955'. ment plug at 3113'. Hrs. RIH and tag plu on. Approved | ified NMOCD. t 7850'. Pull and lay down casing. Test casing to 500 psi. ug at 845'. for Plugging of wellbore only. Liability under |
| 09/28/16 MIRU to P&A. Tested casing to 1000 psi. 60 09/29/16 RIH and tag fish at 12422'. Pump 25 sx Class H cet 09/30/16 RIH and tag plug at 10930'. 10/04/16 Cut 4-1/2" casing at 9850'. Attempted to pull casing Pumped 25 sx Class H cement plug at 9913'. 10/05/16 RIH and tag plug at 9550'. Notified NMOCD. RIH to 10/07/16 Pump 40 sx Class H cement plug at 7916'. RIH and Notified NMOCD. Pump 60 sx Class C cement plug at 5448'. 10/08/16 RIH and tag plug at 5040'. Pump 30 sx Class C cere Pump 55 sx Class C cement plug at 1186'. WOC 4 Pump Class C cement from 118' to surface. 10/10/16 Cut off wellhead, weld on P&A marker, clean location | ment plug at 11820'. , unsuccessful. Not o cut 4-1/2" casing a d tag plug at 7640'. g at 5955'. ment plug at 3113'. Hrs. RIH and tag plu on. Approved bond is re | ified NMOCD. t 7850'. Pull and lay down casing. Test casing to 500 psi. ug at 845'. for Plugging of wellbore only. Liability under tained pending restoration and completion |
| 09/28/16 MIRU to P&A. Tested casing to 1000 psi. 60 09/29/16 RIH and tag fish at 12422'. Pump 25 sx Class H cerolog/30/16 RIH and tag plug at 10930'. 10/04/16 Cut 4-1/2" casing at 9850'. Attempted to pull casing Pumped 25 sx Class H cement plug at 9913'. 10/05/16 RIH and tag plug at 9550'. Notified NMOCD. RIH to 10/07/16 Pump 40 sx Class H cement plug at 7916'. RIH and Notified NMOCD. Pump 60 sx Class C cement plug Pumped 35 sx Class C cement plug at 5448'. 10/08/16 RIH and tag plug at 5040'. Pump 30 sx Class C cere Pump 55 sx Class C cement plug at 1186'. WOC 4 Pump Class C cement from 118' to surface. | ment plug at 11820'. , unsuccessful. Not o cut 4-1/2" casing a d tag plug at 7640'. g at 5955'. ment plug at 3113'. Hrs. RIH and tag plu on. Approved bond is re of the C-10 | ified NMOCD. t 7850'. Pull and lay down casing. Test casing to 500 psi. ug at 845'. for Plugging of wellbore only. Liability under tained pending restoration and completion 03, Specific for Subsequent Report of |
| 09/28/16 MIRU to P&A. Tested casing to 1000 psi. 60 09/29/16 RIH and tag fish at 12422'. Pump 25 sx Class H cet 09/30/16 RIH and tag plug at 10930'. 10/04/16 Cut 4-1/2" casing at 9850'. Attempted to pull casing Pumped 25 sx Class H cement plug at 9913'. 10/05/16 RIH and tag plug at 9550'. Notified NMOCD. RIH to 10/07/16 Pump 40 sx Class H cement plug at 7916'. RIH and Notified NMOCD. Pump 60 sx Class C cement plug at 5448'. 10/08/16 RIH and tag plug at 5040'. Pump 30 sx Class C cere Pump 55 sx Class C cement plug at 1186'. WOC 4 Pump Class C cement from 118' to surface. 10/10/16 Cut off wellhead, weld on P&A marker, clean location | ment plug at 11820'. , unsuccessful. Not o cut 4-1/2" casing a d tag plug at 7640'. g at 5955'. ment plug at 3113'. Hrs. RIH and tag plu on. Approved bond is re of the C-10 Well Plugg | ified NMOCD. t 7850'. Pull and lay down casing. Test casing to 500 psi. ug at 845'. for Plugging of wellbore only. Liability under tained pending restoration and completion |
| 09/28/16 MIRU to P&A. Tested casing to 1000 psi. 60 09/29/16 RIH and tag fish at 12422'. Pump 25 sx Class H cer 09/30/16 RIH and tag plug at 10930'. 10/04/16 Cut 4-1/2" casing at 9850'. Attempted to pull casing Pumped 25 sx Class H cement plug at 9913'. 10/05/16 RIH and tag plug at 9550'. Notified NMOCD. RIH to 10/07/16 Pump 40 sx Class H cement plug at 7916'. RIH and Notified NMOCD. Pump 60 sx Class C cement plug Pumped 35 sx Class C cement plug at 5448'. 10/08/16 RIH and tag plug at 5040'. Pump 30 sx Class C cer Pump 55 sx Class C cement plug at 1186'. WOC 4 Pump Class C cement from 118' to surface. 10/10/16 Cut off wellhead, weld on P&A marker, clean location Spud Date: Rig Release D | ment plug at 11820'. , unsuccessful. Not o cut 4-1/2" casing a d tag plug at 7640'. g at 5955'. ment plug at 3113'. Hrs. RIH and tag plu on. Approved bond is re of the C-10 Well Plugg web page | ified NMOCD. t 7850'. Pull and lay down casing. Test casing to 500 psi. ug at 845'. for Plugging of wellbore only. Liability under tained pending restoration and completion 03, Specific for Subsequent Report of ging, which may be found on the OCD under forms. |
| 09/28/16 MIRU to P&A. Tested casing to 1000 psi. 60 09/29/16 RIH and tag fish at 12422'. Pump 25 sx Class H cet 09/30/16 RIH and tag plug at 10930'. 10/04/16 Cut 4-1/2" casing at 9850'. Attempted to pull casing Pumped 25 sx Class H cement plug at 9913'. 10/05/16 RIH and tag plug at 9550'. Notified NMOCD. RIH to 10/07/16 Pump 40 sx Class H cement plug at 7916'. RIH and Notified NMOCD. Pump 60 sx Class C cement plug at 5448'. 10/08/16 RIH and tag plug at 5040'. Pump 30 sx Class C cere Pump 55 sx Class C cement plug at 1186'. WOC 4 Pump Class C cement from 118' to surface. 10/10/16 Cut off wellhead, weld on P&A marker, clean location | ment plug at 11820'. , unsuccessful. Not o cut 4-1/2" casing a d tag plug at 7640'. g at 5955'. ment plug at 3113'. Hrs. RIH and tag plu on. Approved bond is re of the C-10 Well Plugg web page | ified NMOCD. t 7850'. Pull and lay down casing. Test casing to 500 psi. ug at 845'. for Plugging of wellbore only. Liability under tained pending restoration and completion 03, Specific for Subsequent Report of ging, which may be found on the OCD under forms. |
| 09/28/16 MIRU to P&A. Tested casing to 1000 psi. 60 09/29/16 RIH and tag fish at 12422'. Pump 25 sx Class H cer 09/30/16 RIH and tag plug at 10930'. 10/04/16 Cut 4-1/2" casing at 9850'. Attempted to pull casing Pumped 25 sx Class H cerent plug at 9913'. 10/05/16 RIH and tag plug at 9550'. Notified NMOCD. RIH to 10/07/16 Pump 40 sx Class H cement plug at 7916'. RIH and Notified NMOCD. Pump 60 sx Class C cement plug Pumped 35 sx Class C cement plug at 5448'. 10/08/16 RIH and tag plug at 5040'. Pump 30 sx Class C cere Pump 55 sx Class C cement plug at 1186'. WOC 4 Pump Class C cement from 118' to surface. 10/10/16 Cut off wellhead, weld on P&A marker, clean location Spud Date: Rig Release D | ment plug at 11820'. , unsuccessful. Not o cut 4-1/2" casing a d tag plug at 7640'. g at 5955'. ment plug at 3113'. Hrs. RIH and tag plu on. Approved bond is re of the C-10 Well Plugg web page | ified NMOCD. t 7850'. Pull and lay down casing. Test casing to 500 psi. ug at 845'. for Plugging of wellbore only. Liability under tained pending restoration and completion 03, Specific for Subsequent Report of ging, which may be found on the OCD under forms. |
| 09/28/16 MIRU to P&A. Tested casing to 1000 psi. 60 09/29/16 RIH and tag fish at 12422'. Pump 25 sx Class H cere 09/30/16 RIH and tag plug at 10930'. 10/04/16 Cut 4-1/2" casing at 9850'. Attempted to pull casing Pumped 25 sx Class H cereent plug at 9913'. 10/05/16 RIH and tag plug at 9550'. Notified NMOCD. RIH to 10/07/16 Pumped 25 sx Class H cement plug at 7916'. RIH and Notified NMOCD. Pump 60 sx Class C cement plug Pumped 35 sx Class C cement plug at 5448'. 10/08/16 RIH and tag plug at 5040'. Pump 30 sx Class C cere Pump 55 sx Class C cement plug at 1186'. WOC 4 Pump Class C cement from 118' to surface. 10/10/16 Cut off wellhead, weld on P&A marker, clean location Spud Date: Rig Release D I hereby certify that the information above is true and complete to the b SIGNATURE Stan Wagner | ment plug at 11820'. , unsuccessful. Not o cut 4-1/2" casing a d tag plug at 7640'. g at 5955'. ment plug at 3113'. Hrs. RIH and tag plu on. Approved bond is re of the C-10 Well Plugg web page posst of my knowledg | ified NMOCD. t 7850'. Pull and lay down casing. Test casing to 500 psi. ug at 845'. for Plugging of wellbore only. Liability under tained pending restoration and completion 03, Specific for Subsequent Report of jing, which may be found on the OCD under forms. the and Denet. 10/12/2016 |
| 09/28/16 MIRU to P&A. Tested casing to 1000 psi. 60 09/29/16 RIH and tag fish at 12422'. Pump 25 sx Class H cere 09/30/16 RIH and tag plug at 10930'. 10/04/16 Cut 4-1/2" casing at 9850'. Attempted to pull casing Pumped 25 sx Class H cereent plug at 9913'. 10/05/16 RIH and tag plug at 9550'. Notified NMOCD. RIH to 10/07/16 Pumped 25 sx Class H cement plug at 7916'. RIH and Notified NMOCD. Pump 60 sx Class C cement plug Pumped 35 sx Class C cement plug at 5448'. 10/08/16 RIH and tag plug at 5040'. Pump 30 sx Class C cere Pump 55 sx Class C cement plug at 1186'. WOC 4 Pump Class C cement from 118' to surface. 10/10/16 Cut off wellhead, weld on P&A marker, clean location Spud Date: Rig Release D I hereby certify that the information above is true and complete to the b SIGNATURE Stan Wagner | ment plug at 11820'. , unsuccessful. Not o cut 4-1/2" casing a d tag plug at 7640'. g at 5955'. ment plug at 3113'. Hrs. RIH and tag plu on. Approved bond is re of the C-10 Well Plugg web page posst of my knowledg | ified NMOCD. t 7850'. Pull and lay down casing. Test casing to 500 psi. ug at 845'. for Plugging of wellbore only. Liability under tained pending restoration and completion 03, Specific for Subsequent Report of ging, which may be found on the OCD under forms. the and benet. list 10/12/2016 PHONE: 432-686-3689 |
| 09/28/16 MIRU to P&A. Tested casing to 1000 psi. 60 09/29/16 RIH and tag fish at 12422'. Pump 25 sx Class H cere 09/30/16 RIH and tag plug at 10930'. 10/04/16 Cut 4-1/2" casing at 9850'. Attempted to pull casing Pumped 25 sx Class H cement plug at 9913'. 10/05/16 RIH and tag plug at 9550'. Notified NMOCD. RIH to 10/05/16 RIH and tag plug at 9550'. Notified NMOCD. RIH to 10/07/16 Pump 40 sx Class H cement plug at 7916'. RIH and Notified NMOCD. Pump 60 sx Class C cement plug Pumped 35 sx Class C cement plug at 5448'. 10/08/16 RIH and tag plug at 5040'. Pump 30 sx Class C cere Pump 55 sx Class C cement plug at 1186'. WOC 4 Pump Class C cement from 118' to surface. 10/10/16 Cut off wellhead, weld on P&A marker, clean location Spud Date: Rig Release D I hereby certify that the information above is true and complete to the b SIGNATURE Stan Wagner TITLE Type or print name E-mail address | ment plug at 11820'. n, unsuccessful. Not o cut 4-1/2" casing a d tag plug at 7640'. g at 5955'. ment plug at 3113'. Hrs. RIH and tag plu on. Approved bond is re of the C-10 Well Plugg web page poest of my knowledg gulatory Specia | ified NMOCD. t 7850'. Pull and lay down casing. Test casing to 500 psi. ug at 845'. for Plugging of wellbore only. Liability under tained pending restoration and completion 03, Specific for Subsequent Report of jing, which may be found on the OCD under forms. the and benet. list 10/12/2016 |