	To Appropriate District BBS OC Brate of New Mexico Energy, Minerals and Natural Resources						Form C-103 Revised July 18, 2013			
District I – (575) 393-6161 1625 N. French Dr., Hobbs, NM 88240 C Solution of the control of th						WELL A	WELL API NO.			
811 S. First St., Artesia, NM 88210							30-025-07560 5. Indicate Type of Lease			
District III - (505) 334-6178 1220 South St. Francis Dr.						S	STATE FEE			
District IV - (505) 476-3460 Santa Fe, NM 87505 1220 S. St. Francis Dr., Santa Fe, NM 87505							6. State Oil & Gas Lease No. 19552			
SUNDRY NOTICES AND REPORTS ON WELLS							7. Lease Name or Unit Agreement Name			
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)							North Hobbs Unit (G/SA)			
1. Type of Well: Oil Well Gas Well Other Injector							8. Well Number 221			
Name of Operator Occidental Permian Ltd							9. OGRID Number 157984			
3. Address of Operator							10. Pool name or Wildcat			
	P.O. Box 4294, Houston, TX 77210							Hobbs (G/SA)		
4. Well Loca	tion Letter F	. 2310	feet from the	North	line and	1320	feet from the	West	line	
Sect			Township	18S Ra					_	
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3637' GR										
	12. Che	eck Approp	riate Box to In	dicate N	ature of Not	tice, Report	or Other Data			
NOTICE OF INTENTION TO: SUE							ENT REPOR	T OF:		
PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐ REMEDIAL WOR						WORK	X ALTE	RING CASIN	1G □	
TEMPORARILY ABANDON								DA		
	COMMINGLE	☐ MULT	IPLE COMPL	П	CASING/CE	MEN I JOB				
	OP SYSTEM									
OTHER:					OTHER:					
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date										
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.										
06/20/16 – 07/06/16										
MIRU x NDWH x NU					-	•				
@ 592' – 623'. RIH !				_					-	
w/ 25 sx cmt. RIH 4						_				
POOH pkr x RIH 22 RIH RBP @ 3940'. R							nen reii out to 67	9. POUR KE	IP @ 1007 X	
	an ore up to sure	acc. No x No.		Well left 3	aspenaca					
10/26/16 - 11/08/										
MIRU x NDWH x NU										
RDWL. RIH 5" test p			•		_			-		
job w/ 3570 gals 15 ***Well returned to		nj pkr @ 3945	9 W/ 122 Jts tubii	ng x on/on	tool. Kan IVII	and passed -	Chart attached.	KU X NUBUP	X NOWH.	
Spud Date:	06/20/16		Rig	Release Da	ate: 11/08	3/16				
I hereby certif	fy that the inform	nation above i	s true and comple	ete to the b	est of my kno	wledge and be	lief.		,	
SIGNATURE	Ant	il X	m		atory Specialis		DATE	11/15/201	6	
	P									
Type or print name April Hood E-mail address: April_Hood@Oxy.com PHONE: 713-366-5771										
APPROVED	BY: Max	eysb	LOWN ATT	LE Di	st Su	Rewy	O DATE	12/19	2016	
Conditions of	Approval (if any	v)·/\				1		. //		

RBDMS - CHART

