Submit One Copy To Appropriate District	State of New Me	vico	Form C-103
Office District I	Energy, Minerals and Natu		Revised November 3, 2011
1625 N. French Dr., Hobbs, NM 88240	Lifergy, winerars and ruta	and Resources	WELL API NO.
District II 811 S. First St., Artesia, NM 88210	OIL CONSERVATION	DIVISION	30-025-10977
District III 1220 South St. Francis Dr.		ncis Dr.	5. Indicate Type of Lease
1000 Rio Brazos Rd., Aztec, NM 87410 District IV Santa Fe, NM 87505		6. State Oil & Gas Lease No.	
1220 S. St. Francis Dr., Santa Fe, NM 87505		B9974	
SUNDRY NOTICES AND REPORTS ON WELLS		7. Lease Name or Unit Agreement Name	
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH		UG BACK TO A	MYERS LANGLIE MATTIX UNIT
PROPOSALS.)		8. Well Number	
1. Type of Well: Oil Well Gas Well Other			
OXY USA WTP LP JAN 3 0 2017		9. OGRID Number	
3. Address of Operator			10. Pool name or Wildcat
PO BOX 4294; HOUSTON, TX 77	210 REC	FIVED	LANGLIE MATTIX 7RVR QN-GB
4. Well Location C			
Unit Letter <u>3</u> : <u>660</u> feet from the <u>NORTH</u> line and <u>1978</u> feet from the <u>WEST</u> line			
Section 2 Township 24S Range 37E NMPM County LEA			
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3230'			
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data			
	TENTION TO: PLUG AND ABANDON	SUB REMEDIAL WOR	SEQUENT REPORT OF:
TEMPORARILY ABANDON CHANGE PLOG AND ABANDON CHANGE OR COMMENCE OR			
		CASING/CEMEN	
			eady for OCD inspection after P&A
OTHER: I Location is ready for OCD inspection after P&A A A A A A A A A A A A A A A A A A A			
Rat hole and cellar have been filled and leveled. Cathodic protection holes have been properly abandoned.			
A steel marker at least 4" in diameter and at least 4' above ground level has been set in concrete. It shows the			
OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, QUARTER/OUARTER LOCATION OR			
UNIT LETTER, SECTION, TOWNSHIP, AND RANGE. All INFORMATION HAS BEEN WELDED OR			
PERMANENTLY STAMPED ON THE MARKER'S SURFACE.			
The location has been leveled as nearly as possible to original ground contour and has been cleared of all junk, trash, flow lines and			
other production equipment.			
 Anchors, dead men, tie downs and risers have been cut off at least two feet below ground level. If this is a one-well lease or last remaining well on lease, the battery and pit location(s) have been remediated in compliance with 			
OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, production equipment and junk have been removed			
from lease and well location.			
All metal bolts and other materials have been removed. Portable bases have been removed. (Poured onsite concrete bases do not have			
to be removed.) All other environmental concerr	ns have been addressed as per OCD) rules.	
Pipelines and flow lines have been abandoned in accordance with 19.15.35.10 NMAC. All fluids have been removed from non-			
retrieved flow lines and pipelines. If this is a one-well lease or last remaining well on lease: all electrical service poles and lines have been removed from lease and well			
location, except for utility's distribution infrastructure.			
. /			
When all work has been goinpleted, return this form to the appropriate District office to schedule an inspection.			
A/1	_		100 17
SIGNATURE	TITLE_F	ENVIRONMENTA	LADVISOR_DATE $1-26-17$
TYPE OF PRINT NAME ASEY			
TYPE OR PRINT NAME E-MAIL: E-MAIL: PHONE: _575-513-8289 For State Use Only			
For State Use Only	L SUMMERS E-MAIL: _case	y_summers @ox y.c	
For State Use Only	\bigcap		
	L SUMMERS_ E-MAIL: <u>case</u> Fitala		DATE 01/30/2017