Submit 1 Copy To Appropriate District Office District II - (575) \$93 Gro B S OCD 1625 N. French Dr., Hobbs, NM 88240 District II - (575) 748-1283 811 S. First St., Artesia, NM 885002017 District III - (505) 334 Gri 78 1000 Rio Brazos Rd., Aztec, NM 87410 District IV - (505) 476 3460 Exercise Dr. Santa Fe, NM 87505       OIL CONSERVATION DIVISION 1220 South St. Francis Dr. Santa Fe, NM 87505         SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)         1. Type of Well: Oil Well □ Gas Well ☑ Other         2. Name of Operator Apache Corporation         3. Address of Operator 303 Veterans Airpark Lane, Suite 1000         4. Well Location Unit Letter _ F : 1980         feet from the North Unit Letter _ F : 1980	
Section 32 Township 21S Range 35E	NMPM County Lea
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3611' GR	
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data         NOTICE OF INTENTION TO:         PERFORM REMEDIAL WORK       PLUG AND ABANDON         TEMPORARILY ABANDON       CHANGE PLANS         PULL OR ALTER CASING       MULTIPLE COMPL         DOWNHOLE COMMINGLE       CASING/CEMENT JOB         CLOSED-LOOP SYSTEM       OTHER:         0THER:       OTHER:         13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.         Apache would like to perform the following work: Producing Interval: 12,636-41'; 12,794-808'. Objective: Isolate lower interval with a CIBP and TA wellbore.         Procedure:       1         1. MIRU WO Rig and wireline unit       22,580'         2. RIH with gauge ring and go down to 12,580'         3. Pick up a CIBP and set it inside 2.3/8' tbg @ 12,570'         4. RIH with chemical cutter and cut tbg @ 12,560'         5. Scant tbg and lay down junk pipe         6. RIH and set CIBP @ 12,550' will 35' cmt         7. Circulate fluid and pressure test casing to 500 psi         8. Record pressure test on a chart and submit to OCD for approval	
Spud Date: 04/03/1982 Rig Release Date:	
I hereby certify that the information above is true and complete to the best of my knowledge and belief.	
SIGNATURE     Stabel Husson     TITLE Regulatory Analyst       Type or print name     Isabel Hudson     E-mail address:     Isabel.hudson@ap       For State Use Only     Image: Conly     Image: Conly     Image: Conly	DATE 01/23/2017 PHONE: (432) 818-1142
APPROVED BY: Maley A DIOLON TITLE NO/11 Conditions of Approval (if any):	DATE 2/1/2017



January 23, 2017

San Simon 32 B State Gas Com # 1 API # 30-025-27746 Lea County, NM Production Liner: 5" 15# Set @ 10,736' – 13,247' Producing Interval: **12,636-41'; 12,794-808'** 

Objective: Isolate lower interval with a CIBP and TA wellbore

## Procedure:

- 1. MIRU WO Rig and wireline unit
- 2. RIH with gauge ring and go down to 12,580'
- 3. Pick up a CIBP and set it inside 2-3/8" tbg @ 12,570'
- 4. RIH with chemical cutter and cut tbg @ 12,560'
- 5. Scant tbg and lay down junk pipe
- 6. RIH and set CIBP @ 12,550' w/ 35' cmt
- 7. Circulate fluid and pressure test casing to 500 psi
- 8. Record pressure test on a chart and submit to OCD for approval

