Submit 3 Copies To Appropriate District Office State of New Mexico	Form C-103
District I Energy, Minerals and Natural Resources	May 27, 2004
1625 N. French Dr., Hobbs, NM 88240	WELL API NO. 30-025-30856
District II of 1301 W. Grand Ave., Artesia, NM 88210 OIL CONSERVATION DIVISION	
District III 1220 South St. Francis Dr.	5. Indicate Type of Lease
1000 Rio Brazos Rd., Aztec, NM 87410 District IV Santa Fe, NM 87505	STATE FEE
1220 S. St. Francis Dr., Santa Fe, NM	6. State Oil & Gas Lease No.
87505	
SUNDRY NOTICES AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A	J.L. Reed
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	8. Well Number 6
1. Type of Well: Oil Well Gas Well Other	
2. Name of Operator Paladin Energy Corp.	9. OGRID Number 164070
(
3. Address of Operator 10290 Monroe Dr., Suite 301	10. Pool name or Wildcat
Dallas, Texas 75229	King Wolfcamp
4. Well Location	
Unit Letter <u>G</u> : 1800 feet from the <u>North</u> line and <u>1650</u>	feet from the <u>East</u> line /
Section 35 Township 13S Range 37E	NMPM Lea County
11. Elevation (Show whether DR, RKB, RT, GR, etc.,	
3849' GR	
12. Check Appropriate Box to Indicate Nature of Notice,	Report or Other Data
NOTICE OF INTENTION TO	050115115 05005 05
	SEQUENT REPORT OF:
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WOR	
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRI	
PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMEN	T JOB \square
OTHER: T&A VEAR OTHER:	_
	d give pertinent dates, including estimated date
13. Describe proposed or completed operations. (Clearly state all pertinent details, and	
 Describe proposed or completed operations. (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 1103. For Multiple Completions: At 	
13. Describe proposed or completed operations. (Clearly state all pertinent details, and	
 Describe proposed or completed operations. (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 1103. For Multiple Completions: At 	
 Describe proposed or completed operations. (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 1103. For Multiple Completions: At or recompletion. 	
 Describe proposed or completed operations. (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 1103. For Multiple Completions: At 	
13. Describe proposed or completed operations. (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 1103. For Multiple Completions: At or recompletion. Request permission to extend T&A status.	tach wellbore diagram of proposed completion
 13. Describe proposed or completed operations. (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 1103. For Multiple Completions: At or recompletion. Request permission to extend T&A status. R/U pumping unit. CIBP set at 9,200' above Top perforation at 9,328'-9 	2,417'. Fill Casing with fluid, test 5-
13. Describe proposed or completed operations. (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 1103. For Multiple Completions: At or recompletion. Request permission to extend T&A status.	2,417'. Fill Casing with fluid, test 5-t.
 13. Describe proposed or completed operations. (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 1103. For Multiple Completions: At or recompletion. Request permission to extend T&A status. R/U pumping unit. CIBP set at 9,200' above Top perforation at 9,328'-91/2" casing to 500# and hold for 30 minutes. Record chart. Submit chart. 	2,417'. Fill Casing with fluid, test 5-t.
 13. Describe proposed or completed operations. (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 1103. For Multiple Completions: At or recompletion. Request permission to extend T&A status. R/U pumping unit. CIBP set at 9,200' above Top perforation at 9,328'-91/2" casing to 500# and hold for 30 minutes. Record chart. Submit chart. 	2,417'. Fill Casing with fluid, test 5-t.
13. Describe proposed or completed operations. (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 1103. For Multiple Completions: At or recompletion. Request permission to extend T&A status. R/U pumping unit. CIBP set at 9,200' above Top perforation at 9,328'-91/2" casing to 500# and hold for 30 minutes. Record chart. Submit chart.	2,417'. Fill Casing with fluid, test 5-t.
 13. Describe proposed or completed operations. (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 1103. For Multiple Completions: At or recompletion. Request permission to extend T&A status. R/U pumping unit. CIBP set at 9,200' above Top perforation at 9,328'-91/2" casing to 500# and hold for 30 minutes. Record chart. Submit chart. 	2,417'. Fill Casing with fluid, test 5-t.
13. Describe proposed or completed operations. (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 1103. For Multiple Completions: At or recompletion. Request permission to extend T&A status. R/U pumping unit. CIBP set at 9,200' above Top perforation at 9,328'-91/2" casing to 500# and hold for 30 minutes. Record chart. Submit chart Conditation of the permission of the perm	2,417'. Fill Casing with fluid, test 5-t. ion of Approval: notify Hobbs office 24 hours
13. Describe proposed or completed operations. (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 1103. For Multiple Completions: At or recompletion. Request permission to extend T&A status. R/U pumping unit. CIBP set at 9,200' above Top perforation at 9,328'-91/2" casing to 500# and hold for 30 minutes. Record chart. Submit chart Conditation of the permission of the perm	2,417'. Fill Casing with fluid, test 5-t.
13. Describe proposed or completed operations. (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 1103. For Multiple Completions: At or recompletion. Request permission to extend T&A status. R/U pumping unit. CIBP set at 9,200' above Top perforation at 9,328'-91/2" casing to 500# and hold for 30 minutes. Record chart. Submit chart Conditation of the permission of the perm	2,417'. Fill Casing with fluid, test 5-t. ion of Approval: notify Hobbs office 24 hours unning MIT Test & Chart
13. Describe proposed or completed operations. (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 1103. For Multiple Completions: At or recompletion. Request permission to extend T&A status. R/U pumping unit. CIBP set at 9,200' above Top perforation at 9,328'-91/2" casing to 500# and hold for 30 minutes. Record chart. Submit chart Conditates are prior of recompleted operations. Rig Release Date:	2,417'. Fill Casing with fluid, test 5-t. ion of Approval: notify Hobbs office 24 hours unning MIT Test & Chart e and belief.
13. Describe proposed or completed operations. (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 1103. For Multiple Completions: At or recompletion. Request permission to extend T&A status. R/U pumping unit. CIBP set at 9,200' above Top perforation at 9,328'-91/2" casing to 500# and hold for 30 minutes. Record chart. Submit chart Conditates are prior of recompleted operations. Rig Release Date:	2,417'. Fill Casing with fluid, test 5-t. ion of Approval: notify Hobbs office 24 hours unning MIT Test & Chart
13. Describe proposed or completed operations. (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 1103. For Multiple Completions: At or recompletion. Request permission to extend T&A status. R/U pumping unit. CIBP set at 9,200' above Top perforation at 9,328'-91/2" casing to 500# and hold for 30 minutes. Record chart. Submit chart Condit. Spud Date: Rig Release Date: Rig Release Date: Title VP Exploration	2,417'. Fill Casing with fluid, test 5-t. ion of Approval: notify Hobbs office 24 hours unning MIT Test & Chart e and belief. & Production DATE 3/17/2017
13. Describe proposed or completed operations. (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 1103. For Multiple Completions: At or recompletion. Request permission to extend T&A status. R/U pumping unit. CIBP set at 9,200' above Top perforation at 9,328'-91/2" casing to 500# and hold for 30 minutes. Record chart. Submit chart Condit. Spud Date: Rig Release Date: OCD Prior of r Thereby certify that the information above is true and complete to the best of my knowledge SIGNATURE Plant of TITLE VP Exploration Type or print name: David Plaisance E-mail address: dplaisance@paladinene	2,417'. Fill Casing with fluid, test 5-t. ion of Approval: notify Hobbs office 24 hours unning MIT Test & Chart e and belief.
13. Describe proposed or completed operations. (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 1103. For Multiple Completions: At or recompletion. Request permission to extend T&A status. R/U pumping unit. CIBP set at 9,200' above Top perforation at 9,328'-5' 1/2" casing to 500# and hold for 30 minutes. Record chart. Submit chart. Spud Date: Rig Release Date: Condit Spud Date: Rig Release Date: Title VP Exploration Type or print name: David Plaisance E-mail address: dplaisance@paladinence.	2,417'. Fill Casing with fluid, test 5-t. ion of Approval: notify Hobbs office 24 hours unning MIT Test & Chart e and belief. & Production DATE 3/17/2017
13. Describe proposed or completed operations. (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 1103. For Multiple Completions: At or recompletion. Request permission to extend T&A status. R/U pumping unit. CIBP set at 9,200' above Top perforation at 9,328'-5' 1/2" casing to 500# and hold for 30 minutes. Record chart. Submit chart. Spud Date: Rig Release Date: Condit Spud Date: Rig Release Date: Title VP Exploration Type or print name: David Plaisance E-mail address: dplaisance@paladinence.	2,417'. Fill Casing with fluid, test 5-t. ion of Approval: notify Hobbs office 24 hours unning MIT Test & Chart e and belief. & Production DATE 3/17/2017
13. Describe proposed or completed operations. (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 1103. For Multiple Completions: At or recompletion. Request permission to extend T&A status. R/U pumping unit. CIBP set at 9,200' above Top perforation at 9,328'-91/2" casing to 500# and hold for 30 minutes. Record chart. Submit chart Condit. Spud Date: Rig Release Date: OCD Prior of r Thereby certify that the information above is true and complete to the best of my knowledge SIGNATURE Plant of TITLE VP Exploration Type or print name: David Plaisance E-mail address: dplaisance@paladinene	2,417'. Fill Casing with fluid, test 5-t. ion of Approval: notify Hobbs office 24 hours unning MIT Test & Chart e and belief. & Production DATE 3/17/2017

