Submit 1 Copy To A Office		State of Energy, Mineral	f New Mexico		Form C-103 October 13, 2009			
<u>District I</u> – (575) 393 1625 N. French Dr.,			•		WELL API		13, 2007	
<u>District II</u> – (575) 74		OIL CONSER	VATION DI	TOTAL	30-025-3529			
811 S. First St., Arte		OIL CONSER	VATION DI	VISION	5. Indicate 7	Type of Lease		
<u>District III</u> – (505) 3 1000 Rio Brazos Rd		1220 Sour	th St. Francis		STAT	E 🛛 FE	E 🗆 🖊	
District IV – (505) 4		Santa I	Fe, NM 87505	64.	6. State Oil	& Gas Lease No	).	
1220 S. St. Francis I 87505			VATION DIV th St. Francis Fe, NM 87505	<017	302600			
	SUNDRY NOTICES	AND REPORTS (	ON WELLS	SILL	7. Lease Na	me or Unit Agre	ement Name	
	S FORM FOR PROPOSALS RVOIR. USE "APPLICATIO	TO DRILL OR TO DE	EPEN OR PLUG BA		New Mexico		/	
PROPOSALS.)  1. Type of Well		Well Dother			8. Well Nun	nber 26	,	
2. Name of Ope					9. OGRID N	Number		
CrownQuest O			/		213190		/	
3. Address of O						ne or Wildcat		
	, Midland, TX 79710				Saunders; P	ermo Upper Pe	enn	
4. Well Location								
	tter N : 560	feet from the				et from the		
Section		Township 14S			MPM	County L	ea	
		Elevation (Show v	whether DR, RKB	3, RT, GR, etc.)				
<b>经验的</b>	Gr	R 4208				<b>发生的</b> 医秦星素系统		
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data								
	12. Chock rippi	opridic Box to 1	nareate reature		-			
Approved for Plugging of wellbore only. Liability					SEQUENT	REPORT O	F:	
			INIT TO DA	<	<	☐ ALTERING	G CASING	
under bond is retained pending restoration and completion of the C-103, Specific for Subsequent							X	
	ging, which may be		P&A NR	m.x	JOB			
	the OCD web page under forms. P&A R							
Restoration Due By	02-21-2018						_	
13 Describe	proposed or completed	operations (Clear	ly state all pertin	ent details and	give pertinen	t dates includin	g estimated date	
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of								
proposed completion or recompletion.								
02/16/17 MIRU Plugging equipment. 02/17/17 Dug out cellar, ND wellhead, NU BOP. RIH w/ guage ring & tag'd fish								
	. RIH & set 5 1/2 CIB							
	ass H cmt @ 8985-8732							
	Tag'd plug @ 3900'.							
POH w/ 65 jts. 02/21/17 POH w/ rest of 5 1/2 csg, 85 jts total. Pump'd 300 bbls H20 @ 3050. Spot'd 40 sx class C cmt @ 3050-2865'. WOC. Tag'd plug @ 2895'. Pressure tested 8 5/8 csg, held 500 psi. Spot'd 40 sx class C cmt @ 1650-1496'.								
Spot'd 50 sx class C cmt @ 460-267. WOC 02/22/17 Tag'd plug @ 290'. Spot'd 15 sx class C cmt @ 60' to surface.								
Rigged	down and moved off. 0	2/28/17 Moved in	backhoe and we	lder. Dug out	cellar. Cut of	ff well head. We		
"Above Ground Dry Hole Marker". Backfilled cellar. Cut off deadmen. Cleaned location, moved off.								
_								
0 15	00/1/2/0015	ъ.	B.1 B.	02/	22/2017			
Spud Date:	02/16/2017	Rı	g Release Date:	02/2	22/2017			
I hereby certify th	at the information above	e is true and comple	ete to the best of	my knowledge	and belief			
		()		my knowieage	una bener.			
	/// .	$\stackrel{\sim}{\sim}$						
SIGNATURE		TII TII	LE Lease	Manager		_DATE3/15	/2017	
Temporariot	Cault	/			us oot com	DIJONE 422	FF0 0000	
Type or print nam For State Use Qr		E-n	nail address: sle	yva@crowng	uest.com	PHONE: 432	-339-9066	
ror state Use Of	^							
APPROVED BY:	Wallti	talm TIT	LEP,E.S.			DATE 03-	27-2017	
Conditions of App		111				DILLI -	1 1	