Form 3160-5 (June 2015) DE BU	FORM APPROVED OMB NO. 1004-0137 Expires: January 31, 2018 5. Lease Serial No.									
SUNDRY Do not use thi	5. Lease Serial No. NMLC054453									
abandoned we	II. Use form 3160-3 (API	D) for such p	CD H	hha						
SUBMIT IN	TRIPLICATE - Other inst	tructions on	page 2	0005	7. If Unit or CA/Agreen SW319	nent, Name and/or No.				
1. Type of Well □ Oil Well ⊠ Gas Well □ Otl	lar				8. Well Name and No. DUTHIE ANDREW	S 04				
2. Name of Operator APACHE CORPORATION	Contact:	REESA FISH			<ol> <li>API Well No. 30-025-25070-00</li> </ol>					
3a. Address	E-Mail: Reesa.Fish		(include area code)	e)	10. Field and Pool or E					
303 VETERANS AIRPARK LA MIDLAND, TX 79705	ANE SUITE 3000	Ph: 432-81	8-1062		JALMAT-TAN-YATES-7RVRS LANGLIE MATTIX-7RVRS-QN-GB					
4. Location of Well (Footage, Sec., 7	C., R., M., or Survey Description,	)	HOBBS (	CD	tate					
Sec 19 T23S R37E NWNE 66		LEA COUNTY, NM								
			MAR 31 2	J17						
12. CHECK THE A	PPROPRIATE BOX(ES)	TO INDICA	TE NATURE O	F NOTICE,	REPORT, OR OTH	ER DATA				
TYPE OF SUBMISSION			FACTION							
Notice of Intent	Acidize	Dee	pen	Product	tion (Start/Resume)	□ Water Shut-Off				
_	Alter Casing	🗖 Hyd	Iraulic Fracturing	C Reclam	ation	U Well Integrity				
□ Subsequent Report	Casing Repair	_	v Construction	Recom		□ Other				
Final Abandonment Notice	<ul> <li>Change Plans</li> <li>Convert to Injection</li> </ul>	Plug Plug Plug Plug Plug Plug Plug Plug	g and Abandon	Water 1	rarily Abandon					
Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandomment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection. Apache Corporation requests approval to TA this wellbore for a period of 1 year. We are in the process of evaluating the Seven Rivers/Queen and Tansill/Yates formations for bypassed pay as well as the potential utility of this wellbore for future exploration. Procedure: Day 1: MIRU SU. POOH w/rods (if applicable) laying down. POOH w/tubing. RUWL, Rith and set CBP @ 3,330? via wireline. RIH and dump bail 35? of cement on top of CIBP. FOONS OF APPROVAL Day 2: RIH and tag TOC w/wireline. Record depth of TOC. RIH and set CIBP @ 2,840? via wireline. RIH w/tubing and test casing. Circulate inhibited fluid in wellbore.										
14. I hereby certify that the foregoing i	Electronic Submission # For APAC	364952 verifie HE CORPORA	d by the BLM We TION, sent to the	II Informatio	n System					
Name (Printed/Typed) REESA F	nmitted to AFMSS for proc ISHER	essing by PRI		No. of Concession, Name of Street, or other	ATORY ANALYST					
Signature (Electronic	017	PRUVED								
	THIS SPACE FO	OR FEDER			SE 2 2017					
				L						
Approved ByMUSTAFA_HAQUE Conditions of approval, if any, are attached certify that the applicant holds legal or eq which would entitle the applicant to condi-	d. Approval of this notice does uitable title to those rights in the	TitlePETROLEUMENGINEER MANAGEMENT CARLSBAD FIELD OFFICE								
Title 18 U.S.C. Section 1001 and Title 43 States any false, fictitious or fraudulent	U.S.C. Section 1212, make it a	crime for any posto any matter w	erson knowingly and	willfully to m	ake to any department or a	agency of the United				
(Instructions on page 2) ** BLM REV	ISED ** BLM REVISEI	D ** BLM RI	EVISED ** BLN	REVISE	D ** BLM REVISED	** /				

Additional data for EC transaction #364952 that would not fit on the form

## 32. Additional remarks, continued

4


POOH w/tubing. RU wireline. Dump bail 35? of cement on top of CIBP. WOC.

Day 3: RIH and tag TOC w/wireline. RD wireline. Perform MIT NOTE: Please contact BLM 48 hours prior to performing MIT test.

- CURRENT-

à

				~	CUR	REI	UT-							
Apache	Corporation									-			n / Midlan	
Work Objective					-				District		Office Type	NW / E	unice Sou	th
		TBD End Date		e TBD			Description	0.D.	Grade		Veight	Deat	h Cmt S	X TOC
Start Date	TBD Andrews, Duthie WN	KB			12'		Description	0.0.	Graue		veigni	Depi	300	Circulated to
Well Name	Andrews, Duthle WN	Well No	damage and the second sec		#4		Surface Cs	g 8-5/8	K-55		24#	418	Class	
Field	Langlie-Mattix (BP)	TD @	CP-Streamstering the stre		700'				_					
County	Lea	PBTD C	and the second se		695'		Inter Csg	1						
State	New Mexico	ETD @	Contraction of the particular in		N/A		Deed Con	4.4/0			0.54	3700	350	1950'
AFE #	TBD	API #	30-02		5-25070		Prod Csg	4-1/2			9.5#	3700	350	Temp Svy
Gross AFE	TBD	Spud Da	te	8/3	/1975		Casing Line	ar						
Apache WI	100.000000%	Comp. Da	ate	7/24	4/1983									1
			Det		Zone			Actual	arforation	10		-	JSPF	Total Perfs
				Date 8/18/1975		2	Actual Perforations 2895', 2900', 2905', 2910', 2915', 2920', 2925', 2930', 2940', 2945', 2950', 3020', 3025', 3030', 3035'				-		Total Feris	
												1		
							3463', 3467', 3492', 3495', 3508', 3511', 3514', 3517', 3520', 3523',						1	~13
			11111010		1		3595', 3603', 3606' 3386', 3390', 3394', 3398', 3436', 3440', 3446', 3452', 3456', 3483',					_		- 10
		3	12/30/11		7 River	5 2	1386', 3390', 3394', 3 1487', 3561', 3566', 3						1	
			1/6/19	981	Queen		634', 3638', 3642', 3							
			7/24/1	983	Jaimal G		2895', 2903', 10', 17', 73', 75', 3200', 03', 33		44', 49', 82',	84', 302	1', 27', 34',	43'.	1	~20
HOLE SIZE						ľ	3,75,3200,03,3	206						
12-1/4*														
			Dat		Zone	-	Stim	ulation / F	roducing	Interv	8		P	mount
			8/18/1	975	Yates	14	Acid 2895'-3035' w/ 1	500 gals. Fr	ac w/ 20,000	gals wtr	+ 40,000# 8	d		
			11/17/	975	Langlie Mattix		Acid 3463'-3606' w/ 1	500 gals. Fr	ac w/ 15.000	gals wtr	+ 37.000# :	d		
			12/30/1		7 River	IS A	Acid 3386'-3684' w/ 3							
			1/6/11		Queen		CO2 + 57.000# sd Acidized perts 2895'-	3206' w/ 200	0 oals 15% l	IEFE ac	id. Frac'd w	_		
			7/24/1	983	Jalmat G		20.000 gals x linked							
						-								
Cemented 1260' to surface w/900 sx (circ.)					I	<u> </u>	à.							1
			Jts	F	eet I	Pulle	ed Description	Tub	ing	Jts	Feet	T	Ran	Description
Peri 4 1/2" holes @ 1260"									#VALUE!					
Cemented below 1260'						-		Pup JT	#VALUE!	1	4.10			
w/700 sx								SN	#VALUEI #VALUEI	1	1.10			
				-				TBG	#VALUEI	118	3630.1	5		
100								TAC	#VALUEI					
						-		TBG	#VALUEI	1	31.16			
								BULL N/A	#VALUE!	1	0.45	$\rightarrow$		
								KB	12'	123	3676.9	COMPANY OF TAXABLE PARTY.		
24			Jts	F	eet I	Pulle	ed Description	Ro		Jts	Feet		Ran	Description
1		Yates				_		Gas A						
- Entro		Jalmat Gas						Pu	Name of Column 2 is not the Owner, or other					
		Jamai Gas		+				K-B						
													×	
								K-B						
								RO						
								RO						
								RO						
				-				POL				-		
TBG Set @ 3677												-		
IDU 361 @ 36/7		anglie Mattix								0	0.00	1		
81933 81937	E SHIEL	(Queen)						Well Hist	ory / Failu	Ire				
1600 E		Rivers Queen				-								
100		and a good												
			Apache	Repres	sentativo	6			Cor	ntract I	Rig/Numb	per		
MULE SIZE /														
7/8*	V		Apache	Engine	er		Jacob Bowe	r	Оре	erator				



## BUREAU OF LAND MANAGEMENT Carlsbad Field Office 620 East Greene Street Carlsbad, New Mexico 88220 575-234-5972

## Temporary Abandonment of Wells on Federal Lands Conditions of Approval

A temporarily abandoned well is defined as a completion that is not capable of production in paying quantities but which may have value as a service well. Pursuant to 43 CFR 3162.3-4 (c), no well may be temporarily abandoned for more than 30 days without the prior approval of the authorized officer.

Temporary Abandonment (TA) status approval requires a successful mechanical or casing integrity test as follows:

- 1. A Notice of Intent (NOI) Sundry Notice (Form 3160-5) requesting approval to run a mechanical integrity test (MIT) or casing integrity test (CIT).
- 2. A description of the temporary abandonment procedure.

a. A bridge plug or packer must be installed as close to 50 feet above any open perforations or open hole as possible. If a cement plug is used, the top of the cement must be verified by tagging. CIBP must be capped with minimum 25 sacks cement, **placed with tubing** or 35 feet of cement if placed with bailer.

b. The wellbore must be filled with corrosion inhibited fluid and pressure tested to 500 psi. The casing shall be capable of holding this pressure for at least 30 minutes. Any leak-off will be evaluated.

c. All downhole production/injection equipment (tubing, rods, etc.) shall be removed from the casing if they are not isolated by a packer.

d. A bradenhead test must be conducted. If the test indicates a problem exists, a remedial plan and time frame for remediation shall be submitted within ninety (90) days of the test.

e. Contact the appropriate BLM office at least 24 hours prior to the scheduled Casing Integrity Test. For wells in Eddy County, 575-361-2822; Lea County 575-393-3612.

3. Provides justification why the well should be temporarily abandoned rather than permanently plugged and abandoned and an estimated date that the well will be returned to beneficial use or plugged and abandoned. 43 CFR 3162.3-4 (a). The operator shall promptly plug and abandon wells in which oil or gas is not encountered in paying quantities.

Wells that successfully pass the casing integrity test **may** be approved for Temporary Abandonment (TA) status provided that the operator:

- 1. **Submits a subsequent Sundry Notice** (Form 3160-5) requesting TA approval <u>with well bore diagram</u> with all perforations and CIBP's and tops of cement on CIBP's.
- 2. Describes the temporary abandonment procedure.
- 3. Attaches a clear copy or the original of the pressure test chart.
- 4. Give justification to allow well to be place in TA status and plan for future use of well with time frame that well will be place back on line or plans to P&A well will be submitted.

If the well does not pass the casing integrity test, then the operator shall within 30 days submit to BLM for approval one of the following:

- 1. A procedure to repair the casing so that a TA approval can be granted.
- 2. A procedure to plug and abandon the well.

## **Duthie Andrews 4**

2

- 1. Well may be approved to be TA/SI for a period of <u>1</u> year or until <u>Date: 03/22/2018</u> after successful MIT and subsequent report is submitted.
- 2. Must submit NOI to recomplete or NOI to P&A. Must be submitted by 03/22/2018
- 3. Contact BLM 24 hrs. prior to setting of plug so as it may be witnessed.