

Submit 1 Copy To Appropriate District Office

District I - (575) 393-6161
1625 N. French Dr., Hobbs, NM 88240
District II - (575) 748-1283
811 S. First St., Artesia, NM 88210
District III - (505) 334-6178
1000 Rio Brazos Rd., Aztec, NM 87410
District IV - (505) 476-3460
1220 S. St. Francis Dr., Santa Fe, NM 87505

HOBBS OGD
State of New Mexico
Energy, Minerals and Natural Resources
JUN 30 2017
OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505
RECEIVED

Form C-103
Revised August 1, 2011

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		WELL API NO. 30-025-31173
1. Type of Well: Oil Well <input type="checkbox"/> Gas Well <input checked="" type="checkbox"/> Other SWD		5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
2. Name of Operator Buckeye Disposal LLC		6. State Oil & Gas Lease No. 033446
3. Address of Operator PO Box 513 Hobbs New Mexico		7. Lease Name or Unit Agreement Name CBM
4. Well Location Unit Letter P : 467 feet from the S line and 467 feet from the E line Section 24 Township 19S Range 37E NMPM County LCA		8. Well Number 1
11. Elevation (Show whether DR, RKB, RT, GR, etc.)		9. OGRID Number 222759
		10. Pool name or Wildcat SKA999 ABO NORTH

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☒ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐
DOWNHOLE COMMINGLE ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☒ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ P AND A ☐
CASING/CEMENT JOB ☐

OTHER: ☐

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

5-27/ Rig up pulling unit
2 put B.O.P. on well
3 Release packer pull tubing + packer
4 Test tubing Replace bad tubing 10 joints
5 Shut down while new packer being coated with nickel
5-29 Run new packer with on off tool set at 4403.14 5 1/2 ASIX packer
Test packer to 500 PSI Run chart
Rig down get off of hole

NO chart Attached

Spud Date:

Rig Release Date:

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE JIM SAYRE TITLE MANAGER DATE 5-29-17
Type or print name JIM SAYRE E-mail address: jms@standardenergy.com PHONE: 575-361-5072
For State Use Only

APPROVED BY: MS Brown 7/3/2017 TITLE MANAGER DATE 7/3/2017
Conditions of Approval (if any): Well pulled again 6/30 witnessed chart. MRS

Accepted for Record Only