Submit 1 Copy To Appropriate District	State of New Mexico	Form C-103
Office <u>District I</u> – (575) 393-6161	Energy, Minerals and Natural Resources	Revised July 18, 2013
1625 N. French Dr., Hobbs, NM 88240		WELL API NO. 30-025-42562
<u>District II</u> ~ (575) 748-1283 811 S. First St., Artesia, NM 88210	OIL CONSERVATION DIVISION	5. Indicate Type of Lease
District III - (505) 334-6178	1220 South St. Francis Dr.	STATE FEE
1000 Rio Brazos Rd., Aztec, NM 87410 <u>District IV</u> – (505) 476-3460	Santa Fe, NM 87505	6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM 87505		
	ICES AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPO	SALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A	
PROPOSALS.)	CATION FOR PERMIT" (FORMED BOR SUCH	Edel Weisse 28 21 State Com
1. Type of Well: Oil Well	Gas Well Other	8. Well Number
2. Name of Operator	JUL 192017	9. OGRID Number
Devon Energy Production Compar	ıv, LP	6137
3. Address of Operator	RECEIVED	10. Pool name or Wildcat
333 W. Sheridan Avenue, Oklahor	na City, OK 73102	2 ND Bone Spring Sand MIDWAY; B.S.
4. Well Location		
Unit Letter E : 2440 feet from the North line and 400 feet from the West line		
Section 28	Township 17S Range 37E	NMPM Lea County, NM
11. Elevation (Show whether DR, RKB, RT, GR, etc.)		
3754' GL		
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data		
NOTICE OF INTENTION TO: SUBSEQUENT		
PERFORM REMEDIAL WORK	PLUG AND ABANDON ☑ REMEDIAL WOR	
TEMPORARILY ABANDON	CHANGE PLANS COMMENCE DR	ILLING OPNS
PULL OR ALTER CASING	MULTIPLE COMPL CASING/CEMEN	
DOWNHOLE COMMINGLE		P&A R
CLOSED-LOOP SYSTEM	□ OTHER:	
OTHER: 13 Describe proposed or comp	leted operations. (Clearly state all pertinent details, an	d give pertinent dates, including estimated date
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of		
proposed completion or recompletion.		
TO COLORED THE DAVIE GOVERNE	NOTIFE	
PROPOSED TO PLUG CONDUCTOR HOLE BEGIN		OCD 24
1. Cut conductor/mouse pipe off 3' BGL.		
PROPOSED TO PLUG CONDUCTOR HOLE 1. Cut conductor/mouse pipe off 3' BGL. 2. MIRU Redi-Mix Truck. Fill up conductor/mouse hole with redi mix cement. 3. Install dry hole marker. 4. Dig up ten horn/back fill cellar w/ dirt.		
Install dry hole marker.		OPERATIO
Dig up ten horn/back fill ce	llar w/ dirt.	MONS
Spud Date:	Rig Release Date:	
I hereby certify that the information above is true and complete to the best of my knowledge and belief.		
ρ , ρ		
SIGNATURE RAMMA XIII	TITLE Production Technologic	st
SIGNATURE ROMME Slack TITLE Production Technologist DATE 7-19-17		
Type or print name Ronnie SlackE-mail address: _Ronnie.Slack@dvn.com PHONE: _405-552-4615		
For State Use Only		
APPROVED BY: Mah Whitela TITLE P.E.S. DATE 07/19/2017		
Conditions of Approval (if any):		