

District I - (575) 393-6161  
1625 N. French Dr., Hobbs, NM 88240  
District II - (575) 748-1283  
811 S. First St., Artesia, NM 88210  
District III - (505) 334-6178  
1000 Rio Brazos Rd., Aztec, NM 87410  
District IV - (505) 476-3460  
1220 S. St. Francis Dr., Santa Fe, NM 87505

**HOBBS OGD**

**SEP 05 2017**

**RECEIVED**

CONSERVATION DIVISION  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

WELL API NO. 30-025-07365
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name North Hobbs (G/SA) Unit
8. Well Number 19-141
9. OGRID Number: 157984
10. Pool name or Wildcat Hobbs (G/SA)

<p><b>SUNDY NOTICES AND REPORTS ON WELLS</b> (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)</p>	
<p>1. Type of Well: Oil Well <input checked="" type="checkbox"/> Gas Well <input type="checkbox"/> Other Injector <input type="checkbox"/></p>	
<p>2. Name of Operator Occidental Permian Ltd.</p>	
<p>3. Address of Operator HCR 1 Box 90 Denver City, TX 79323</p>	
<p>4. Well Location Unit Letter <u>M</u> : <u>330</u> feet from the <u>South</u> line and <u>330</u> feet from the <u>West</u> line Section <u>19</u> Township <u>18S</u> Range <u>38E</u> NMPM Lea County</p>	
<p>11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3663' (DF)</p>	

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

- PERFORM REMEDIAL WORK ☒ PLUG AND ABANDON ☐  
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐  
PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐  
DOWNHOLE COMMINGLE ☐

SUBSEQUENT REPORT OF:

- REMEDIAL WORK ☐ ALTERING CASING ☐  
COMMENCE DRILLING OPNS. ☐ P AND A ☐  
CASING/CEMENT JOB ☐

OTHER: ☐

OTHER: ☐

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

- MIRU PU
- POOH with ESP
- RIH with perforating guns and add pay selectively 4045'-4150' in San Andres Zone 1 and 2C.
- Acidize all perfs
- RIH with ESP
- Return well to production

During this procedure we plan to use the closed-loop system with a steel tank and haul contents to the required disposal per ODC Rule 19.15.17

*SUBMIT CURRENT W.B.D.  
W/ SUBSEQUENT C-103.*

Spud Date:

Rig Release Date:

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE *Rick Reeves* TITLE *Production Engineer* DATE *9/5/17*

Type or print name Rick Reeves E-mail address: rick\_reeves@oxy.com PHONE: 713-215-7653

For State Use Only

*Mary Brown*

APPROVED BY: *AO/II* TITLE *AO/II* DATE *9/5/2017*

Conditions of Approval (if any):