District I (575) 202 6161	ce Charles Chil	
	State of New Mexico	Form C-103
<u>District I</u> - (575) 393-6161 1625 N. French Dr., Hobbs, NM 88240	Energy, Minerals and Natural Resource	Revised July 18,2013 WELL API NO.
District II - (575) 748-1283	OIL CONSERVATION DIVISION	30-025-20562
811 S. First St., Artesia, NM 88210		5. Indicate Type of Lease
<u>Disrtict III - (505)</u> 334-6178 1000 Rio Brazos Rd. Aztec, NM 87410	1220 South S. Paraisis Q.C.D	STATE ☐ FEE ☑
District IV - (505) 476-3460	Santa Fee NIM 8750517	6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM 8750	Santa Fes EM 675 2517	
SUNDRY NO	OTICES AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOS	ALS TO DRILL OR DEEPEN OR PLUCIAGE TO AVITE RENT	Grizzell
RESERVIOR. USE "APPLICATION FOR	PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	8. Well Number
1. Type of Well: Oil Well	Gas Well 🗸 Other	9
2. Name of Operator	/	9. OGRID Numer
	Apache Corporation	873
3. Address of Operator	ark Lana Sta 2000 Midland TV 70705	10. Pool Name or Wildcat
4. Well Location	ark Lane, Ste. 3000, Midland, TX 79705	Eunice; San Andres, Southwest
Unit Letter O	: 810 feet from the S line and	1980 feet from t E line
Section 8	Township 22S Range 37E	NMPM County Lea
	11. Elevation (Show whether DR, RKB,RT, GR, etc.)	
造工艺是是一个	3404' GR	
12. Ch	eck Appropriate Box To Indicate Nature of Notice, I	Report, or Other Data
	·	
Approved for Plugging of we		EQUENT REPORT OF:
under bond is retained pendi		☐ ALTERING CASING PAND A ☐ PAND A
completion of the C-103, Spe		T AND A
Report of Well Plugging, which	Il may be found on	
the OCD web page under form	115.	
Restoration bue by		
	leted operations. (Clearly state all pertinent details, a	
	oposed work.) SEE RULE 19.15.7.14 NMAC. For l	Multiple Completions: Attach wellbore
diagram or proposed completion	or recompletion.	
7/11/17 - Decission was made to	D&A well Guinn Burks & Jacob Bower met with Ma	evie Brown & Mark Whitaker
	o P&A well. Guinn Burks & Jacob Bower met with Ma	
at the OCD office to propose to	o P&A well. Guinn Burks & Jacob Bower met with Madrill down beside 4 1/2' and perf into casing form outs	
at the OCD office to propose to wellbore.	drill down beside 4 1/2' and perf into casing form outs	
at the OCD office to propose to wellbore. 7/11-17 - 8-7/17 - Continued to	drill down beside 4 1/2' and perf into casing form outs drill down outside of casing to a depth of 1100'.	ide and pump cmt into lower
at the OCD office to propose to wellbore. 7/11-17 - 8-7/17 - Continued to 8/8/17 - RIH w/WL & perf'd 20 s	drill down beside 4 1/2' and perf into casing form outs	ide and pump cmt into lower
at the OCD office to propose to wellbore. 7/11-17 - 8-7/17 - Continued to 8/8/17 - RIH w/WL & perf'd 20 s to surf.	drill down beside 4 1/2' and perf into casing form outs drill down outside of casing to a depth of 1100'. hots into 4 1/2" csg @ 1100', csg went on vac. Spott	ed 35 sx cmt, started getting CIRC
at the OCD office to propose to wellbore. 7/11-17 - 8-7/17 - Continued to 8/8/17 - RIH w/WL & perf'd 20 s to surf. 8/9/17 - 2 3/8" tbg cemented in t	drill down beside 4 1/2' and perf into casing form outs drill down outside of casing to a depth of 1100'. hots into 4 1/2" csg @ 1100', csg went on vac. Spott he hole. Tagged cmt @ 1097' inside tbg. Re-perfed	ed 35 sx cmt, started getting CIRC
at the OCD office to propose to wellbore. 7/11-17 - 8-7/17 - Continued to 8/8/17 - RIH w/WL & perf'd 20 s to surf. 8/9/17 - 2 3/8" tbg cemented in t into 4 1/2" csg. Pressured up. S	drill down beside 4 1/2' and perf into casing form outs drill down outside of casing to a depth of 1100'. hots into 4 1/2" csg @ 1100', csg went on vac. Spott	ed 35 sx cmt, started getting CIRC
at the OCD office to propose to wellbore. 7/11-17 - 8-7/17 - Continued to 8/8/17 - RIH w/WL & perf'd 20 s to surf. 8/9/17 - 2 3/8" tbg cemented in t into 4 1/2" csg. Pressured up. S agreed to P&A from free point of	drill down beside 4 1/2' and perf into casing form outs drill down outside of casing to a depth of 1100'. hots into 4 1/2" csg @ 1100', csg went on vac. Spott the hole. Tagged cmt @ 1097' inside tbg. Re-perfed come cmt inside csg @ 1100'. Called Guinn Burks & I	ed 35 sx cmt, started getting CIRC bg & casing in attempt to perf Mark & Maxie, discussed and agreed to
at the OCD office to propose to wellbore. 7/11-17 - 8-7/17 - Continued to 8/8/17 - RIH w/WL & perf'd 20 s to surf. 8/9/17 - 2 3/8" tbg cemented in tinto 4 1/2" csg. Pressured up. Sagreed to P&A from free point of 8/10/17 - RIH w/ dump bailer & 6	drill down beside 4 1/2' and perf into casing form outs drill down outside of casing to a depth of 1100'. hots into 4 1/2" csg @ 1100', csg went on vac. Spott the hole. Tagged cmt @ 1097' inside tbg. Re-perfed some cmt inside csg @ 1100'. Called Guinn Burks & If tbg. Free point tbg @ 740'-stuck, free @ 700'.	ed 35 sx cmt, started getting CIRC bg & casing in attempt to perf Mark & Maxie, discussed and agreed to sx Class "C" cmt @ 699', POOH
at the OCD office to propose to wellbore. 7/11-17 - 8-7/17 - Continued to 8/8/17 - RIH w/WL & perf'd 20 s to surf. 8/9/17 - 2 3/8" tbg cemented in tinto 4 1/2" csg. Pressured up. Sagreed to P&A from free point of 8/10/17 - RIH w/ dump bailer & w/ tbg. POOH & LD 7" csg @ 5	drill down beside 4 1/2' and perf into casing form outs drill down outside of casing to a depth of 1100'. hots into 4 1/2" csg @ 1100', csg went on vac. Spott the hole. Tagged cmt @ 1097' inside tbg. Re-perfed some cmt inside csg @ 1100'. Called Guinn Burks & I ftbg. Free point tbg @ 740'-stuck, free @ 700'. covered perfs with cmt. Cut tbg @ 700' & spotted 20	ed 35 sx cmt, started getting CIRC bg & casing in attempt to perf Mark & Maxie, discussed and agreed to sx Class "C" cmt @ 699', POOH
at the OCD office to propose to wellbore. 7/11-17 - 8-7/17 - Continued to 8/8/17 - RIH w/WL & perf'd 20 s to surf. 8/9/17 - 2 3/8" tbg cemented in tinto 4 1/2" csg. Pressured up. Sagreed to P&A from free point of 8/10/17 - RIH w/ dump bailer & w/ tbg. POOH & LD 7" csg @ 58/11/2017 - RIH & tagged cmt @	drill down beside 4 1/2' and perf into casing form outs drill down outside of casing to a depth of 1100'. hots into 4 1/2" csg @ 1100', csg went on vac. Spott the hole. Tagged cmt @ 1097' inside tbg. Re-perfed some cmt inside csg @ 1100'. Called Guinn Burks & If tbg. Free point tbg @ 740'-stuck, free @ 700'. covered perfs with cmt. Cut tbg @ 700' & spotted 20 17'. RIH w/tbg & tagged @ 460' & spotted 800 sx Cla	ed 35 sx cmt, started getting CIRC bg & casing in attempt to perf Mark & Maxie, discussed and agreed to sx Class "C" cmt @ 699', POOH ass "C" cmt @ 460', no CIRC to surf.
at the OCD office to propose to wellbore. 7/11-17 - 8-7/17 - Continued to 8/8/17 - RIH w/WL & perf'd 20 s to surf. 8/9/17 - 2 3/8" tbg cemented in tinto 4 1/2" csg. Pressured up. Sagreed to P&A from free point of 8/10/17 - RIH w/ dump bailer & w/ tbg. POOH & LD 7" csg @ 58/11/2017 - RIH & tagged cmt @	drill down beside 4 1/2' and perf into casing form outs drill down outside of casing to a depth of 1100'. hots into 4 1/2" csg @ 1100', csg went on vac. Spott the hole. Tagged cmt @ 1097' inside tbg. Re-perfed some cmt inside csg @ 1100'. Called Guinn Burks & If tbg. Free point tbg @ 740'-stuck, free @ 700'. covered perfs with cmt. Cut tbg @ 700' & spotted 20 17'. RIH w/tbg & tagged @ 460' & spotted 800 sx Cla 274', wait on cementer till Monday.	ed 35 sx cmt, started getting CIRC bg & casing in attempt to perf Mark & Maxie, discussed and agreed to sx Class "C" cmt @ 699', POOH ass "C" cmt @ 460', no CIRC to surf.
at the OCD office to propose to wellbore. 7/11-17 - 8-7/17 - Continued to 8/8/17 - RIH w/WL & perf'd 20 s to surf. 8/9/17 - 2 3/8" tbg cemented in tinto 4 1/2" csg. Pressured up. Sagreed to P&A from free point of 8/10/17 - RIH w/ dump bailer & w/ tbg. POOH & LD 7" csg @ 5 8/11/2017 - RIH & tagged cmt @ 8/14/17 - MIRU cementer & spot	drill down beside 4 1/2' and perf into casing form outs drill down outside of casing to a depth of 1100'. hots into 4 1/2" csg @ 1100', csg went on vac. Spott the hole. Tagged cmt @ 1097' inside tbg. Re-perfed some cmt inside csg @ 1100'. Called Guinn Burks & If tbg. Free point tbg @ 740'-stuck, free @ 700'. covered perfs with cmt. Cut tbg @ 700' & spotted 20 17'. RIH w/tbg & tagged @ 460' & spotted 800 sx Cla 274', wait on cementer till Monday.	ed 35 sx cmt, started getting CIRC bg & casing in attempt to perf Mark & Maxie, discussed and agreed to sx Class "C" cmt @ 699', POOH ass "C" cmt @ 460', no CIRC to surf.
at the OCD office to propose to wellbore. 7/11-17 - 8-7/17 - Continued to 8/8/17 - RIH w/WL & perf'd 20 s to surf. 8/9/17 - 2 3/8" tbg cemented in t into 4 1/2" csg. Pressured up. Sagreed to P&A from free point of 8/10/17 - RIH w/ dump bailer & 6 w/ tbg. POOH & LD 7" csg @ 5 8/11/2017 - RIH & tagged cmt @ 8/14/17 - MIRU cementer & spot RDMO.	drill down beside 4 1/2' and perf into casing form outs drill down outside of casing to a depth of 1100'. hots into 4 1/2" csg @ 1100', csg went on vac. Spott the hole. Tagged cmt @ 1097' inside tbg. Re-perfed from cmt inside csg @ 1100'. Called Guinn Burks & If tbg. Free point tbg @ 740'-stuck, free @ 700'. covered perfs with cmt. Cut tbg @ 700' & spotted 20 17'. RIH w/tbg & tagged @ 460' & spotted 800 sx Class 274', wait on cementer till Monday.	ed 35 sx cmt, started getting CIRC bg & casing in attempt to perf Mark & Maxie, discussed and agreed to sx Class "C" cmt @ 699', POOH ass "C" cmt @ 460', no CIRC to surf.
at the OCD office to propose to wellbore. 7/11-17 - 8-7/17 - Continued to 8/8/17 - RIH w/WL & perf'd 20 s to surf. 8/9/17 - 2 3/8" tbg cemented in t into 4 1/2" csg. Pressured up. Sagreed to P&A from free point of 8/10/17 - RIH w/ dump bailer & 6 w/ tbg. POOH & LD 7" csg @ 5 8/11/2017 - RIH & tagged cmt @ 8/14/17 - MIRU cementer & spot RDMO.	drill down beside 4 1/2' and perf into casing form outs drill down outside of casing to a depth of 1100'. hots into 4 1/2" csg @ 1100', csg went on vac. Spott the hole. Tagged cmt @ 1097' inside tbg. Re-perfed from cmt inside csg @ 1100'. Called Guinn Burks & If tbg. Free point tbg @ 740'-stuck, free @ 700'. covered perfs with cmt. Cut tbg @ 700' & spotted 20 17'. RIH w/tbg & tagged @ 460' & spotted 800 sx Class 274', wait on cementer till Monday.	ed 35 sx cmt, started getting CIRC bg & casing in attempt to perf Mark & Maxie, discussed and agreed to sx Class "C" cmt @ 699', POOH ass "C" cmt @ 460', no CIRC to surf.
at the OCD office to propose to wellbore. 7/11-17 - 8-7/17 - Continued to 8/8/17 - RIH w/WL & perf'd 20 s to surf. 8/9/17 - 2 3/8" tbg cemented in tinto 4 1/2" csg. Pressured up. Sagreed to P&A from free point of 8/10/17 - RIH w/ dump bailer & w/tbg. POOH & LD 7" csg @ 5 8/11/2017 - RIH & tagged cmt @ 8/14/17 - MIRU cementer & spot RDMO. Spud Date:	drill down beside 4 1/2' and perf into casing form outs drill down outside of casing to a depth of 1100'. hots into 4 1/2" csg @ 1100', csg went on vac. Spott the hole. Tagged cmt @ 1097' inside tbg. Re-perfed from cmt inside csg @ 1100'. Called Guinn Burks & If tbg. Free point tbg @ 740'-stuck, free @ 700'. covered perfs with cmt. Cut tbg @ 700' & spotted 20 17'. RIH w/tbg & tagged @ 460' & spotted 800 sx Class 274', wait on cementer till Monday.	ed 35 sx cmt, started getting CIRC bg & casing in attempt to perf Mark & Maxie, discussed and agreed to sx Class "C" cmt @ 699', POOH ass "C" cmt @ 460', no CIRC to surf. bg & topped off surf csg. Well Plugged.
at the OCD office to propose to wellbore. 7/11-17 - 8-7/17 - Continued to 8/8/17 - RIH w/WL & perf'd 20 s to surf. 8/9/17 - 2 3/8" tbg cemented in to into 4 1/2" csg. Pressured up. Sagreed to P&A from free point of 8/10/17 - RIH w/ dump bailer & w/ tbg. POOH & LD 7" csg @ 5 8/11/2017 - RIH & tagged cmt @ 8/14/17 - MIRU cementer & spot RDMO. Spud Date:	drill down beside 4 1/2' and perf into casing form outs drill down outside of casing to a depth of 1100'. hots into 4 1/2" csg @ 1100', csg went on vac. Spott the hole. Tagged cmt @ 1097' inside tbg. Re-perfed from cmt inside csg @ 1100'. Called Guinn Burks & If tbg. Free point tbg @ 740'-stuck, free @ 700'. covered perfs with cmt. Cut tbg @ 700' & spotted 20 17'. RIH w/tbg & tagged @ 460' & spotted 800 sx Cla 274', wait on cementer till Monday. tted 76 sx Class "C" cmt from 274' to surf, POOH w/ the Rig Release Date:	ed 35 sx cmt, started getting CIRC bg & casing in attempt to perf Mark & Maxie, discussed and agreed to sx Class "C" cmt @ 699', POOH ass "C" cmt @ 460', no CIRC to surf. bg & topped off surf csg. Well Plugged.
at the OCD office to propose to wellbore. 7/11-17 - 8-7/17 - Continued to 8/8/17 - RIH w/WL & perf'd 20 s to surf. 8/9/17 - 2 3/8" tbg cemented in to into 4 1/2" csg. Pressured up. Sagreed to P&A from free point of 8/10/17 - RIH w/ dump bailer & w/ tbg. POOH & LD 7" csg @ 5 8/11/2017 - RIH & tagged cmt @ 8/14/17 - MIRU cementer & spot RDMO. Spud Date:	drill down beside 4 1/2' and perf into casing form outs drill down outside of casing to a depth of 1100'. hots into 4 1/2" csg @ 1100', csg went on vac. Spott the hole. Tagged cmt @ 1097' inside tbg. Re-perfed some cmt inside csg @ 1100'. Called Guinn Burks & I f tbg. Free point tbg @ 740'-stuck, free @ 700'. covered perfs with cmt. Cut tbg @ 700' & spotted 20 17'. RIH w/tbg & tagged @ 460' & spotted 800 sx Cla 274', wait on cementer till Monday. tted 76 sx Class "C" cmt from 274' to surf, POOH w/ the Rig Release Date:	ed 35 sx cmt, started getting CIRC bg & casing in attempt to perf Mark & Maxie, discussed and agreed to sx Class "C" cmt @ 699', POOH ass "C" cmt @ 460', no CIRC to surf. bg & topped off surf csg. Well Plugged.
at the OCD office to propose to wellbore. 7/11-17 - 8-7/17 - Continued to 8/8/17 - RIH w/WL & perf'd 20 s to surf. 8/9/17 - 2 3/8" tbg cemented in to into 4 1/2" csg. Pressured up. Sagreed to P&A from free point of 8/10/17 - RIH w/ dump bailer & w/ tbg. POOH & LD 7" csg @ 5 8/11/2017 - RIH & tagged cmt @ 8/14/17 - MIRU cementer & spot RDMO. Spud Date:	drill down beside 4 1/2' and perf into casing form outs drill down outside of casing to a depth of 1100'. hots into 4 1/2" csg @ 1100', csg went on vac. Spott the hole. Tagged cmt @ 1097' inside tbg. Re-perfed from cmt inside csg @ 1100'. Called Guinn Burks & If tbg. Free point tbg @ 740'-stuck, free @ 700'. covered perfs with cmt. Cut tbg @ 700' & spotted 20 17'. RIH w/tbg & tagged @ 460' & spotted 800 sx Cla 274', wait on cementer till Monday. tted 76 sx Class "C" cmt from 274' to surf, POOH w/ the Rig Release Date:	ed 35 sx cmt, started getting CIRC bg & casing in attempt to perf Mark & Maxie, discussed and agreed to sx Class "C" cmt @ 699', POOH ass "C" cmt @ 460', no CIRC to surf. bg & topped off surf csg. Well Plugged.
at the OCD office to propose to wellbore. 7/11-17 - 8-7/17 - Continued to 8/8/17 - RIH w/WL & perf'd 20 s to surf. 8/9/17 - 2 3/8" tbg cemented in tinto 4 1/2" csg. Pressured up. Sagreed to P&A from free point of 8/10/17 - RIH w/ dump bailer & w/tbg. POOH & LD 7" csg @ 58/11/2017 - RIH & tagged cmt @ 8/14/17 - MIRU cementer & spot RDMO. Spud Date:	drill down beside 4 1/2' and perf into casing form outs drill down outside of casing to a depth of 1100'. hots into 4 1/2" csg @ 1100', csg went on vac. Spott the hole. Tagged cmt @ 1097' inside tbg. Re-perfed from cmt inside csg @ 1100'. Called Guinn Burks & If tbg. Free point tbg @ 740'-stuck, free @ 700'. covered perfs with cmt. Cut tbg @ 700' & spotted 20 17'. RIH w/tbg & tagged @ 460' & spotted 800 sx Cla 274', wait on cementer till Monday. tted 76 sx Class "C" cmt from 274' to surf, POOH w/ the Rig Release Date:	ed 35 sx cmt, started getting CIRC bg & casing in attempt to perf Mark & Maxie, discussed and agreed to sx Class "C" cmt @ 699', POOH ass "C" cmt @ 460', no CIRC to surf. bg & topped off surf csg. Well Plugged. wledge and belief. Foreman DATE 8/30/17
at the OCD office to propose to wellbore. 7/11-17 - 8-7/17 - Continued to 8/8/17 - RIH w/WL & perf'd 20 s to surf. 8/9/17 - 2 3/8" tbg cemented in tinto 4 1/2" csg. Pressured up. Sagreed to P&A from free point of 8/10/17 - RIH w/ dump bailer & w/tbg. POOH & LD 7" csg @ 5 8/11/2017 - RIH & tagged cmt @ 8/14/17 - MIRU cementer & spot RDMO. Spud Date:	drill down beside 4 1/2' and perf into casing form outs drill down outside of casing to a depth of 1100'. hots into 4 1/2" csg @ 1100', csg went on vac. Spott the hole. Tagged cmt @ 1097' inside tbg. Re-perfed from cmt inside csg @ 1100'. Called Guinn Burks & If tbg. Free point tbg @ 740'-stuck, free @ 700'. covered perfs with cmt. Cut tbg @ 700' & spotted 20 17'. RIH w/tbg & tagged @ 460' & spotted 800 sx Class 274', wait on cementer till Monday. tted 76 sx Class "C" cmt from 274' to surf, POOH w/ to Rig Release Date: TITLE Sr. Reclamation	ed 35 sx cmt, started getting CIRC bg & casing in attempt to perf Mark & Maxie, discussed and agreed to sx Class "C" cmt @ 699', POOH ass "C" cmt @ 460', no CIRC to surf. bg & topped off surf csg. Well Plugged. wledge and belief. Foreman DATE 8/30/17
at the OCD office to propose to wellbore. 7/11-17 - 8-7/17 - Continued to 8/8/17 - RIH w/WL & perf'd 20 s to surf. 8/9/17 - 2 3/8" tbg cemented in tinto 4 1/2" csg. Pressured up. Sagreed to P&A from free point of 8/10/17 - RIH w/ dump bailer & w/tbg. POOH & LD 7" csg @ 5 8/11/2017 - RIH & tagged cmt @ 8/14/17 - MIRU cementer & spot RDMO. Spud Date: I hereby certify that the information of SIGNATURE Type or print name For State Use Only	drill down beside 4 1/2' and perf into casing form outs drill down outside of casing to a depth of 1100'. hots into 4 1/2" csg @ 1100', csg went on vac. Spott the hole. Tagged cmt @ 1097' inside tbg. Re-perfed some cmt inside csg @ 1100'. Called Guinn Burks & If tbg. Free point tbg @ 740'-stuck, free @ 700'. covered perfs with cmt. Cut tbg @ 700' & spotted 20 17'. RIH w/tbg & tagged @ 460' & spotted 800 sx Cla 274', wait on cementer till Monday. Itted 76 sx Class "C" cmt from 274' to surf, POOH w/ to Rig Release Date: TITLE Sr. Reclamation Guinn Burks E-mail add. guinn.burks@apach	ed 35 sx cmt, started getting CIRC bg & casing in attempt to perf Mark & Maxie, discussed and agreed to sx Class "C" cmt @ 699', POOH ass "C" cmt @ 460', no CIRC to surf. bg & topped off surf csg. Well Plugged. wledge and belief. Foreman DATE 8/30/17 eccorp.com PHONE: 432-556-9143
at the OCD office to propose to wellbore. 7/11-17 - 8-7/17 - Continued to 8/8/17 - RIH w/WL & perf'd 20 s to surf. 8/9/17 - 2 3/8" tbg cemented in t into 4 1/2" csg. Pressured up. Sagreed to P&A from free point of 8/10/17 - RIH w/ dump bailer & w/ tbg. POOH & LD 7" csg @ 5 8/11/2017 - RIH & tagged cmt @ 8/14/17 - MIRU cementer & spot RDMO. Spud Date: I hereby certify that the information of the supplementary of the supple	drill down beside 4 1/2' and perf into casing form outs drill down outside of casing to a depth of 1100'. hots into 4 1/2" csg @ 1100', csg went on vac. Spott the hole. Tagged cmt @ 1097' inside tbg. Re-perfed from cmt inside csg @ 1100'. Called Guinn Burks & If tbg. Free point tbg @ 740'-stuck, free @ 700'. covered perfs with cmt. Cut tbg @ 700' & spotted 20 17'. RIH w/tbg & tagged @ 460' & spotted 800 sx Class 274', wait on cementer till Monday. tted 76 sx Class "C" cmt from 274' to surf, POOH w/ to Rig Release Date: TITLE Sr. Reclamation	ed 35 sx cmt, started getting CIRC bg & casing in attempt to perf Mark & Maxie, discussed and agreed to sx Class "C" cmt @ 699', POOH ass "C" cmt @ 460', no CIRC to surf. bg & topped off surf csg. Well Plugged. wledge and belief. Foreman DATE 8/30/17