Submit 1 Copy To Appropriate District State of New Mexico	Form C-103
Office HOBBS OCD linerals and Natural Resources	Revised July 18, 2013
1625 N French Dr., Hobbs, NM 88240	WELL API NO. 30-025-02399
811 S. First SL, Artesia, NM 88210 JEP U / QUUYONSERVATION DIVISION	5. Indicate Type of Lease
District III - (505) 334-6178 1220 South St. Francis Dr.   1000 Rio Brazos Rd, Aztec, NM 87410 Santa Fe, NM 87505   District IV - (505) 476-3460 Santa Fe, NM 87505   1220 South St. Francis Dr. Santa Fe, NM 87505	STATE FEE
District IV - (505) 476-3460 <b>RECEIVED</b> Salita FC, 1919 87505 1220 S St Francis Dr., Santa Fc, NM	6. State Oil & Gas Lease No.
87505 SUNDRY NOTICES AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A	. Deale Manie of One Agreement Manie
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	MESCALERO RIDGE UNIT
1. Type of Well: Oil Well Gas Well S Other JU	8. Well Number 282
2. Name of Operator LINN OPERATING, LLC	9. OGRID Number 269324
3. Address of Operator	10. Pool name or Wildcat
600 TRAVIS ST., SUITE 1400, HOUSTON, TX 77002 4. Well Location	SWD; YATES
4. Well Location Unit Letter B : 660 feet from the N line and 1980 feet from the F line	
Section 28 Township 19S Range 34E NMPM LEA County	
11. Elevation (Show whether DR, RKB, RT, GR, etc.)	
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING	
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PAND A	
PULL OR ALTER CASING DULTIPLE COMPL CASING/CEMENT JOB	
CLOSED-LOOP SYSTEM	
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date	
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed	
completion or recompletion.	
Linn is respectfully submitting an operational summary for work performed to repair hole in tubing. In addition a successful MIT was conducted on 8/30/2017 and is included in this submittal.	
successful with was conducted on 6/30/2017 and is included in this submittal.	
The Mescalero Ridge Unit #282 SWD was returned to injection on 9/6/2017. The initial injection rate was 47 bbls.	
This well should be classified as active.	
Please note that this well is on our ACOI 262-I Agreement.	
Spud Date: Rig Release Date:	
I hereby certify that the information above is mue and complete to the best of my knowledge and belief.	
NIL. Marca	
SIGNATURE DATE 08/22/2017	
SIGNATORE TO OUT POST THE Regulatory manager DATE COLDECT	
Type or print name Debi Gordon E-mail address: dgordon@linnenergy.com PHONE: 281.840.4010	
For State Use Only Mal HELOWID ADIT QM 2014	
APPROVED BY: DATE DATE	
Conditions of Approval (if any):	
v	


RBDMS-CHART-V

## MESCALERO RIDGE UNIT 282 SWD API 30-025-02399 LEA COUNTY, NM REPAIR HOLE IN TUBING AND RETURN WELL TO INJECTION OPERATIONAL SUMMARY

- 08/24/2017 RU WSU, SET FRAC TANK IN PLACE, CHECED SITP/SICP, TBG & CSG PRESSURE WAS 30 PSI. SDFD DUE TO LIGHTNING & RAIN.
- 08/25/2017 AOL, HSM, CHECKED SITP/SICP, TBG & CSG PRESSURE WAS 30 PSI. BLED OFF PRESSURE TO FT, ND WH, NU BOP & RELEASED SEALED BORE PACKER TOOL. CIRCULATED 20 BBLS OF 10# BRINE, TOOH STANDING BACK TBG, FOUND HOLE IN TBG @ JT 68, CONTINUED TOOH, LAID DOWN SEALED BORE TOOL, TIH WITH TBG & LAID DOWN ALL TBG DUE TO ICP BEING CORRODED. SWI & SDFWE.
- 08/28/2017 AOL, HSM, CHECKED SICP & CSH PRESSURE WAS 70 PSI. BLED OFF PRESSURE TO FT, FOUND SERVICE COMPANY DELIVERED WRONG TBG FROM YARD, WAITED ON ORDERS & SDFD.
- 08/29/2017 AOL, HSM, CHECKED SICP & CSG PRESSURE WAS O PSI. BLED OFF TO FT, MU RE-DRESED SEALED BORE ASSEMBLY STINGER, TIH WITH 115 JTS OF 2 3/8" IPC TBG, STUNG INTO 9 5/8" PACKER ASSEMBLY, TESTED TO 500 PSI FOR 30 MINS WITH NO LOSS OF PRESSURE, BLED OFF PRESSURE & LD 1 JT. SPACED OUT TBG WITH 4', 8' 10' TBG SUBS, PU 1 JT, TIH TO 2' ABOVE SEALED BORE PACKER ASSEMBLY, REVERSE CIRCULATED 260 BBLS OF PACKER FLUID, STUNG INTO PACKER ASSEMBLY, ND BOP, NU WH FLANGE, LANDED TBG UNDER 5 PTS OF TENSION, INSTALLED NEW RING & WELLHEAD BOLTS. TESTED TO 500 PSI WITH NO LOSS OF PRESSURE, BLED OFF PRESSURE, SWI & SDFD. \*\*TBG DETAIL\*\*

1 JT 2 3/8" IPC = 33.51 4' 2 3/8" IPC TBG SUB = 4.1' 8' 2 3/8" IPC TBG SUB= 8.1' 10' 2 3/8" IPC TBG SUB= 10.1' 114 JTS 2 3/8" IPC TBG = 3,721.61' 2 3/8" BAKER HUGHES SEALED BORE ASSEMBLY STINGER (3.24" OD) PART #32509 BAKER 443-01 \*\*TOP OF PACKER ASSEMBLY @ 3,777.52'

- 08/30/2017 AOL, HSM, CHECKED SITP/SICP, TBG PRESSURE WAS 30 PSI & CSG PRESSURE WAS O PSI. WAITED ON KILL TRUCK TO AOL WITH RECORDER EQUIPMENT, RU KT TO CSG, PERFORMED MIT TEST TO 380 PSI FOR 40 MINUTES, GOOD TEST, RD WSU, CLEAN & MOVE OFF LOCATION.
- 09/06/2017 RETURNED WELL TO INJECTION. THE INITIAL INJECTION RATE WAS 47 BBLS.



Updated 9/7/17

