Submit 1 Copy To Appropriate District Office State of New Mexico District I - (575) 393-6161 Energy, Minerals and Natural Resources 1625 N. French Dr., Hobbs, NM 88240 District II - (575) 748-1283 1811 S. First St., Artesia, NM 88210 OIL CONSERVATION DIVISION District II - (505) 334-6178 OIL CONSERVATION DIVISION 1000 Rio Brazos Rd., Aztec, NM 87 to DBBS OI220 South St. Francis Dr. 1000 Rio Brazos Rd., Aztec, NM 87 to DBBS Sep 2 0 2017 87505 SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSE TO CERVITE (FORM C-101) FOR SUCH PROPOSALS.) Gas Well 1. Type of Well: Oil Well Gas Well Other 2. Name of Operator / 3. Address of Operator / 4. Well Location .	Form C-103 Revised July 18, 2013 WELL API NO. <u>30-025-27845</u> 5. Indicate Type of Lease STATE FEE - 6. State Oil & Gas Lease No. 7. Lease Name or Unit Agreement Name Langlie Jal Unit 8. Well Number 100 / 9. OGRID Number 372000 / 10. Pool name or Wildcat Langlie Mattix
Unit Letter $_$: 1426 feet from the $_$ line and 1300 feet from the $_$ line	
Section 32 Township 24 S Range 37E	NMPM County LEA
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 32.35	
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON TEMPORARILY ABANDON CHANGE PLANS PULL OR ALTER CASING MULTIPLE COMPL CLOSED-LOOP SYSTEM COMMENCE ORILLING OPNS. PULL OR ALTER CASING MULTIPLE COMPL CLOSED-LOOP SYSTEM COTHER: CLOSED-LOOP SYSTEM OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion. Scope of work: Langlie Jal Unit #100 is an inactive well on Pogo's agreed compliance order. Records indicate that this well was left down due to a hole in the tubing from a prior operator. Pogo respectfully request to repair this well and return it to normal production. Expected production from this well is 2 BOPD and 125 BWPD. Estimated start of work: 10/1/2017 Procedure: 1) Test Anchors. AOL. ND WH, NU BOP. RU WO rig. 3) POOH w/ 2-7/8'' tbg. LD as needed. 3) POOH w/ 2-7/8'' tbg. LD as needed. 4) POOH w/ 2-7/8'' tbg. Da se neede. 6) Check for good pump and rods. 6) Check for good pump action. Check for good pump action. 7) ND BOP, NU WH. 6) Clean location, RD WO unit, move out	
Spud Date: Rig Release Date:	
I hereby certify that the information above is true and complete to the best of my knowledge and belief. SIGNATURE TITLE Operations Manager Type or print name: Kyle Townsend E-mail address: kyle@pogoresources.com PHONE:713-305-9886	
For State Use Only	
APPROVED BY:	