		OCD-HOBE	38			
	UNITED STATES EPARTMENT OF THE IN UREAU OF LAND MANAC			OMB N Expires: Ja	APPROVED O. 1004-0137 anuary 31, 2018	
SUNDRY	NOTICES AND REPOR	RTS ON WELLS	OCH	5. Lease Serial No. NMNM100864		
abandoned well. Use form 3160-3 (APD) for such proposalsp				6. If Indian, Allottee or Tribe Name		
SUBMIT IN TRIPLICATE - Other instructions on page 2				7. If Unit or CA/Agreement, Name and/or No. NMNM111768		
Type of Well Oil Well	ED	8. Well Name and No. RIO BLANCO 33				
Name of Operator DEVON ENERGY PRODUCT		9. API Well No. 30-025-36359-00-S1				
3a. Address 6488 SEVEN RIVERS HIGHWAY ARTESIA, NM 88211 3b. Phone No. (include area code) Ph: 405-228-8429				10. Field and Pool or Exploratory Area BELL LAKE		
4. Location of Well (Footage, Sec., T		11. County or Parish, State				
Sec 33 T22S R34E SESW 10 32.343689 N Lat, 103.478308		LEA COUNTY, NM				
12. CHECK THE AI	PPROPRIATE BOX(ES)	TO INDICATE NATURE OF	F NOTICE, I	REPORT, OR OTH	HER DATA	
TYPE OF SUBMISSION	TYPE OF ACTION					
Notice of Intent	☐ Acidize	☐ Deepen	☐ Production	on (Start/Resume)	☐ Water Shut-Off	
	☐ Alter Casing	☐ Hydraulic Fracturing	☐ Reclamat	tion	■ Well Integrity	
☐ Subsequent Report	☐ Casing Repair	☐ New Construction	Recompl Recompl	ete	☐ Other	
☐ Final Abandonment Notice	☐ Change Plans	☐ Plug and Abandon	☐ Tempora	rily Abandon		
	☐ Convert to Injection	☐ Plug Back	☐ Water Di	sposal		
13. Describe Proposed or Completed Op If the proposal is to deepen direction Attach the Bond under which the wo following completion of the involved testing has been completed. Final Al determined that the site is ready for f Devon Energy Production Co.	ally or recomplete horizontally, g rk will be performed or provide t I operations. If the operation res- bandonment Notices must be file final inspection.	give subsurface locations and measur the Bond No. on file with BLM/BIA ults in a multiple completion or reco d only after all requirements, includi	red and true ver . Required subs mpletion in a ne ing reclamation,	tical depths of all pertin sequent reports must be ew interval, a Form 316 have been completed.	nent markers and zones. filed within 30 days	
recomplete to the Atoka.	respectionly requests app	roval to abandon the bevonia	in formation (aria		
Current producing interval is 1	14,497-14,682? (open hole	SEE AT	TACHE	D FOR		
Proposed Procedure: -Unset production packer at 1 -RIH w/ WL and set CIBP at 1 -Set CIBP at 12,700? to coverPerforate Atoka from 12,070RIH w/ redressed packer, on -RIH w/ on/off tool and production	4,397?; dump 35? cement r top of Morrow; dump 35? -12,100? at 4 spf /off tool and plug in place; ction tubing string; circulate	ng BHA Len tep of plug. Complete of plug. WL set packer at 12,040? e annulus with packer fluid, la	NS OF A	PPROVAL APPR(OVED	
14. I hereby certify that the foregoing is	Electronic Submission #3	80568 verified by the BLM Welly PRODUCTION COM LP, sen				

14. I hereby certify that the foregoing is true and correct. Electronic Submission #380568 verified by the BLM Well Information System For DEVON ENERGY PRODUCTION COM LP, sent to the Hobbs Committed to AFMSS for processing by PRISCILLA PEREZ on 07/17/2017 (17PP0433SE)							
Name (Printed/Typed) REBECCA DEAL		Title	Title REGULATORY COMPLIANCE PROFESSI				
Signature	(Electronic Submission)	Date	07/05/2017	,			
THIS SPACE FOR FEDERAL OR STATE OFFICE USE							
Approved By	Swart 09/07/2017	Title	TPET	Date			
Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.		nt or ase	Office BUREAU OF LAND MANAGEMENT CARLSBAD FIELD OFFICE				

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.


(Instructions on page 2)
** BLM REVISED ** BLM REVISED ** BLM REVISED ** BLM REVISED **


Additional data for EC transaction #380568 that would not fit on the form

32. Additional remarks, continued

production packer, and test annulus
-Hang on tubing, NU production tree and test.
-Retrieve plug in packer and swab test
-Produce well and evaluate for acid stimulation
-If necessary, acidize perforations with 2500 gals 15% HCL
-Return well to production

Please see attached current and proposed wellbore schematics.





Conditions of Approval

Devon Energy Production Company Rio Blanco - 01, API 3002536359 T22S-R34E, Sec 33, 1000FSL & 1620FWL September 07, 2017

- 1. Within 90 days of these conditions of approval for the processed Electronic Submission #380568 notice of intent begin wellbore operations.
- 2. Operator is required to have the BLM approved NOI procedure with applicable conditions of approval on location for this workover operation.
- 3. Due to being within the Lesser Prairie Chicken habitat, this workover activity will be restricted to the hours of 9:00am through 3:00am for the period of March 1 through June 15.
- 4. The communization agreement for this well (NM11768) does not include the Atoka pay. Amendments to that agreement may be necessary.
- 5. Subject to like approval by the New Mexico Oil Conservation Division.
- 6. Before adding, replacing, or repairing casing or a liner, prior BLM approval of the design is required. Use notice of intent Form 3160-5.
- 7. A closed loop system is required. The operator shall properly dispose of drilling/circulating contents at an authorized disposal site. Tanks are required for all operations, no excavated pits.
- 8. Surface disturbance beyond the existing pad shall have prior BLM approval.
- 9. Functional H₂S monitoring equipment shall be on location.
- 10. Blow Out Prevention Equipment shop tested to 10000 (10M) to be used. All BOPE and workover procedures shall establish fail safe well control. Ram(s) for the work string(s) used is required equipment. Manual BOP closure system including a blind ram and pipe ram(s) designed to close on all (hand wheels or automatic locking devices) equipment installed regardless of BOP design. Function test the installed BOPE to 500psig when well conditions allow. Related equipment, (choke manifolds, kill trucks, gas vent or flare lines, etc.) employed when needed for reasonable well control requirements.
- 11. All waste (i.e. trash, salts, chemicals, sewage, gray water, etc.) created during work over operations shall be safely contained and disposed of properly at a waste disposal facility. No waste material or fluid shall be disposed of on the well location or surrounding area. Portojohns and trash containers will be on-location during fracturing operations or any other crewintensive operations.
- 12. Notify BLM 575-393-3612 Lea Co as work begins. Some procedures witnessed.
- 13. The BLM PET witness is to run tbg tally and agree to cement volumes and placement.

 Sample each plug for cement curing time and tag and/or pressure test as requested by BLM PET witness.

- 14. Set cement plugs to cover a minimum of 100ft plus 10ft for every 1,000ft from the bottom of the plug, rounding the number of necessary sacks up to the nearest 5 sacks. Never use less than 25sx. Examples: A cement plug set at 8000 in 7" casing would require a min of 35sx.
- 15. Class H > 7500ft cement plugs(s) will be necessary. For any "H" plug that requires a tag or pressure test a minimum WOC time of 8 hours required. Formation isolation plugs of Class "H" to be mixed 16.4#/gal, 1.06ft³/sx, 4.3gal/sx water.
- 16. Minimum requirement for mud placed between plugs is 25 sacks of salt water gel per 100 barrels in 9 lb/gal brine.
- 17. Set a CIBP as near as possible to the Devonion formation top at 14486'and pressure test the casing to 500psig.
- 18. Perform a 30 minute casing integrity test of 2000psig minimum. Document the pressure test on a one hour full rotation calibrated (within 6 months) recorder chart registering within 35 to 85 per cent of its full range. Verify all annular casing vents plumbed to the surface and open during this pressure test. Call BLM 575-393-3612 Lea Co. and arrange for a BLM witness of that pressure test. Include a copy of the chart with the subsequent sundry for this workover.
- 19. Provide BLM with an electronic copy (Adobe Acrobat Document) cement bond log record from the 11678' taken with 0psig casing pressure to TOC. Attach the CBL to a pswartz@blm.gov email.
- 20. Set a balanced plug on the CIBP set as near as possible to the Devonion formation top of 14486'. WOC, and tag the plug with tbg at 14221' covering the formation top.
- 21. Set a balanced cmt plug across Morrow formation top from 12800 or below. WOC, and tag the plug with tbg at 12570' or above covering the formation top.
- 22. Perforate the Atoka formation as proposed.
- 23. The subsequent report is to include stimulation injection pressures. Report maximum/minimum injection rate (BPM) and max/min stimulation injection pressures.
- 24. Submit a (BLM Form 3160-5 subsequent report describing (dated daily) all wellbore activity and the Mechanical Integrity Test. File intermediate Form 3160-5 within 30 days of any interrupted workover procedures and a complete workover subsequent sundry.
- 25. A BLM Well Recompletion Form 3160-4 and a NMOCD Form C-102 "Well Location and Acreage Dedication Plat" with updated information is necessary with the subsequent package when recompletion changes a well's Pool designation.
- 26. File intermediate **subsequent sundry** Form 3160-**5** within 30 days of any interrupted workover procedures and a complete workover subsequent sundry.
- 27. Submit evidence to support your determination that the well is in active "beneficial use" for BLM approval on the Sundry Notice Form 3160-5 within 90 days of this sundry's approval date.
- 28. Should "beneficial use" not be achieved submit for BLM approval a plan for P&A.

