

Submit 1 Copy To Appropriate District Office
District I - (575) 393-6161
1625 N. French Dr., Hobbs, NM 88240
District II - (575) 748-1283
811 S. First St., Artesia, NM 88210
District III - (505) 334-6178
1000 Rio Brazos Rd., Aztec, NM 87410
District IV - (505) 476-3460
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

Form C-103
Revised July 18, 2013

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		WELL API NO. 30-005-62161
1. Type of Well: Oil Well <input type="checkbox"/> Gas Well <input checked="" type="checkbox"/> Other		5. Indicate Type of Lease FEDERAL STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
2. Name of Operator State of New Mexico formerly McKay Oil Corp		6. State Oil & Gas Lease No.
3. Address of Operator 1625 N. French Drive Hobbs, NM 88240		7. Lease Name or Unit Agreement Name McKAY BERRENDO
4. Well Location Unit Letter I : 1920 feet from the SOUTH line and 660 feet from the EAST line Section 2 Township 10S Range 24E NMPM County CHAVES		8. Well Number 1Y
11. Elevation (Show whether DR, RKB, RT, GR, etc.)		9. OGRID Number 14424
		10. Pool name or Wildcat Pecos Slope; Abo, West (Gas)

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	P AND A <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	MULTIPLE COMPL <input type="checkbox"/>	CASING/CEMENT JOB <input type="checkbox"/>	
DOWNHOLE COMMINGLE <input type="checkbox"/>			
CLOSED-LOOP SYSTEM <input type="checkbox"/>			
OTHER: <input type="checkbox"/>		OTHER: <input type="checkbox"/>	

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

SEE ATTACHED PROCEDURE & SCHEMATICS

Spud Date:

Rig Release Date:

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

Mark Whitaker

TITLE Petroleum Engr. Specialist

DATE

10/19/2017

Type or print name Mark Whitaker

E-mail address: marka.whitaker@state.nm.us

PHONE: 575-393-6161

For State Use Only

APPROVED BY:

Maureen Brown

TITLE

AO/II

DATE

10/19/2017

Conditions of Approval (if any):

McKay Oil Corp
McKay Berrendo No. 1Y
30-005-62161
UL – I, Sec. 28, T8S, R22E
1920' FSL & 660' FEL

13 3/8" 48# @ 174' w/ 250 sx cmt
8 5/8" 24# @ 786' w/ 510 sx cmt
4 1/2" 10.5# @ 3622' w/ 650 sx cmt
Top Perforation 2472'

1. MIRU. POOH w/ production equipment.
2. Set CIBP at 2372'. Circulate hole with mud laden fluid. Pressure test casing to 500 psi. Spot 25 sx cement on CIBP.
3. Spot 25 sx at 836'. WOC & Tag.
4. POOH to 224'. Fill to surface w/ cmt.
5. Cut off wellhead 3' below ground level and verify cement to surface all strings.
6. Install below ground P&A marker. Photos should be taken prior to and after welding on plate. Record GPS reading. BLM should be notified prior to cut off so it can be witnessed.

NOTES: Mud laden fluid consists of fresh water with 25 sx salt gel per 100 bbls of fluid. If casing will not hold pressure, contact the OCD for instructions prior to proceeding with P&A.

CURRENT
30-005-62161

McKay Oil
McKay Berrendo #1Y



13 3/8" 48# @ 174' w/ 250 sx. Circ


8 5/8" 24# @ 786' w/ 510 sx. Circ.

Top Perf 2472'

4 1/2" 10.5# @ 3622' w/ 650 sx. Circ.

McKay Oil Corp
McKay Berrendo 1Y

PROPOSED
30-005-62161



13 3/8" 48# @ 174'

CUT OFF WELLHEAD 3' BELOW GL,
VERIFY CEMENT, & INSTALL BELOW GROUND
MARKER. TAKE PHOTO & GPS READINGS

SPOT 25 SX CMT FROM 224' TO SURFACE.

8 5/8" 24# @ 786'

SPOT 25 SX CMT AT 836'. WOC & TAG.

Top Perf 2472

**PRESSURE TEST CASING
CIRCULATE MUD LADEN FLUID**

4 1/2" 10.5# @ 3622'

SET CIBP AT 2372'. CAP WITH 25 SX