Office	State of New Me		Form C-103	
District I - (575) 393-6161	Energy, Minerals and Natu	ral Resources	Revised July 18, 2013	
1625 N. French Dr., Hobbs, NM 88240		20	API NO. 025-20176	
811 S. First St., Artesia, NM 88210	OIL CONSERVATION	DIVISION	cate Type of Lease	
District III - (505) 334-6178 1000 Rio Brazos Rd., Aztec, NM 87410 District IV - (505) 476-3460 1220 S. St. Francis Dr., Santa Fe, NM 87505 1220 South St. Francis Dr. Santa Fe, NM 87505 SUNDRY NOTICES AND REPORTS ON WELLS		ncis Dr.	STATE X FEE -	
District IV - (505) 476-3460	Santa Fe, NM 87	505 6. Stat	e Oil & Gas Lease No.	
1220 S. St. Francis Dr., Santa Fe, NM 87505	*10	BBS OCD 3	12477	
SUNDRI NUTICES AND REPORTS ON WELLS			se Name or Unit Agreement Name	
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR TUGBACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCIEDAD			/	
			O STATE I Number 7	
PROPOSALS.) 1. Type of Well: Oil Well Gas Well Other 2. Name of Operator		CEIVED 8. WEI		
Name of Operator CROSS TIMBERS ENERGY, LLC			RID Number 298299	
3. Address of Operator			10. Pool name or Wildcat	
400 W 7TH ST, FORT WORTH, TX 76102		2 VACU	VACUUM; ABO REEF	
4. Well Location				
Unit Letter A : 995 feet from the N line and 330 feet from the E line				
Section 12		inge 34E NMPM	County LEA	
11. Elevation (Show whether DR, RKB, RT, GR, etc.)				
	3983 GR			
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data				
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:				
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS.			☐ ALTERING CASING ☐ PNS.☐ P AND A ☐	
PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMENT JOB				
DOWNHOLE COMMINGLE				
CLOSED-LOOP SYSTEM				
OTHER: OPEN ADDITIONAL PAY				
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date				
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.				
1. Set CIBP @ 8320'				
2. Set 2nd CIBP @ 8312' on WL				
3. Perforate 8048-52', 8071-75', 8091-95', 8140-44', 8151-55', 8157-61', 8178-82', 8205-09', 8216-20', 8230-34', 8244-48',				
8251-55', 8259-63', 8266-70', 8286-90', 8290-94', 8302-06', 8307-11'. (90 Holes - 0.42" Dia, 1 SPF, 60° Phase)				
 Set Pkr @ 7993' and acidize perfs f/ 8048-8311' w/ 4500 gal 15% NEFE HCL 				
5. CIBP @ 8312' believed to have failed during acid job				
6. POH w/ Tbg and Pkr				
7. RIH w/ RBP @ 8281' and spot 10' sd on top of RBP				
8. Set Pkr @ 7901' and acidize perfs f/ 8048-8270' w/ 4,000 gal 15% NEFE HCL				
	2. 2. 2		,	
Spud Date: 03/05/1963	Rig Release Da	te: 04/07/1963		
I hereby certify that the information above is true and complete to the best of my knowledge and belief.				
SIGNATURE Mui by ach TITLE REGULATORY TECH DATE 10/18/17				
Type or print name CONNIE BLA	YLOCK E-mail address	chlaylock@mspartners.d	com PHONE: 817-334-7882	
For State Use Only	E-man addres	Thopartholo.	THORE. ST. 604 1662	
	3	Petroleum Engineer	inlantes	
APPROVED BY:				
Conditions of Approval (if any):				