HODE						
Submit 1 Copy To Appropriate District State of New Mexico						
Office District I – (575) 393-6161 Energy, Minerals and Natural Resources						
District II _ (575) 748-1283	WELL API NO. 30-025-41703					
811 S. First St., Artesia, NM 88210 OIL CONSERVATION DIVISION	5. Indicate Type of Lease					
District III – (505) 334-6178 1220 South St. Francis Dr. VED	STATE FEE x					
<u>District IV</u> – (505) 476-3460 Santa Fe, NM 8/505	6. State Oil & Gas Lease No.					
1220 S. St. Francis Dr., Santa Fe, NM 87505						
SUNDRY NOTICES AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name					
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH	Berry SWD					
PROPOSALS.)	8. Well Number 1					
1. Type of Well: Oil Well Gas Well Other x SWD						
2. Name of Operator	9. OGRID Number 160825					
BC Operating, Inc. 3. Address of Operator	10. Pool name or Wildcat					
P.O. Box 50820, Midland, Texas 79710	SWD; Cherry Canyon					
4. Well Location						
Unit Letter I : 1620 feet from the South line and 30	4 feet from the East line					
	NMPM Lea County					
11. Elevation (Show whether DR, RKB, RT, GR, etc.)						
	然是特殊的					
12. Check Appropriate Box to Indicate Nature of Notice,	Report or Other Data					
NOTICE OF INTENTION TO: SUB	SEQUENT REPORT OF:					
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WOR						
TEMPORARILY ABANDON						
PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMENT	T JOB					
DOWNHOLE COMMINGLE						
CLOSED-LOOP SYSTEM ☐ OTHER: ☐ STEP RATE TEST OTHER: ☐						
OTHER: STEP RATE TEST OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date						
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of						
proposed completion or recompletion.						
BC OPERATING, INC. RESPECTFULLY REQUESTS PERMISSION TO CONDUCT A STEP RATE TEST ON THE						
REFERENCED WELL (PROCEDURE AND WBD ATTACHED)						
, and the same of						
PROVIDE S.R.T. RESULTS						
TO SANTA FE OCD FOR						
Spud Date: APPROVAL						
I hereby certify that the information above is true and complete to the best of my knowledge	a and haliaf					
Thereby certify that the information above is true and complete to the best of my knowledge	e and bener.					
$C \cap A \cap A$						
SIGNATURE TITLE REGULATORY AT	NALYST DATE <u>2.16.2018</u>					
Type or print name SARAH PRESLEY E-mail address: SPRESLEY@BCOPERATING.COM PHONE: 432.684.9696						
Type or print name <u>SARAH PRESLEY</u> E-mail address: <u>SPRESLEY@BCOP</u> For State Use Only	EKATING.COM_ PHONE:432.684.9696					
APPROVED BY: Accepted for Record Only	DATE					
Conditions of Approval (if any): MSBrown 2/20/201	2					
The state of the s						

Berry SWD #1 1620' FSL 304' FEL, Section 35, T-20-S, R-34-E Lea County, New Mexico API# 30-025-41703

Step Rate Test

Well Data

Tubing:

4 1/2" 11.6# IPC EUE J55

Casing:

7" 26# J-55 LTC

TD:

7.062

PBTD: 7,018'

GL: 3,782'

KB: 13'

Procedure

- 1. Comply with all company and governmental safety regulations.
- 2. Prep well for injection test, shut in 48 hrs prior to test.
- 3. Set (8) 500 bbl frac tanks. Fill tanks with produced water.
- 4. Contact OCD, have a representative on location day of test.
- 5. Remove injection equipment. MIRU pump trucks.
- 6. MIRU slickline w downhole pressure bomb measurement tools.
- 7. Establish injection rate per schedule below. Maintain each step rate increase for a minimum of 30 minutes per step. Document pressure and rate when stable.

		Clean	Fluid	Fluid	Stage
Stage #	Fluid Type	Rate	Volume	Volume	Time
		BPM	GAL	BBL	Mins
1	Water	6	7560	180	30
2	Water	8	10080	240	30
3	Water	10	12600	300	30
4	Water	22	27720	660	30
5	Water	24	30240	720	30
6	Water	26	32760	780	30
		Total:	120960	2880	

- 8. RDMO slickline. RDMO pump trucks.
- 9. Hook up injection equipment, return well to injection.

Contacts


Bruce Madden	Production Foreman	432-894-0721
Nick Klopp	Operations Engineer	979-422-2510
Jason Wacker	Operations Manager	432-631-2142
Doug Swift	Geo-Tech	432-684-9696



BERRY SWD #1

API #30-025-41703 UNIT LETTER "I" 1539' FSL & 304' FEL SEC. 35, T20S, R34E LEA COUNTY, NEW MEXICO

CURRENT WELLBORE



PBTD: 7,062' **TD**: 7,018'