(DO NOT USE THIS FORM FOR PROP	FICES AND REPORTS ON WELLS	VISION Sp. OCD 5 05 2018	Form C-103 Revised August 1, 2011 WELL API NO. 30-025-06219 5. Indicate Type of Lease STATE FEE / 6. State Oil & Gas Lease No. 7. Lease Name or Unit Agreement Name Eumont Hardy Unit
DIFFERENT RESERVOIR. USE "APPL PROPOSALS.)	ICATION FOR PERMIT" (FORM C-101) FOR SU	JCH	
1. Type of Well: Oil Well			3. Well Number 021
2. Name of Operator			9. OGRID Number
Mar Oil and Gas Corporation 3. Address of Operator			151228 10. Pool name or Wildcat
	a Fe, NM 87502		Eumont; Yates, 7 Rivers, Queen
4. Well Location			
	660 feet from the South	ne and 1980	feet from the West line
Section 36	Township 20S	Range 37E	NMPM Lea County
	11. Elevation (Show whether DR, RKI		
		1	
NOTICE OF II PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING DOWNHOLE COMMINGLE OTHER: 13. Describe proposed or com of starting any proposed w proposed completion or re-	COMPL COMPL COMPL CAMPLET COMPL CAMPLET COMPL CAMPL CAMPLET COMPL CAMPLET COMPL CAMPLET COMPLET COMPLET COMPLET COMPLET COMPLET CAMPLET CAMPLE	SUBSE MEDIAL WORK OMMENCE DRILL SING/CEMENT JO HER: nent details, and g or Multiple Comp	INT TO PA PAN [] P&A NR P&A R give pertinent dates, including estimated date
Spud Date:	Rig Release Date:	Emy knowledge	and holiof
I hereby certify that the information above is true and complete to the best of my knowledge and belief.			
SIGNATURE Billy F.	Title Foreman		DATE 2/26/18
Type or print name Billy(Bill)E. Prichard E-mail address: billy@pwllc.net PHONE: 432-934-7680 For State Use Only APPROVED BY: Mah Wittah TITLE Petroleom Engris Specialist DATE 03/05/208 Conditions of Approval (if any):			

C103 INTENT TO P&A EXPIRES 03-05-2019

Mar Oil & Gas Corporation Eumont Hardy Unit # 21 API 30-025-06219 UL "N", Sec 36, T20S, R37E 660 FSL x 1980 FWL

Plugging Procedure

MIRUSU Pull rods and pump **NU BOP** Pull tubing Run and set CIBP at 3475' Tag CIBP Pressure test casing Spot 25 sx cmt Displace casing with gelled brine Perf at 2610' Squeeze w/ 35sx cmt x WOC Tag cmt plug at 2510' or above Perf at 1480' 1/300' Squeeze w/35sx cmt x WOC Tag cmt plug 1380 or above 1200 Perf 350' Squeeze w/ 35sx cmt x WOC Tag cmt plug x Circulate cement to surface Cut of well head Insure casing is full of cement Cut off Su anchors and install PA marker **Clean location** Prepare for release


Mar Oil & Gas Corporation

<u>Eumont Hardy Unit # 21</u> API # 3002506219

Unit Letter "N", Section 36, T20S, R37E

Lea County, New Mexico

660 FSL x 1980 FWL



Mar Oil & Gas Corporation

<u>Eumont Hardy Unit # 21</u> API # 3002506219

<u>Unit Letter "N", Section 36, T20S, R37E</u>

<u>Lea County, New Mexico</u>

660 FSL x 1980 FWL

