

Submit 1 Copy To Appropriate District Office

District I - (575) 393-6161
1625 N. French Dr., Hobbs, NM 88240
District II - (575) 748-1283
811 S. First St., Artesia, NM 88210
District III - (505) 334-6178
1000 Rio Brazos Rd., Aztec, NM 87410
District IV - (505) 476-3460
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico

Energy, Minerals and Natural Resources

Form C-103

Revised July 18, 2013

HOBBS OCD

APR 24 2018

RECEIVED

OIL CONSERVATION DIVISION

220 South St. Francis Dr.

Santa Fe, NM 87505

WELL API NO.

30-025-36993

5. Indicate Type of Lease

STATE ☒ FEE ☐

6. State Oil & Gas Lease No.

VO-6174

7. Lease Name or Unit Agreement Name

Peter Grande State

8. Well Number

1

9. OGRID Number

231429

10. Pool name or Wildcat

Mescalero, North SWD; SAN ANDRES

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: Oil Well ☒ Gas Well ☐ Other ☒ SWA

2. Name of Operator

Manzano, LLC

3. Address of Operator

P.O. Box 2107, Roswell NM 88202-2107

4. Well Location

Unit Letter M : 330 feet from the South line and 400 feet from the

West line

Section 1 Township 10S Range 32E NMPM County Lea

11. Elevation (Show whether DR, RKB, RT, GR, etc.)

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☒ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐
DOWNHOLE COMMINGLE ☐
CLOSED-LOOP SYSTEM ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ P AND A ☐
CASING/CEMENT JOB ☐
OTHER: ☐

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

- 1) Pull and inspect tubing, re-dress packer
- 2) Hydrotest tubing and replace as necessary
- 3) Run packer and tubing. Load casing-tubing annulus with packer fluid.
- 4) Set packer and pressure test casing to 500 psi. Chart and record pressures.

Condition of Approval: notify
OCD Hobbs office 24 hours
prior of running MIT Test & Chart

Spud Date:

Rig Release Date:

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

TITLE

N.P. Production

DATE 4/24/18

Type or print name: John B. Thompson

E-mail address: john@manzanoenergy.com

PHONE: 575-840-5797

For State Use Only

APPROVED BY:

Maury Brown

TITLE

AO/II

DATE

4/24/2018

Conditions of Approval (if any):

MB