UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

OCD Hobbs HOBES

FORM APPROVED OMB NO. 1004-0137

Expires: January 31, 2018

5. Lease Serial No. NMLC029405B

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use thi	NOTICES AND REPO is form for proposals to II. Use form 3160-3 (API	drill or to re-enter an WA D) for such proposals.	AY 08 20	NMLC02	Allottee or Tribe Name		
SUBMIT IN	TRIPLICATE - Other inst	ructions on page 2	CEIVE	1.0 If Unit or 892000	CA/Agreement, Name and/or No. 3410		
1. Type of Well ☑ Oil Well ☐ Gas Well ☐ Other					8. Well Name and No. MCA UNIT 269		
Name of Operator CONOCOPHILLIPS COMPANY COMPANY CONOCOPHILLIPS COMPANY CONDITION					9. API Well No. 30-025-23706-00-S1		
3a. Address 3b. Phone No. (include area code) Ph: 432-563-3355 MIDLAND, TX 79710 Fx: 432-563-3364					10. Field and Pool or Exploratory Area MALJAMAR		
4. Location of Well (Footage, Sec., T., R., M., or Survey Description)					or Parish, State		
Sec 20 T17S R32E SESE 125FSL 1295FEL					LEA COUNTY, NM		
12. CHECK THE AI	PPROPRIATE BOX(ES)	TO INDICATE NATURE C	F NOTICE,	REPORT,	OR OTHER DATA		
TYPE OF SUBMISSION		ТҮРЕ О	F ACTION				
Notice of Intent	☐ Acidize	□ Deepen	☐ Product	ion (Start/)			
	☐ Alter Casing	☐ Hydraulic Fracturing	☐ Reclama	ation	INT TO PARM		
☐ Subsequent Report	☐ Casing Repair	■ New Construction	☐ Recomp	lete	P&A NR		
☐ Final Abandonment Notice	☐ Change Plans	☑ Plug and Abandon	☐ Tempor	arily Abar	P&A R		
	☐ Convert to Injection	Plug Back	□ Water D	Disposal			
1. MIRU. ND WH, NU BOP. P 2. Set 5-1/2 CIBP @ 3650'. Ci 3. Perf & Sqz 40sx cmt @ 200 4. Perf & Sqz 100sx cmt @ 10 5. Perf @ 300'. POOH, ND B0 6. POOH. Top off well. RDMO	rc hole w/ MLF. Cap w/ 7 00' - 1880'. WOC-Tag 000' - 720'. WOC-Tag 0P. Circ 90sx cmt @ 300'	to surface					
Below around	level day	hole made	CO		CHED FOR NS OF APPROVAL		
14. I hereby certify that the foregoing is	Electronic Submission # For CONOCO	412696 verified by the BLM We PHILLIPS COMPANY, sent to processing by JIM AMOS on 05	Il Information				
Name (Printed/Typed) GREG BR	YANT	Title AGEN					
Signature (Electronic S	Submission)	Date 04/27/2	2018				
	THIS SPACE FO	R FEDERAL OR STATE	OFFICE U	SE			
Approved By James (P. limos	Title	sv. A	ET	5-2-18 Date		
Conditions of approval, if any, are attached artify that the applicant holds legal or equivalent would entitle the applicant to condu	itable title to those rights in the		Isbab				
Fitle 18 U.S.C. Section 1001 and Title 43 States any false, fictitious or fraudulent s			willfully to ma	ike to any depa	artment or agency of the United		

(Instructions on page 2) ** BLM REVISED ** BLM REVISED ** BLM REVISED ** BLM REVISED **





WELLBORE SKETCH ConocoPhillips Company -- Permian Basin Business Unit

					Dato 3/22/18
RKB@ 39	98"				
DF @ 39	98'		_		
GL @ 39	187	Subarea Lease & Well N	Buckeye	WCA Unit #269	
1				Sec 20. T-17S, R-32E	125' FSL - 1295' FEL
111	Surface	Legal Description County		State State	
	8-5/8", 20#/h	Field	MALJAM		Now Mexico
	Cmr'd w/ 400 SX	Date Spudded		3/4/71	
	TOC - Circ'd to surface	API Number	300252370		
'	1100 Care to surface	Partitulipe	300232370		
				Operator Nun	nber
	Production			Lease ID	
	5-1/2", 14#/ft			Field Number	
	Cmrd w/ 300 SX				
	TOC - 2700' Calc				
-					
	Grayburg				
	Re-Complete Perfs 3750', - 3782', (12/13/90)				
05	Squeezed Perfs -3752' - 3782' (7/31/73)				
=	=				
	Rods and pump detailed				
	on Tubing & Rods Tab				
1					
	San Andres				
=	=3856' - 3935'				
=	=				
=	=				
= =					
=	San Andres				
=	= 4002' · 4022'				
=	_				
$\equiv \Box$					
	=				
	11				
1250	PBTD @4115				
i to water.	TD @ 4130				

WELLBORE SKETCH ConocoPhillips Company -- Permian Basin Business Unit

			Date 3/22/18
RKB @ 3998'			
DF @ 3998'			
GL @ 3987	Subarea	Buckeye Vacuum ABO Unit	
	Lease & Well N	o MGA Unit #269	
P&S 90s x cmt @ 300 -4	Legal Description	1000	125 FSL 1295 FEL
			THE PLANT AND ADDRESS OF THE PARTY.
Surface (2/4	County	LEA State	New Mexico
18-5/8" 20#/tt, 770'	Field	MALJAMAR	
		3/4/71	
Cmt'd w/ 400 SX	Date Spudded		
TOC Circ'd to surface	API Number	3002523706	
P&S 100sx cmt @ 1000'.720' Tag			
P&S 40sx cmt @ 2000 -1880 Tag		Operator Num	ber
Production		Lease ID	
5-1/2" 14#/11 4136"		Field Number	
E completent vine to second description			
Cmt'd w' 300 SX			-77
1.00 - 2700 Calc		TGA	810
	21.	1/2011	0
treatment of	7 1/8		1905
Spot 70sx cmt @ 3650"-3000" Tag	118	1/ 1/	10-5-
Set CIBP @ 3650"		MICALE	1903
		the sail	
Grayburg			3062
Re-Complete Perfs 3750' - 3782' (12/13/90)			2063
差 Squeezed Perfs - 3752′ 3782′ (7/31/73)		Cu	204
Re-Complete Peris 3750 - 3782 (12/13/90) Squeezed Peris -3752* 3782* (7/31/73) Rods and pump detailed los Tubing & Rods Tat San Andres San Andres Sur Andres 4 v. 4822			
= =		68	
= =			3444
Rods and pump detailed		- 1	744
lon Tubing & Rods Tab			37//
Ton mond 9 Kods 185			
- -			
— San Andres			
= = 3856 3935			
		SA	2020
		3/7	3820
		, , , ,	
and the same			, 3964
		(OVing Tor	, 0 16
= = Sar Andres			
= =			
記載 開 PBTD 選4115			
10 3 4130			
112 2 4100			

BUREAU OF LAND MANAGEMENT Carlsbad Field Office 620 East Greene Street Carlsbad, New Mexico 88220 575-234-5972

Permanent Abandonment of Federal Wells Conditions of Approval (LPC Habitat)

Failure to comply with the following Conditions of Approval may result in a Notice of Incidents of Noncompliance (INC) in accordance with 43 CFR 3163.1.

1. Plugging operations shall commence within <u>ninety (90)</u> days from the approval date of this Notice of Intent to Abandon.

If you are unable to plug the well by the 90th day provide this office, prior to the 90th day, with the reason for not meeting the deadline and a date when we can expect the well to be plugged. Failure to do so will result in enforcement action.

The rig used for the plugging procedure cannot be released and moved off without the prior approval of the authorized officer. Failure to do so may result in enforcement action.

- 2. <u>Notification:</u> Contact the appropriate BLM office at least 24 hours prior to the commencing of any plugging operations. For wells in Chaves and Roosevelt County, call 575-627-0272; Eddy County, call 575-361-2822; Lea County, call 575-393-3612.
- 3. <u>Blowout Preventers</u>: A blowout preventer (BOP), as appropriate, shall be installed before commencing any plugging operation. The BOP must be installed and maintained as per API and manufacturer recommendations. The minimum BOP requirement is a 2M system for a well not deeper than 9,090 feet; a 3M system for a well not deeper than 13,636 feet; and a 5M system for a well not deeper than 22,727 feet.
- 4. <u>Mud Requirement:</u> Mud shall be placed between all plugs. Minimum consistency of plugging mud shall be obtained by mixing at the rate of 25 sacks (50 pounds each) of gel per 100 barrels of brine water. Minimum nine (9) pounds per gallon.
- 5. <u>Cement Requirement</u>: Sufficient cement shall be used to bring any required plug to the specified depth and length. Any given cement volumes on the proposed plugging procedure are merely estimates and are not final. Unless specific approval is received, no plug except the surface plug shall be less than 25 sacks of cement. Any plug that requires a tag will have a minimum WOC time of 4 hours.

In lieu of a cement plug across perforations in a cased hole (not for any other plugs), a bridge plug set within 50 feet to 100 feet above the perforations shall be capped with 25 sacks of cement. If a bailer is used to cap this plug, 35 feet of cement shall be sufficient. Before pumping or bailing cement on top of CIBP, tag will be required to verify depth. Based on depth, a tag of the cement may be deemed necessary.

Unless otherwise specified in the approved procedure, the cement plug shall consist of either Neat Class "C", for up to 7,500 feet of depth or Neat Class "H", for deeper than 7,500 feet plugs.

6. Below Ground Level Cap (Lesser Prairie-Chicken Habitat): All casing shall be cut-off at the base of the cellar or 3 feet below final restored ground level (whichever is deeper). The BLM is to be notified a minimum of 4 hours prior to the wellhead being cut off to verify that cement is to surface in the casing and all annuluses. Wellhead cut off shall commence within ten (10) calendar days of the well being plugged. If the cut off cannot be done by the 10th day, the BLM is to be contacted with justification to receive an extension for completing the cut off. Upon the plugging and subsequent abandonment of wells that are located in lesser prairie-chicken habitat, the casings shall be cut-off at the base of the cellar or 3 feet below final restored ground level (whichever is deeper). The well bore shall then be covered with a metal plate at least ¼ inch thick and welded in place. A weep hole shall be left in the plate and/or casing.

NMOCD also requires the operator to notify NMOCD when this type of dry hole marker is used. This can be done on the subsequent report of abandonment which is submitted to the BLM after the well is plugged. State that a below ground cap was installed as required in the COA's from the BLM.

- 7. <u>Subsequent Plugging Reporting:</u> Within 30 days after plugging work is completed, file one original and three copies of the Subsequent Report of Abandonment, Form 3160-5 to BLM. The report should give in detail the manner in which the plugging work was carried out, the extent (by depths) of cement plugs placed, and the size and location (by depths) of casing left in the well. Show date well was plugged.
- 8. <u>Trash:</u> All trash, junk and other waste material shall be contained in trash cages or bins to prevent scattering and will be removed and deposited in an approved sanitary landfill. Burial on site is not permitted.

Following the submission and approval of the Subsequent Report of Abandonment, surface restoration will be required. See attached reclamation objectives.

<u>Timing Limitation Stipulation/ Condition of Approval for Lesser Prairie-Chicken:</u>
From March 1st through June 15th annually, abandonment activities will be allowed except between the hours from 3:00 am and 9:00 am. Normal vehicle use on existing roads will not be restricted