

Submit 1 Copy To Appropriate District Office

District I – (575) 393-6161
1625 N. French Dr., Hobbs, NM 88240
District II – (575) 748-1283
811 S. First St., Artesia, NM 88210
District III – (505) 334-6178
1000 Rio Brazos Rd., Aztec, NM 87410
District IV – (505) 476-3460
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico

Energy, Minerals and Natural Resources

HOBBS OGD

OIL CONSERVATION DIVISION

JUL 02 2018 20 South St. Francis Dr.

Santa Fe, NM 87505

RECEIVED

Form C-103

Revised August 1, 2011

WELL API NO. 30-025-28976
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No. N/A
7. Lease Name or Unit Agreement Name South Hobbs (G/SA) Unit
8. Well Number 178
9. OGRID Number: 157984
10. Pool name or Wildcat: Hobbs (G/SA)

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: Oil Well <input type="checkbox"/> Gas Well <input type="checkbox"/> Other Temporarily Abandoned <input checked="" type="checkbox"/>	
2. Name of Operator Occidental Permian Ltd.	
3. Address of Operator P.O. Box 4294, Houston, Tx 77210	
4. Well Location (Surface) Unit Letter <u>C</u> : <u>862</u> feet from the <u>North</u> line and <u>1745</u> feet from the <u>West</u> line Section <u>5</u> Township <u>19S</u> Range <u>38E</u> NMPM Lea County	
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3640' (KB)	

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐
DOWNHOLE COMMINGLE ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ P AND A ☐
CASING/CEMENT JOB ☐

OTHER: ☒ RTP well in San Andres formation

OTHER: ☐

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

- 1) MIRU PU. ND Wellhead. NU BOP.
- 2) Cleanout well to current TD
- 3) Selectively perforate San Andres
- 4) Design stimulation based on new pay. Stim with 15% HCL at ± 50 gal/ft
- 5) Set RBP at $\pm 3900'$ and $\pm 1000'$ and prepare well for wellhead change

Following wellhead change:

- 6) MIRU PU; Pull plugs
- 7) RIH with ESP
- 8) ND BOP. NU Wellhead. RDMO PU. RTP Well

During this procedure we plan to use the closed-loop system with a steel tank and haul contents to the required disposal per ODC Rule 19.15.17

Spud Date:

Rig Release Date:

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Jacob A Cox TITLE Production Engineer DATE 07/02/2018

Type or print name Jacob S. Cox E-mail address: Jacob_Cox@oxy.com PHONE: 713-497-2053

For State Use Only

APPROVED BY: Mary Brown TITLE AO/I DATE 7/2/2018

Conditions of Approval (if any):

MB