

Submit 1 Copy To Appropriate District
Office
District I - (575) 393-6161
1625 N. French Dr., Hobbs, NM 88240
District II - (575) 748-1283
811 S. First St., Artesia, NM 88210
District III - (505) 334-6178
1000 Rio Brazos Rd., Aztec, NM 87410
District IV - (505) 476-3460
1220 S. St. Francis Dr., Santa Fe, NM
87505

State of New Mexico
Energy, Minerals and Natural Resources

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-103
Revised August 1, 2011

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		WELL API NO. 30-015-00940
1. Type of Well: Oil Well <input checked="" type="checkbox"/> Gas Well <input type="checkbox"/> Other <input type="checkbox"/>		5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
2. Name of Operator State of New Mexico formerly Canyon E&P Company		6. State Oil & Gas Lease No.
3. Address of Operator 1625 N. French Drive Hobbs, NM 88240		7. Lease Name or Unit Agreement Name Artesia Metex Unit
4. Well Location Unit Letter <u>B</u> : <u>990</u> feet from the <u>North</u> line and <u>2310</u> feet from the <u>East</u> line Section <u>24</u> Township <u>18S</u> Range <u>27E</u> NMPM <u>Eddy</u> County		8. Well Number 001
11. Elevation (Show whether DR, RKB, RT, GR, etc.)		9. OGRID Number 269864
		10. Pool name or Wildcat Artesia; QU-GB-SA

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐
DOWNHOLE COMMINGLE ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ P AND A ☒ XX
CASING/CEMENT JOB ☐

OTHER: ☐

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

HOBBS OCD

JUL 10 2018

SEE ATTACHED

RECEIVED

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE _____ TITLE _____ DATE _____

Type or print name _____ E-mail address: _____ PHONE: _____

For State Use Only

APPROVED BY: Mark Whitaker TITLE PES DATE 07/10/2018


Conditions of Approval (if any):

Plugging Report
Artesia Metex Unit #1
30-015-00940

3/28/2018 Clear location. Move in and rig up. Nipple down wellhead. Unseated pump and laid down 79 5/8" rods and the pump. While installing the tubing sub to pull the tubing off of the wellhead, the casing subsided. Tubing was stuck. Worked tubing free and POOH with 63 joints of 2 3/8" tubing. Secured the wellhead as good as conditions would allow. Will attempt to repair wellhead in the morning and install the BOP. SION

3/29/2018 Dug out around wellhead. Removed bad wellhead from 8 5/8" casing and welded on a replacement tubing head. Moved in remaining equipment and RIH with tubing to 1512'. Attempted circulation. Strong blow to pit until static after 30 bbls. Spotted 50 sx cement at 1512' with CaCl and LCM. POOH and WOC. No tag at 1512'. Spotted another 50 sx with CaCl and LCM at 1512'. POOH and SION.

3/30/2018 Tagged cement at 1343'. Pumped MLF. No circulation to surface. Dumped 6 yards of gravel. RIH with tubing and tagged at 520'. Still could not circulate. POOH with tubing and dumped another 4 yards gravel. RIH and tagged at 435'. Established circulation and circulated cement to surface from 435' with 115 sx. Laid down remaining pipe and SION.

 Rigged down and cut off wellhead. Filled up 8 5/8" casing with 20 sx cement. Installed marker and cut off anchors. Cleaned the pit and cleared the location.