Submit 1 Copy To Appropriate District	State of New Mexico	Form C-103				
Office District I – (575) 393-6161	Energy, Minerals and Natural Resources	Revised July 18, 2013				
1625 N. French Dr. Hobbs NM 88240		WELL API NO.				
<u>District II</u> - (575) 748-1283	CONSERVATION DIVISION	30-025-41551				
811 S. First St., Artesia, NM 88210	CONSERVATION DIVISION	5. Indicate Type of Lease				
District III – (505) 334-6178	COIL CONSERVATION DIVISION 1220 South St. Francis Dr. Santa Fe, NM 87505	STATE FEE X				
District IV - (505) 476-3460	Santa Fe, NM 87505	6. State Oil & Gas Lease No.				
1220 S. St. Francis Dr., Santa Fe, NM						
87505						
SUNDRY NOTICE	ES A TOMEPORTS ON WELLS TO DRILL OR TO DEEPEN OR PLUG BACK TO A NON FOR PERMIT" (FORM C-101) FOR SUCH	7. Lease Name or Unit Agreement Name				
(DO NOT USE THIS FORM FOR PROPOSA	DRILL OR TO DEEPEN OR PLUG BACK TO A	North Hobbs G/SA Unit				
DIFFERENT RESERVOIR. USE "APPLICA"	MON FOR PERMIT" (FORM C-101) FOR SUCH	North Hobbs G/SA Unit 2				
PROPOSALS.)	as Well 🗍 Other	8. Well Number 947				
<u></u>	as Well Other					
2. Name of Operator		9. OGRID Number				
Occidental Permian LTD		157984				
Address of Operator		10. Pool name or Wildcat				
PO Box 4294 Houston, TX 77210		Hobbs; Grayburg - San Andres				
4. Well Location	· · · · · · · · · · · · · · · · · · ·					
Unit Letter A :	278feet from theN line and	1123 feet from the E line				
Section 19	Township 18S Range 38E	NMPM County Lea				
11. Elevation (Show whether DR, RKB, RT, GR, etc.)						
	3678' KB					
12. Check Ap	propriate Box to Indicate Nature of Notice,	, Report or Other Data				
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:						

TEMPORARILY ABANDON PULL OR ALTER CASING		CHANGE PLANS MULTIPLE COMPL		COMMENCE DRILLING OPNS	P AND A	Ō
DOWNHOLE COMMINGLE						
CLOSED-LOOP SYSTEM						
OTHER:				OTHER:		
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date						

 Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

MIRU x NDWH x NUBOP. POOH 130 jts tbg x ESP equipment. RIH 6 1/8" bit x tagged PBTD @ 4620'.

RIH 7" RBP @ 4300' x ran USIT log from 4300' to surface. POOH RBP x shot new perfs @ 4462' to 4468' w/ total of 28 holes. Ran acid job # 1- perfs 4544'-4572' pumped 900 gals acid x 472 gals SCW261 x flushed w/ 32 gals BW. #2 -perfs 4487'-4530' pumped 1350 gals acid x 716 gals SCW261 x flushed w/ 32 bblsBW. #3- perfs 4462'-4468' pumped 500 gals acid x 114 gals SCW261 x flushed w/ 32bbls BW. #4- perfs 4403'-4447' pumped 1350 gals acid 733gals SWC261 x flushed w/ 32 bbls BW. #5- perfs 4339'-4365' pumped 800gals acid 440gals SCW261 x flushed w/ 32 bbls BW. RIH w/ 130 jts tbg @ 4287 ESP @ 4307'. RD x NDBOP x NUWH.

Spud Date:	05/09/2018	Rig Release Date:	05/15/2018]
I hereby certify	that the information above is true	and complete to the best of my k	nowledge and belief.	
SIGNATURE	Legit X at	TITLE Regulatory Spo	ecialistDAT	E06/14/2018
Type or print n	ameApril Hood	E-mail address:	lood@Oxy.com PHO	NE: 713-366-5771
For State Use	<u>Only</u>	۸.		
	Dates of work performed ated when reporting. Am mit.		Ngrdate	<u>- 7-5-18</u>