Form 3160-5 (June 2015)

UNITED STATES DEPARTMENT OF THE ATTERIOR DATE BUREAU OF LAND MAN GREEN DATE FOR THE BUREAU OF LAND MAN GREEN DATE OF THE BUREAU OF TH

FORM APPROVED OMB NO. 1004-0137 Expires: January 31, 2018

SUNDRY NOTICES AND REPORTS ON WELLS HOUDS

Do not use this form for proposals to drill or to re-enter air abandoned well. Use form 3160-3 (APD) for such proposals.

. Lease Serial No. NMLC058699

6. If Indian, Allottee or Tribe Name

SUBMIT IN TRIPLICATE - Other instructions on page 2					7. If Unit or CA/Agreement, Name and/or No. 8920003410		
Type of Well					8. Well Name and No. MCA UNIT 273		
Name of Operator Contact: RHONDA ROGERS CONOCOPHILLIPS COMPANY E-Mail: rogers@conocophillips.com					9. API Well No. 30-025-23730-00)-S1	
			o. (include area code) 10. Field 88-9174 MAL		10. Field and Pool or E MALJAMAR	Field and Pool or Exploratory Area MALJAMAR	
MIDLAND, TX 79710				· · · · · · · · · · · · · · · · · · ·			
4. Location of Well (Footage, Sec., T.			11. County or Parish, State				
Sec 26 T17S R32E NWSW 19				LEA COUNTY, NM			
12. CHECK THE APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA							
TYPE OF SUBMISSION	TYPE OF ACTION						
Notice of Intent ■ Notice of Intent Notice of Inten	☐ Acidize	☐ Dee	pen	☐ Product	ion (Start/Resume)	☐ Water Shut-C	Off
	☐ Alter Casing	☐ Hyd	raulic Fracturing	☐ Reclam	ation	☑ Well Integrit	у
☐ Subsequent Report	□ Casing Repair	□ New	Construction	☐ Recomp	olete	Other	
☐ Final Abandonment Notice	□ Change Plans	Plug	and Abandon	☐ Tempor	arily Abandon		
	Convert to Injection	Plug	Back	☐ Water I	Disposal		
CONOCOPHILLIPS COMPAN REPAIR PER ATTACHED PR ATTACHED IS A CURRENT/F	OCEDURES.			.L. WE WC	JUL 1 9 20 RECEIV	18	
14. I hereby certify that the foregoing is			·				
Electronic Submission #409614 verified by the BLM Well Information System For CONOCOPHILLIPS COMPANY, sent to the Hobbs Committed to AFMSS for processing by PRISCILLA PEREZ on 06/29/2018 (18PP1361SE)							
Name (Printed/Typed) RHONDA ROGERS					ORY TECHNICIAN		
Signature (Electronic S	ubmission)	_	Date 03/28/26	018			
THIS SPACE FOR FEDERAL OR STATE OFFICE USE							
/s/	Jonathon Shepa	rd				MINI O O	2040
Approved By		L	Petrole	um Ei	ngineer -	JUNte 29	2018
Conditions of approval, if any, are attached certify that the applicant holds legal or equivalent would entitle the applicant to condu	itable title to those rights in the		Carlsba		d Office		
Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.							

MCA 273 API #30-025-23730 FAILED BH TEST ISOLATE AND REPAIR

Project Scope

Justification and Background:

The MCA 273W has failed Braden head testing in February 2018 and is currently shut in. This procedure calls for determining and isolating the source of the leak. If economic, the leak will be repaired and a new MIT/BHT will be performed. Otherwise, the well will be prepared for abandonment.

Perforations	nas and the second second					
Type	Formation	Тор	Bottom			
Perforations	Grayburg/SA	4040'	4246'			
PBTD	4188' (Junk In Hole: Possibly old injection packer)					
TD	4260'					

PROCEDURE:

- 1) MIRU well service unit. Kill well if necessary.
- 2) Install Class 1 Hydraulic BOP. Function test BOPE.
- 3) Pull tension on packer and attempt to load and test backside.
 - a. If casing holds pressure, ND BOPE, NU wellhead, and contact Prod. Spec. to perform MIT.
 - b. If casing does not hold, proceed to next step.
- 4) Unlatch packer. Pick up 1 joint and reset packer.
- 5) Attempt to load and test backside.
 - a. If casing holds pressure, ND BOPE, NU wellhead, and contact Prod. Spec. to perform MIT.
 - b. If casing does not hold, proceed to next step.
- 6) Unlatch packer and scan tubing OOH standing back.
- 7) Visually inspect IPC coating while TOOH. Call PE after 5 double stands to discuss results and potentially laydown tubing. Inspect packer and send in for servicing if needed.
- 8) RU hydro-testers & RIH w/ new or redressed inj pkr, hydro testing tbg to 5000 psi. Set packer at original depth (3960'). Packer must be within 100' of top perf.
- 9) RU pump truck. Load backside and test pkr to 550 psi surface pressure. If pkr holds then proceed.
- 10) RU pump truck. Circulate packer fluid to surface.
- 11) ND BOPE, NU wellhead.
- 12) RU chart recorder w/ 1,000 psi chart to casing. Pressure test backside to 500 psi for 35 mins.

MCA 273 API #30-025-23730 **FAILED BH TEST** ISOLATE AND REPAIR

- a. Notify the NMOCD of impending test.
 b. If test fails, notify Production Eng. for possible job scope change.
 c. Do not look for casing leak without approval.

13) RDMO well service unit.

Proposed Rod and Tubing Configuration MCA 273

