Submit 3 Copies To Appropriate District Office Energy, Minerals and Natural Resources		Form C-103 October 25, 2007
District I 1625 N. French Dr., Hobbs, NM 87240		WELL API NO.
District II 1301 W Grand Ave. Artesia NM 88210 OIL CONSERVATION DIVISION		30-041-20449 5. Indicate Type of Lease
District III 1220 South St. Francis Dr.		STATE FEE XX
District IV		6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM 87505		23845
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR PROPOSALS.)		7. Lease Name or Unit Agreement Name: Lambirth
1. Type of Well: X Oil Well Gas Well Other	IG 0 1 2018	8. Well Number
2. Name of Operator	JG 11 1 2010	9, OGRID Number
	-OENED	162928
3. Address of Operator	ECEIVED	10. Pool name or Wildcat
3510 N. "A" St., Bldgs, A & B, Midland, TX 79705		Peterson, Fusselman, South
4. Well Location Unit Letter K : 1980 feet from the SOUTH line and 1980 feet from the WEST line		
Section 31 Township 5S Range 33E	NMPM	County Roosevelt
11. Elevation (Show whether DR, RKB, RT, GR, etc.)		
GR: 4414 GR		
12. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data		
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:		
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING		
TEMPORARILY ABANDON		
PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMENT JOB		
1		
OTHER:	Location is read	ly for OCD Inspection after P&A
All pits have been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan.		
Rat hole and cellar have been filled and leveled. Cathodic protection holes have been properly abandoned.		
A steel marker at least 4" in diameter and at least 4' above ground level has been set in concrete. It shows the		
OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, QUARTER/QUARTER LOCATION OR UNIT LETTER, SECTION, TOWNSHIP, AND RANGE. All INFORMATION HAS BEEN WELDED OR PERMANENTLY STAMPED ON THE MARKER'S SURFACE.		
The location has been leveled as nearly as possible to original ground contour and has been cleared of all junk, trash, flow lines and		
other production equipment.		
Anchors, dead men, tie downs and risers have been cut off at least two feet below ground level.		
If this is a one-well lease or last remaining well on lease, the battery and pit location(s) have been remediated in compliance with		
OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, production equipment and junk have been removed		
from lease and well location.		
All metal bolts and other materials have been removed. Portable bases have been removed. (Poured onsite concrete bases do not have to be removed.)		
All other environmental concerns have been addressed as per OCD rules.		
Pipelines and flow lines have been abandoned in accordance with 19.15.9.714.B(4)(b) NMAC. All fluids have been removed from		
non-retrieved flow lines and pipelines.		
When all work has been completed, return this form to the appropriate District office to schedule an inspection. If more than one		
inspection has to be made to a P&A location because it does not meet the criteria above, a penalty may be assessed.		
SIGNATURE Tommy York TITLE Sr. Prod. Super: Intendent DATE 7-31-18		
TITLE Sr. Prod. Super: Intendent DATE 7-3/-18 TYPE OR PRINT NAME Tamony York E-MAILTOMMY. 432-209-2483		
For State Lies Only		
APPROVED BY Kerry Fortner TITLE Compliance Office ATE 8-2-18		
Conditions of Approval, if any:		10