UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

OCD Hobbs

FORM APPROVED OMB NO. 1004-0137 Expires: January 31, 2018

5. Lease Serial No.
NMNM69377
6. If indian, Allottee or Tribe Name

BUREAU OF LAND MANAGEMENT	IL B 🚗 🕳
SUNDRY NOTICES AND REPORTS ON WELLS	HOBBS
Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such proposals.	Auc

AUG OF

SUBMIT IN	TRIPLICATE - Other inst	tructions on	page 2	O, If Un	it or CA/Agreement	, Name and/or No.	
1. Type of Well				CEIVE DWell I	Name and No.		
☑ Oil Well ☐ Gas Well ☐ Ot							
2. Name of Operator OXY USA INCORPORATED	Contact: E-Mail: david_stev	DAVID STEV vart@oxy.com	VART		Well No. 125-36009-00-S1		
3a. Address P O BOX 4294 HOUSTON, TX 77210-4294		3b. Phone No. (include area code) Ph: 432-685-5717			10. Field and Pool or Exploratory Area W RED TANK		
4. Location of Well (Footage, Sec., 7	., R., M., or Survey Description)		11. Cou	nty or Parish, State		
Sec 28 T22S R32E SWSE 33	0FSL 2310FEL			LEA	COUNTY, NM		
12. CHECK THE A	PPROPRIATE BOX(ES)	TO INDICA	TE NATURE OI	F NOTICE, REPOR	T, OR OTHER	DATA	
TYPE OF SUBMISSION	TYPE OF ACTION						
☑ Notice of Intent☐ Subsequent Report☐ Final Abandonment Notice	☐ Acidize ☐ Alter Casing ☐ Casing Repair ☐ Change Plans ☐ Convert to Injection		pen raulic Fracturing Construction and Abandon Back	☐ Production (Sta☐ Reclamation☐ Recomplete☐ Temporarily A☐ Water Disposal	INT TO PAPM P&A NR P&A R		
13. Describe Proposed or Completed Op If the proposal is to deepen direction Attach the Bond under which the wo following completion of the involvet testing has been completed. Final A determined that the site is ready for the TD-8680' PBTD-8645' P 13-3/8" 54.5# csg @ 805' w/ 9 8-5/8" 32# csg @ 4486' w/ 17 5-1/2" 17# csg @ 8680' w/ 70 *Perf @ 7870', 5490' sqz tota 1. RIH & set CIBP @ 8430', 12. M&P 25sx cmt @ 7920-77 3. M&P 25sx cmt @ 6815-66 4. M&P 25sx cmt @ 5540-53 5. M&P 35sx cmt @ 4702-44	ally or recomplete horizontally, rk will be performed or provide to operations. If the operation re bandonment Notices must be fil inal inspection. Perfs-4636-4652', 8480-85', 8455x, 17-1/2" hole, TOC-10sx, 11" hole, TOC-Surfosx, 7-7/8" hole, *TOC-79 in 1650sx cmt, TOC-2425'-W&P 25sx cmt to 8255' 45' WOC-Tag 40' WOC-Tag 65' WOC-Tag 36' WOC-Tag	give subsurface the Bond No. o sults in a multip ed only after all 28' Surf-Circ -Circ -Circ 910'-CBL	locations and measure in file with BLM/BIA te completion or reco	red and true vertical dept Required subsequent rimpletion in a new interving reclamation, have been seen as SEE ATT	hs of all pertinent me eports must be filed al, a Form 3160-4 m	arkers and zones. within 30 days sust be filed once e operator has	
Cor	# Electronic Submission For OXY US nmitted to AFMSS for proc	A INCORPOR	ATÉD, sent to the SCILLA PEREZ or	Hobbs 1 06/18/2018 (18PP12	85SE)		
Name (Printed/Typed) DAVID S	TEWART		Title SR. REC	GULATORY ADVIS	OR	·	
Signature (Electronic	Submission)		Date 06/18/20	018			
	THIS SPACE FO	OR FEDERA	L OR STATE	OFFICE USE			
Approved By Conditions of approval, if any, are attached	d. Approval of this notice does	not warrant or	Title	apr. 167	,	Date 8-1-18	
certify that the applicant holds legal or eq which would entitle the applicant to cond	uitable title to those rights in the	subject lease	Office	arlabad			
Title 18 U.S.C. Section 1001 and Title 43 States any false, fictitious or fraudulent			erson knowingly and	willfully to make to any	department or agend	cy of the United	

Additional data for EC transaction #424470 that would not fit on the form

32. Additional remarks, continued

6. Perf @ 2710' sqz 40sx cmt to 2580' WOC-Tag Add Alug (T/saft) ferf @ 1114', SDZ. cmt. to 7. Perf @ 855' sqz 35sx cmt to 745' WOC-Tag
8. Perf @ 250' sqz 80sx cmt to Surface
10# MLF between plugs - Above ground steel tanks will be utilized

Can Combine.

17-1/2" hole @ 805' 13-3/8" csg @ 805' w/ 945sx-TOC-Surf-Circ 4

Rustler 989 +1-7/salt 1064 +1-B/salt 4528 +1-

21.

Be15 4629 Cherry SS18 Brushy 6762

\$5 8579

11" hole @ 4486' 8-5/8" csg @ 4486' w/ 1710sx-TOC-Surf-Circ

Perfs @ 4636-4652

*Perf @ 5490', sqz 790sx cmt-TOC-2425'-CBL

7-7/8" hole @ 8680'. 5-1/2" csg @ 8680' w/ 700sx-*TOC-7910'-CBL

*Perf @ 7870', sqz 860sx cmt-TOC-5510'-CBL *

Perfs @ 8480-8528'

PB-8645'

TD-8680'

OXY USA Inc. - Proposed Red Tank 28 Federal #4 API No. 30-025-36009 17-1/2" hole @ 805' 80sx @ 250'-Surface Perf @ 250' 13-3/8" csg @ 805' w/ 945sx-TOC-Surf-Circ 35sx @ 855-745' WOC-Tag Perf @ 855' 40sx @ 2710-2580' WOC-Tag Perf @ 2710' 11" hole @ 4486' 8-5/8" csg @ 4486' 35sx @ 4702-4436' WOC-Tag w/ 1710sx-TOC-Surf-Circ Perfs @ 4636-4652' 25sx @ 5540-5365' WOC-Tag *Perf @ 5490', sqz 790sx cmt-TOC-2425'-CBL 25sx @ 6815-6640' WOC-Tag 7-7/8" hole @ 8680' 5-1/2" csg @ 8680' w/ 700sx-*TOC-7910'-CBL 25sx @ 7920-7745' WOC-Tag *Perf @ 7870', sqz 860sx cmt-TOC-5510'-CBL

Perfs @ 8480-8528'

CIBP @ 8430' w/ 25sx to 8255'

PB-8645'

BUREAU OF LAND MANAGEMENT Carlsbad Field Office 620 East Greene Street Carlsbad, New Mexico 88220 575-234-5972

Permanent Abandonment of Federal Wells Conditions of Approval

Failure to comply with the following Conditions of Approval may result in a Notice of Incidents of Noncompliance (INC) in accordance with 43 CFR 3163.1.

1. Plugging operations shall commence within <u>ninety (90)</u> days from the approval date of this Notice of Intent to Abandon.

If you are unable to plug the well by the 90th day provide this office, prior to the 90th day, with the reason for not meeting the deadline and a date when we can expect the well to be plugged. Failure to do so will result in enforcement action.

The rig used for the plugging procedure cannot be released and moved off without the prior approval of the authorized officer. Failure to do so may result in enforcement action.

- 2. <u>Notification:</u> Contact the appropriate BLM office at least 24 hours prior to the commencing of any plugging operations. For wells in Chaves and Roosevelt County, call 575-627-0272; Eddy County, call 575-361-2822; Lea County, call 575-393-3612.
- 3. <u>Blowout Preventers</u>: A blowout preventer (BOP), as appropriate, shall be installed before commencing any plugging operation. The BOP must be installed and maintained as per API and manufacturer recommendations. The minimum BOP requirement is a 2M system for a well not deeper than 9,090 feet; a 3M system for a well not deeper than 13,636 feet; and a 5M system for a well not deeper than 22,727 feet.
- 4. <u>Mud Requirement:</u> Mud shall be placed between all plugs. Minimum consistency of plugging mud shall be obtained by mixing at the rate of 25 sacks (50 pounds each) of gel per 100 barrels of **brine** water. Minimum nine (9) pounds per gallon.
- 5. <u>Cement Requirement</u>: Sufficient cement shall be used to bring any required plug to the specified depth and length. Any given cement volumes on the proposed plugging procedure are merely estimates and are not final. Unless specific approval is received, no plug except the surface plug shall be less than 25 sacks of cement. Any plug that requires a tag will have a minimum WOC time of 4 hours.

In lieu of a cement plug across perforations in a cased hole (not for any other plugs), a bridge plug set within 50 feet to 100 feet above the perforations shall be capped with 25 sacks of cement. If a bailer is used to cap this plug, 35 feet of cement shall be sufficient. Before pumping or bailing cement on top of CIBP, tag will be required to verify depth. Based on depth, a tag of the cement may be deemed necessary.

Unless otherwise specified in the approved procedure, the cement plug shall consist of either Neat Class "C", for up to 7,500 feet of depth or Neat Class "H", for deeper than 7,500 feet plugs.

6. <u>Dry Hole Marker</u>: All casing shall be cut-off at the base of the cellar or 3 feet below final restored ground level (whichever is deeper). The BLM is to be notified a minimum of 4 hours prior to the wellhead being cut off to verify that cement is to surface in the casing and all annuluses. Wellhead cut off shall commence within ten (10) calendar days of the well being plugged. If the cut off cannot be done by the 10th day, the BLM is to be contacted with justification to receive an extension for completing the cut off.

The well bore shall then be capped with a 4-inch pipe, 10-feet in length, 4 feet above ground and embedded in cement, unless otherwise noted in COA (requirements will be attached). The following information shall be permanently inscribed on the dry hole marker: well name and number, name of the operator, lease serial number, surveyed location (quarter-quarter section, section, township and range or other authorized survey designation acceptable to the authorized officer such as metes and bounds).

- 7. <u>Subsequent Plugging Reporting</u>: Within 30 days after plugging work is completed, file one original and three copies of the Subsequent Report of Abandonment, Form 3160-5 to BLM. The report should give in detail the manner in which the plugging work was carried out, the extent (by depths) of cement plugs placed, and the size and location (by depths) of casing left in the well. **Show date well was plugged.**
- 8. <u>Trash:</u> All trash, junk and other waste material shall be contained in trash cages or bins to prevent scattering and will be removed and deposited in an approved sanitary landfill. Burial on site is not permitted.

Following the submission and approval of the Subsequent Report of Abandonment, surface restoration will be required. See attached reclamation objectives.