Submit 1 Copy To Appropriate District Office <u>District I</u> – (575) 393-6161	State of New Mexico Energy, Minerals and Natural Resources	Form C-103 Revised July 18, 2013	
1625 N. French Dr., Hobbs, NM 88240 <u>District II</u> – (575) 748-1283 811 S. First St., Artesia, NM 88210 <u>District III</u> – (505) 334-6178 1000 Rio Brazos Rd., Aztec, NM 87410 <u>District IV</u> – (505) 476-3460 1220 S. St. Francis Dr., Santa Fe, NM 87505	OIL CONSERVATION DIVISION 1220 South St. Francis Dr. Santa Fe, NM 87505	WELL API NO. 30-015-00951 5. Indicate Type of Lease STATE FEE 6. State Oil & Gas Lease No.	
SUNDRY NOTIC (DO NOT USE THIS FORM FOR PROPOSA DIFFERENT RESERVOIR. USE "APPLICA PROPOSALS.)	ES AND REPORTS ON WELLS ALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A ATION FOR PERMIT" (FORM C-101) FOR SUCH HOBBS OCD Gas Well Other	<ul> <li>7. Lease Name or Unit Agreement Name</li> <li>Artesia Metex Unit</li> <li>8. Well Number 27</li> </ul>	
<ol> <li>Name of Operator State of New Mexico forme</li> </ol>	AUG 29 2018	9. OGRID Number 269864	
3. Address of Operator	bbbs, NM 88240 RECEIVED	RECEIVED 10. Pool name or Wildcat	
4. Well Location Unit Letter D : Section 25	990 feet from the <u>North</u> line and <u></u> Township 18S Range 27E	990 feet from the West line NMPM County Eddy	
	11. Elevation (Show whether DR, RKB, RT, GR, etc.	c.)	

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:			SUBSEQUENT REPORT OF:			
PERFORM REMEDIAL WORK	PLUG AND ABANDON	X	REMEDIAL WORK	ALTERING CASING 🗋		
TEMPORARILY ABANDON	CHANGE PLANS		COMMENCE DRILLING OPNS.	P AND A		
PULL OR ALTER CASING	MULTIPLE COMPL		CASING/CEMENT JOB			
DOWNHOLE COMMINGLE						
CLOSED-LOOP SYSTEM						
OTHER:			OTHER:			
13 Describe proposed or completed operations (Clearly state all pertinent details and give pertinent dates including estimated date						

 Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

## SEE ATTACHMENTS

Spud Date:	Rig Release Date:	
I hereby certify that the information above is true and c	omplete to the best of my knowledge and belief.	
signature Mark Witch		DATE 8/29/2018
Type or print name Mark Whitaker	E-mail address:	PHONE: 575-393-6161
APPROVED BY: Maley Show Conditions of Approval (if arry):	_TITLEAD/I	DATE 8/29/2018


Canyon E&P Company Artesia Metex Unit No. 27 30-015-00951 990' FNL & 990' FWL UL – D, Sec. 25, T18S, R27E

8 5/8" csg at 496' w/ 50 sx cmt. Open Hole 496' – 2040' TD 2040'

- 1. MIRU plugging equipment. POOH w/ production equipment.
- 2. Run in hole with tubing to 1350'. Circulate MLF.
- 3. Spot 50 sx cement. WOC & Tag.
- 4. POOH to 546'. Pump sufficient cement to circulate to surface.
- 5. Cut off wellhead 3 feet below ground level.
- 6. Verify cement to surface on all strings.
- 7. Install upright P&A marker and cut off anchors.

NOTES: Mud laden fluid consists of 9.5 ppg with 25 sx salt gel per 100 bbls of fluid. If casing will not hold pressure, contact the OCD for instructions prior to proceeding with P&A.

## Canyon E P Company Artesia Metex Unit No. 27



## Canyon E P Company Artesia Metex Unit No. 27

