Form 3160-5 (September 2001)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

HORRE O REgase Serial N

FORM APPROVED OM B No. 1004-0135 Expires: January 31, 2004

	NOTICES AND REPORTS O	HUBBS C	Print Cost 174B
	his form for proposals to drill or ell. Use Form 3160-3 (APD) for s		6. If Indian, Allottee or Tribe Name
	IPLICATE- Other instructions o	n reverence IVE	7. If Unit or CA/Agreement, Name and/or No.
1. Type of Well Oil Well O Gas Well OO Other			8. Well Name and No.
2. Name of Operator HPPC, Inc.			WH Rhodes B Federal NCT 1#9 9. API Well No.
3a. Address 3b. Phone No 306 West Wall Suite 209 432-557-50		No. (include area code) 5067	30-025-12070 10. Field and Pool, or Exploratory Area
4. Location of Well (Footage, Sec., T., R., M., or Survey Description)			Rhodes Yates Seven Rivers 11. County or Parish, State
P: 660 from South line and 66 NMPM Rhodes Field Cour	0 from East line, Section 27, Township 26S ity Lea	, Range 37E	Lea County, NM
12. CHECK A	PPROPRIATE BOX(ES) TO INDICATE	NATURE OF NOTICE,	REPORT, OR OTHER DATA
TYPE OF SUBMISSION	TYPE OF ACTION		
Subsequent Report Final Abandonment Notice	Acidize Deepen Alter Casing Fracture 7 Casing Repair New Con Change Plans Convert to Injection Plug Back	Abandon Complete Comp	
determined that the site is read 1) MIRU, ND WH, NU B 2) RU Wireline and set C 3) RIH with The: Circ ho	y for final inspection.) OP, POOH w/ Prod Equipment (if necessar IBP @ 2970'	(ער	entsurf. woc Tag
		SFF	ATTACHED FOR
CONDITIONS OF APPROVAL			
		い担果	MINONS OF AFFROVAL
14. Thereby certify that the fore Name (Printed/Typed)	going is true and correct	1	
Rajan K Prasad		Title Vice President	
Signature Harris		Date	09/18/2018
	THIS SPACE FOR FEDERA	L OR STATE OFFIC	E USE
which would entitle the applicant t		ease Office Carls	Date 9.20-18 Last field Diffice Ly to make to any department or agency of the United
States any false, fictitious or fraudu	let 3 0.5.C. Section (212, make it a crime for any matti	y person knowingly and willium er within its jurisdiction.	y to make to any department or agency of the Office

(thstructions on page 2)

FOR RECORD ONLY NMOCD 09/27/18

WBD_Rhodes9_PA

Rhodes, W.H.-B- Fed NCT-1 #9 **LEASE & WELL NO.** FORMER NAME n/a **Rhodes Yates Seven Rivers FIELD NAME** COUNTY & STATE Lea County, NM 660' FSL & 660' FEL, Sec 27, T-26-S, R-37-E LOCATION API NO. 30-025-12070 K.B. ELEV. 29981 **Proposed P&A GROUND LEVEL** 2987' 11" Hole Size **Formation Tops MD** Top of Salt 1210' Base of Salt 2713' Yates 2960' **SURFACE CASING** SIZE DEPTH WEIGHT 28# SX. CMT. 350 sx GRADE TOC @ Proposed: Spot 40 sxs (from 1400-1040 TOC @ Surface 7-7/8" Hole Size **WELL HISTORY** SPUD DATE: 10/21/1944 RR DATE: 11/16/1944 **COMPLETION DATE:** 11/23/1944 Mud Laden Fluid Proposed: Spot 50 sxs and tag at 2526' PROPOSED: CIBP @2970' Perforations: 3070-3150 **PRODUCTION CASING** SIZE WEIGHT 14# DEPTH GRADE WC-50 LTC SX. CMT. 300 sx TOC @ PBTD@ 33381 TD@ 3375

BUREAU OF LAND MANAGEMENT Carlsbad Field Office 620 East Greene Street Carlsbad, New Mexico 88220 575-234-5972

Permanent Abandonment of Federal Wells Conditions of Approval

Failure to comply with the following Conditions of Approval may result in a Notice of Incidents of Noncompliance (INC) in accordance with 43 CFR 3163.1.

1. Plugging operations shall commence within <u>ninety (90)</u> days from the approval date of this Notice of Intent to Abandon.

If you are unable to plug the well by the 90th day provide this office, prior to the 90th day, with the reason for not meeting the deadline and a date when we can expect the well to be plugged. Failure to do so will result in enforcement action.

The rig used for the plugging procedure cannot be released and moved off without the prior approval of the authorized officer. Failure to do so may result in enforcement action.

- 2. <u>Notification:</u> Contact the appropriate BLM office at least 24 hours prior to the commencing of any plugging operations. For wells in Chaves and Roosevelt County, call 575-627-0272; Eddy County, call 575-361-2822; Lea County, call 575-393-3612.
- 3. <u>Blowout Preventers</u>: A blowout preventer (BOP), as appropriate, shall be installed before commencing any plugging operation. The BOP must be installed and maintained as per API and manufacturer recommendations. The minimum BOP requirement is a 2M system for a well not deeper than 9,090 feet; a 3M system for a well not deeper than 13,636 feet; and a 5M system for a well not deeper than 22,727 feet.
- 4. <u>Mud Requirement:</u> Mud shall be placed between all plugs. Minimum consistency of plugging mud shall be obtained by mixing at the rate of 25 sacks (50 pounds each) of gel per 100 barrels of **brine** water. Minimum nine (9) pounds per gallon.
- 5. <u>Cement Requirement</u>: Sufficient cement shall be used to bring any required plug to the specified depth and length. Any given cement volumes on the proposed plugging procedure are merely estimates and are not final. Unless specific approval is received, no plug except the surface plug shall be less than 25 sacks of cement. Any plug that requires a tag will have a minimum WOC time of 4 hours.

In lieu of a cement plug across perforations in a cased hole (not for any other plugs), a bridge plug set within 50 feet to 100 feet above the perforations shall be capped with 25 sacks of cement. If a bailer is used to cap this plug, 35 feet of cement shall be sufficient. Before pumping or bailing cement on top of CIBP, tag will be required to verify depth. Based on depth, a tag of the cement may be deemed necessary.

Unless otherwise specified in the approved procedure, the cement plug shall consist of either Neat Class "C", for up to 7,500 feet of depth or Neat Class "H", for deeper than 7,500 feet plugs.

6. <u>Dry Hole Marker</u>: All casing shall be cut-off at the base of the cellar or 3 feet below final restored ground level (whichever is deeper). The BLM is to be notified a minimum of 4 hours prior to the wellhead being cut off to verify that cement is to surface in the casing and all annuluses. Wellhead cut off shall commence within ten (10) calendar days of the well being plugged. If the cut off cannot be done by the 10th day, the BLM is to be contacted with justification to receive an extension for completing the cut off.

The well bore shall then be capped with a 4-inch pipe, 10-feet in length, 4 feet above ground and embedded in cement, unless otherwise noted in COA (requirements will be attached). The following information shall be permanently inscribed on the dry hole marker: well name and number, name of the operator, lease serial number, surveyed location (quarter-quarter section, section, township and range or other authorized survey designation acceptable to the authorized officer such as metes and bounds).

- 7. <u>Subsequent Plugging Reporting:</u> Within 30 days after plugging work is completed, file one original and three copies of the Subsequent Report of Abandonment, Form 3160-5 to BLM. The report should give in detail the manner in which the plugging work was carried out, the extent (by depths) of cement plugs placed, and the size and location (by depths) of casing left in the well. **Show date well was plugged.**
- 8. <u>Trash:</u> All trash, junk and other waste material shall be contained in trash cages or bins to prevent scattering and will be removed and deposited in an approved sanitary landfill. Burial on site is not permitted.

Following the submission and approval of the Subsequent Report of Abandonment, surface restoration will be required. See attached reclamation objectives.