Submit 1 Copy To Appropriate District	State of New Mexic	Form C-103
Office District I – (575) 393-6161	Energy, Minerals and Natural	Revised August 1, 2011
1625 N. French Dr., Hobbs, NM 88240	~	WELL API NO.
District II - (575) 748-1283	OIL CONSERVATION D	IVISION 30-025-06900
811 S. First St., Artesia, NM 88210 District III – (505) 334-6178	1220 South St Grancis	5. Indicate Type of Lease
1000 Rio Brazos Rd., Aztec, NM 87410	Santa Facility 2758	
<u>District IV</u> – (505) 476-3460	Santa For M 8758	6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM 87505	K. K.	
SUNDRY NOT	ICES AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPO	SALS TO DRILL OR TO DEEPEN OR PLUT	ACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH		H T Mattern NCT B
PROPOSALS.) 1. Type of Well: Oil Well	Gas Well Other	8. Well Number: 1
2. Name of Operator	<u> </u>	9. OGRID Number
Chevron USA, Inc.		4323
3. Address of Operator		10. Pool name or Wildcat
6301 Deauville Blvd., Midland	I, TX 79706	Penrose, Skelly, Grayburg
4. Well Location		
Unit Letter I: 2310 feet from	om the SOUTH line and 330 feet from	the EAST line
Section 30 Township 21	S Range 37E, NMPM, County LEA	
	11. Elevation (Show whether DR, RI	(B, RT, GR, etc.)
	GR 3483' GL	
12. Check	Appropriate Box to Indicate Natu	re of Notice, Report or Other Data
Approved for Plugging of wellbo	re only. Liability	P
	restoration and	SUBSEQUENT REPORT OF:
inder bond is retained pending		EMEDIAL WORK
ompletion of the C-103, Specific	nav be found on	OMMENCE DRILLING OPNS. P AND A
inder bond is retained pending completion of the C-103, Specific Report of Well Plugging, which r he OCD web page under forms.	may be found on	OMMENCE DRILLING OPNS. P AND A ASING/CEMENT JOB
ompletion of the C-103, Specific Report of Well Plugging, which r	nay be found on	

17# @3652': TOC @ 2710'
Chevron USA Inc completed abandonment of this well as follows:

proposed completion or recompletion. 10 3/4" 32.75# @ 317': TOC @ surface; 7 5/8" 24# @ 1252': TOC @ surface; 5 ½"

11/12-11/13/2018: MIRU. N/U BOPE and test. Attempt to circulate clean fluid.

11/14/2018: Continue to circulate clean fluid. Mark Whittaker(NMOCD) approved pumping from tubing depth. Perforate @ 3560'. Spot 66 SKS Class C, 1.32 YLD 14.8 PPG, F/3560' T/2900'.

11/15/2018: Continue to circulate clean fluid. Spot 66 SKS Class C, 1.33 YLD 14.8 PPG.

11/16/2018: Performed bubble test – good. Tag cement @ 3650'. Found free point and cut TBG @ 3620'. Set CIBP @ 3592'.

11/17/2018: Pressure test CSG to 500 PSI twice – failed. M/U packer on tubing and TIH t/ tag CIBP @ 3590'. Spot 44 SKS Class C, 1.33 YLD 14.8 PPG, F/ 3033' T/ 3146. Spot 44 SKS Class C, 1.33 YLD 14.8 PPG, F/ 3146' T/ 2700'.

11/19/2018: Tag TOC @ 2959'. Kerry Fortner(NMOCD) approved tag and next plug depth. Perforated @ 5658'. Attempt to establish circulation rate – failed. Spot 50 SKS Class C, 1.33 YLD 14.8 PPG, F/2959' T/2508'. Tag TOC @ 2546'. Pressure test CSG twice to 500 PSI for 10 minutes – failed.

11/20/2018: Pressure test CSG to 500 PSI – failed. Noticed small leak in original CSG valve. Attempt to pressure test again to 500 PSI – failed. Notify Kerry Fortner(NMOCD) of prior tag depth and approved plan to move forward. Tag @ 2207' and found that the tubing unscrewed from the packer in the hole. Screwed back onto packer, TOH and L/D packer. Perforate casing @ 1290'. Attempt to establish circulation rate – failed.

11/28/2018: Pressure test CSG to 500 PSI – failed. Attempt to circulate clean fluid. Mark Whitaker(NMOCD) approved to leave perfs at last depth and pressure up to 1000 PSI. Established rate @ 2.5 BPM with 1000 PSI. Attempted to spot 126 SKS Class C, 1.32 YLD 14.8 PPG, F/2530' T/1300' but unable to continue after 62 SKS due to equipment malfunction. ETOC at 1924'.

11/29/2018: Pressure test CSG to 550 PSI for 15 minutes – good. Tagged TOC @ 1919'. M/P 16 BBLs MLF F/ 1917' T/

11/30/2018: Spot 25 SKS Class C, 1.32 YLD 14.8 PPG, F/ 1320' T/ 1067'. Spot 25 SKS, Class C 1.32 YLD 14.8 PPG, F/ 1067' T/ 814'. Set 5 ½" packer and attempt to squeeze cement, found leak, reverse circulated at 823'.

12/01/2018: Tag TOC @ 850'. M/P 12 BBLS MLF. Pressure up to 1000 PSI – good. Perforate @ 367'. Established rate of .5 BPM at 1000 PSI, unable to establish circulation. Spot 45 SKS Class C, 1.32 YLD 14.8 PPG, T/ surface. RDMO.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

Howie Lucas

Well Abandonment Engineer

SIGNATURE

E-mail address: howie.lucas@chevron.com PHONE: 432-687-7216

For State Use Only

APPROVED BY: Conditions of Approval (if any)

Forther TITLE Compliance Office ADATE 12-11-18