Submit 1 Copy To Appropriate District State of New Mexico Form C-103 Energy, Minerals and Natural Resources Revised August 1, 2011 District I - (575) 393-6161 WELL API NO. 1625 N. French Dr., Hobbs, NM 88240 District II - (575) 748-1283 30-025-28306 OIL CONSERVATION DIVISION 811 S. First St., Artesia, NM 88210 5. Indicate Type of Lease District III - (505) 334-6178 1220 South St. Francis Dr. STATE 🖂 FEE 1000 Rio Brazos Rd., Aztec, NM 87410 Santa Fe, NAB 2005 6. State Oil & Gas Lease No. District IV - (505) 476-3460 1220 S. St. Francis Dr., Santa Fe, NM 19552 87505 SUNDRY NOTICES AND REPORTS ON WRANGS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG B.

DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMANE" (TOTAL OR TO DEEPEN OR PLUG B.) 7. Lease Name or Unit Agreement Name South Hobbs (G/SA) Unit DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR PROPOSALS.) PROPOSALS.) 8. Well Number: COOP 3 Gas Well Other: Injector 1. Type of Well: Oil Well 2. Name of Operator 9. OGRID Number: 157984 Occidental Permian Ltd. 3. Address of Operator 10. Pool name or Wildcat Hobbs (G/SA) HCR 1 Box 90 Denver City, TX 79323 4. Well Location Unit Letter___C__645__feet from the __North__ line and ___2045__feet from the __West___ line Section Township **19S** Range 38E NMPM Lea County 11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3634' 12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK PLUG AND ABANDON П REMEDIAL WORK ALTERING CASING **TEMPORARILY ABANDON CHANGE PLANS** COMMENCE DRILLING OPNS.□ P AND A **PULL OR ALTER CASING** MULTIPLE COMPL П **CASING/CEMENT JOB** DOWNHOLE COMMINGLE OTHER: OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion. During this procedure we plan to use MIRU PU. POOH with Injection Equipment RUWL and run CIL 2. the closed-loop system with a steel Set CIBP and retainer to squeeze leak at ~4155'-4200' tank and haul contents to the required Drill out cement disposal per ODC Rule 19.15.17 RIH injection equipment and set packer at +/-4090' Circulate inhibited packer fluid Perform MIT **RDPU** Spud Date: Rig Release Date: I hereby certify that the information above is true and complete to the best of my knowledge and belief. SIGNATURE TITLE Production Engineer _DATE__06/12/2019 Type or print name/ Make Perry E-mail address: Jake Perry@oxy.com PHONE: 713-215-7546 For State Use Only Petroleum Engineer DATE 06/19/19

APPROVED BY

Conditions of Approval (if any):