Form 3160-5 5 (June 2015)

UNITED STATES DEPARTMENT OF THE INTERIOR **BUREAU OF LAND MANAGEMENT**

FORM APPROVED OMB NO. 1004-0137 Expires: January 31, 2018

SUNDRY NOTICES AND REPORTS ON WELLS

5. Lease Serial No. NMI C031695B

	IAIAI	L	UJ	ı	306	,		
-		••]	••	

Do not use thi	1 11111200010000	•						
abandoned we	6. If Indian, Allottee	6. If Indian, Allottee or Tribe Name						
SUBMIT IN	TRIPLICATE - Other inst	ructions on page 2	7. If Unit or CA/Agr 892000601H	eement, Name and/or No.				
Type of Well Oil Well	ner: INJECTION	7 2 3		8. Well Name and No. WARREN UNIT 32				
2. Name of Operator CONOCOPHILLIPS COMPAN	Contact: NY E-Mail: rogerrs@ca	RHONDA ROGERS conocophillips.com	9. API Well No. 30-025-25043-	9. API Well No. 30-025-25043-00-S1				
3a. Address 925 N ELDRIDGE PARKWAY HOUSTON, TX 77079	,	3b. Phone No. (include area code) Ph: 832-486-2737	10. Field and Pool or Exploratory Area WARREN					
4. Location of Well (Footage, Sec., 7	., R., M., or Survey Description,		11. County or Parish	11. County or Parish, State				
Sec 27 T20S R38E SESE 660	DFSL 660FEL		LEA COUNTY	LEA COUNTY, NM				
12. CHECK THE AI	PPROPRIATE BOX(ES)	TO INDICATE NATURE O	F NOTICE, REPORT, OR OT	HER DATA				
TYPE OF SUBMISSION TYPE OF ACTION								
Notice of Intent	☐ Acidize	Deepen	☐ Production (Start/Resume)	■ Water Shut-Off				
_	□ Alter Casing	☐ Hydraulic Fracturing	■ Reclamation	■ Well Integrity				
☐ Subsequent Report	□ Casing Repair	■ New Construction	☐ Recomplete	Other				
☐ Final Abandonment Notice	☐ Change Plans	Plug and Abandon	□ Temporarily Abandon	Workover Operations				
	☐ Convert to Injection	☐ Plug Back	■ Water Disposal					
Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection. Procedure 1. MIRU well service unit. 2. Kill well as necessary. Use brine if necessary. LOTO injection line. Verify. 3. ND WH. NU BOP. Function test. 4. Release injection packer and POOH w/ tubing laying down. Junk tubing. 5. MI workstring. 6. RIH with RBP and packer to ~5900'. Set RBP. Come up one joint and pressure test RBP to 500 psi. Move BRP and/or packer as needed until good pressure test. 7. Pressure test casing to surface on backside. Record results and contact engineer if cannot get good pressure test. Will likely P&A well if casing								
14. I hereby certify that the foregoing is	Electronic Submission #4 For CONOCO	188199 verified by the BLM We PHILLIPS COMPANY, sent to to essing by PRISCILLA PEREZ o	the Hobbs n 10/17/2019 (20PP0132SE)					
Name (Printed/Typed) RHONDA	ROGERS	Title REGUL	ATORY COORDINATOR					
Signature (Electronic S	Submission)	Date 10/15/2	019					
	THIS SPACE FO	R FEDERAL OR STATE	OFFICE USE					
Approved By JONATHON SHEP A Conditions of approval, if any, are attache certify that the applicant holds legal or equ which would entitle the applicant to condu	d. Approval of this notice does uitable title to those rights in the	not warrant or	UM ENGINEER	Date 10/30/2019				

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

(Instructions on page 2) ** BLM REVISED ** BLM REVISED ** BLM REVISED ** BLM REVISED **



Additional data for EC transaction #488199 that would not fit on the form

32. Additional remarks, continued

leak found.

. 1 2

leak found.

8. If good pressure test, retrieve RBP and COOH.

9. RIH w/ sandline bailer and tag for fill. PBTD at 6736'. Record fill.

10. If no fill, skep to step 11. If fill above 6500? and able to circulate, RIH with bit and clean out to 6720'. Spot 2000 gals 15% HCL NEFE acid across perforations. POOH and let sit overnight.

11. RIH with new injection packer(w/ pump out plug)and set at ~5926'. Pressure test to 500 psi. COOH.

12. Lay down workstring. Pick up new 2-3/8? TK-15 injection tubing.

13. Latch onto on/off tool. Pressure test tubing to 500 psi. Pressure test backside to 500 psi to test packer and casing.

backside to 500 psi to test packer and casing.

14. Release from on/off tool and circulate packer fluid. Latch back on to on/off tool.

15. ND BOP. NU WH.
16. Notify NMOCD of MIT test to witness.
17. Pump out plug and return to injection.

18. RDMO.

Attached is current/proposed wellbore schematic

Revisions to Operator-Submitted EC Data for Sundry Notice #488199

Operator Submitted

BLM Revised (AFMSS)

Sundry Type:

.

CSG NOI

NMLC031695B

WRK NOI

NMLC031695B

Agreement: Operator:

Lease:

CONOCOPHILLIPS COMPANY P. O. BOX 2197 SP2, 12W-155 HOUSTON, TX 77252

Ph: 832-486-2737

892000601H (NMNM71052H)

CONOCOPHILLIPS COMPANY 925 N ELDRIDGE PARKWAY HOUSTON, TX 77079

Ph: 281 206 5281

Admin Contact:

RHONDA ROGERS
REGULATORY COORDINATOR
E-Mail: rogerrs@conocophillips.com

Ph: 832-486-2737

RHONDA ROGERS REGULATORY COORDINATOR E-Mail: rogerrs@conocophillips.com

Ph: 832-486-2737

Tech Contact:

RHONDA ROGERS REGULATORY COORDINATOR E-Mail: rogers@conocophillips.com

Ph: 832-486-2737

RHONDA ROGERS REGULATORY COORDINATOR E-Mail: rogerrs@conocophillips.com

Ph: 832-486-2737

Location:

State: County:

NM LEA

NM LEA

Field/Pool:

WARREN

WARREN

Well/Facility:

WARREN BLINEBURY TUBB UNIT 032

Sec 27 T20S R38E Mer NMP SESE 660FSL 660FEL

WARREN UNIT 32

Sec 27 T20S R38E SESE 660FSL 660FEL

BUREAU OF LAND MANAGEMENT

Carlsbad Field Office 620 East Greene Street Carlsbad, New Mexico 88220 575-234-5972

Conditions of Approval for Workover/Deepening of a Well

- 1. <u>Notification:</u> Contact the appropriate BLM office at least 24 hours prior to the commencing of any operations. For wells in Eddy County, call 575-361-2822. For wells in Lea County, call 575-393-3612
- 2. <u>Blowout Preventers</u>: A blowout preventer (BOP), as appropriate, shall be installed before commencing any operation. The BOP must be installed and maintained as per API and manufacturer recommendations. The minimum BOP requirement is a 2M system for a well not deeper than 9,100 feet, a 3M system for a well not deeper than 13,600 feet, or a 5M system for a well not deeper than 22,700 feet (all depths are for measured well depth).
- 3. <u>Cement</u>: Notify BLM if cement fails to circulate.
- 4. <u>Subsequent Reporting:</u> Within 30 days after work is completed, file a Subsequent Report (Form 3160-5) to BLM. The report should give in detail the manner in which the work was carried out. <u>Show date work was completed</u>. If producing a new zone, submit a Completion Report (Form 3160-4) with the Subsequent Report.
- 5. <u>Trash</u>: All trash, junk and other waste material shall be contained in trash cages or bins to prevent scattering and will be removed and deposited in an approved sanitary landfill. Burial on site is not permitted.
- If well location is within the Timing Limitation Stipulation Area for Lesser Prairie-Chicken:
 From March 1st through June 15th annually, abandonment activities will be allowed except between the hours from 3:00 am and 9:00 am. Normal vehicle use on existing roads will not be restricted.