

Submit 1 Copy To Appropriate District Office

District I - (575) 393-6161
1625 N. French Dr., Hobbs, NM 88240
District II - (575) 748-1283
811 S. First St., Artesia, NM 88210
District III - (505) 334-6178
1000 Rio Brazos Rd., Aztec, NM 87410
District IV - (505) 476-3460
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-103
Revised July 18, 2013

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		WELL API NO. 30-025-34035
1. Type of Well: Oil Well <input checked="" type="checkbox"/> Gas Well <input type="checkbox"/> Other <input type="checkbox"/>		5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
2. Name of Operator SOUTHWEST ROYALTIES, INC.		6. State Oil & Gas Lease No. NM86025
3. Address of Operator P.O. BOX 53570; MIDLAND, TEXAS 79710-3570		7. Lease Name or Unit Agreement Name THOMAS LONG A
4. Well Location Unit Letter M : 430 feet from the SOUTH line and 560 feet from the WEST line Section 11 Township 22S Range 37E NMPM LEA County		8. Well Number #3
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3661' GR		9. OGRID Number 21355
		10. Pool name or Wildcat BLINEBRY OIL AND GAS (PRO GAS)

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	P AND A <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	MULTIPLE COMPL. <input type="checkbox"/>	CASING/CEMENT JOB <input type="checkbox"/>	PNR
DOWNHOLE COMMINGLE <input type="checkbox"/>	OTHER: <input type="checkbox"/>	OTHER: <input type="checkbox"/>	
CLOSED-LOOP SYSTEM <input type="checkbox"/>			

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

12/19/2019: MIRU PU. NDWH NU BOP. No tbg in hole. TIH w/ 45 jts tbg. SION.

12/20/2019: TIH w/ tbg to 4700'. RU CMT trucks. Test lines. Test plug @ 4730' to 520# OK. CIRC hole w/ 115 bbl MLF. Spot 25 sx cmt. POOH LD tbg to 3998' and spot 25 sx cmt balance plug. TOC @ 3753'. POOH w/tbg, RU wireline truck. TIH w/ guns. Shoot 2 holes @ 3100' Collar @ 3166'. POOH. TIH w/ tbg to 3150'. Sqz 50 sxs Class C cmt. Displace w/ 15 bbl. TOC @ 2606'. POOH w/ tbg laying down 30 jts. RU wireline. TIH w/ guns. Shoot 2 holes @ 1150' Collar @ 1160'. POOH w/ wireline. TIH w/ tbg to 1156'. Squeeze 75 sxs Class C cmt, displace w/ 2 bbl. TOC @ 455'. POOH w/ tbg LD 61 jts. RU wireline. TIH w/ guns to 400'. Shot 2 holes @ 403' Collar @ 393'. POOH RD wireline. TIH w/ tbg to 396'. RU cmt. Squeeze 90 sxs Class C cmt to surface. POOH w/ tbg LD. Circ 10 sxs Class C cmt to surface, NDBOP. RU and top off w/ 10 sxs Class C cmt. ND BOP RD CMT TKS. SION Well is P&A.

12/23/2019: Check TOC. Dump 4 SX CMT to get WH topped off. RDMO. Cleaned out pit.

****Equipment move and surface reclamation to follow***

Spud Date: **AUGUST 23, 1997** Rig Release Date: **SEPTEMBER 3, 1997**

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE _____ TITLE **REGULATORY ANALYST** DATE **01/12/2020**

Type or print name **LINDSAY LIVESAY** E-mail address: **llivesay@swrpermian.com** PHONE: **(432) 207-3054**
For State Use Only

APPROVED BY: **Kerry Fortner** TITLE **CO A** DATE **4-13-20**
Conditions of Approval (if any):