Submit 1 Copy To Appropriate District	State of New M	evico	Form C-103
Office	Energy, Minerals and Natural Resources		Revised August 1, 2011
<u>District I</u> – (575) 393-6161 1625 N. French Dr., Hobbs, NM 88240	Energy, witherars and Natural Resources		WELL API NO.
District II - (575) 748-1283	OIL CONSERVATION DIVISION		30-025-31317
811 S. First St., Artesia, NM 88210 District III - (505) 334-6178			5. Indicate Type of Lease
1000 Rio Brazos Rd., Aztec, NM 87410	1220 South St. Francis Dr.		STATE 🛛 FEE 🗌
<u>District IV</u> – (505) 476-3460	Santa Fe, NM 87505		6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM 87505			
	ICES AND REPORTS ON WELLS		7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A			
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.) 1. Type of Well: Oil Well 🛛 Gas Well 🗋 Other Injectic HOBBS		Lovington Paddock Unit	
1. Type of Well: Oil Well 🛛	Gas Well 🔲 Other Injection		8. Well Number: 107
2. Name of Operator		MAY 2 9 2020	9. OGRID Number
Chevron Midcontinent LP		MAY	4323
3. Address of Operator	ADI AND TY 20206	SENED	10. Pool name or Wildcat
6301 DEAUVILLE BLVD., N	IIDLAND, IX 79706	RECEIVED	Lovington Paddock
	<u>290</u> feet from the <u>North</u>		385feet from theWestline
Section 36	Township 16S	Range 36E	NMPM County Lea
	11. Elevation (Show whether DR	R, RKB, RT, GR, etc.)	
<u>.</u>	3,844' GL, 3,854' KB		I
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data			
	ITENTION TO:	SUB	SEQUENT REPORT OF:
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WOR			
	CHANGE PLANS	COMMENCE DRI	_
PULL OR ALTER CASING		CASING/CEMENT	
	—		
	_		_
OTHER:		OTHER:	TEMPORARILY ABANDON
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of			
proposed completion or recompletion. 8-5/8" @ 1,335' TOC Surface, 5-1/2" @ 6,450' TOC Surface. Perforations: 6,053'-			
6,363'.			
Chevron USA INC respectfully requests to abandon this well as follows:			
All Cement sack volumes are calculated using 1.32 yield for Class C and 1.18 yield for Class H. Adjust volumes to			
match footage as necessary based on the yield used at the time of execution.			
2. MIRU pulling unit.			
3. Check well pressures, kill well as necessary, perform bubble test on surface casing annuli, if bubble test fails			

- Chevron intends to Zonite, cut and pull casing, or eliminate SCP with another means after the well is plugged to a certain point agreed upon by the NMOCD and Chevron.
 - a. Bubble test should be at least 30 minutes and follow the bubble test SOP.
 - b. Bubble tests should occur each morning, critical times are prior to pumping upper hydrocarbon plug or pumping cement to surface.
 - c. Perform final bubble test after cement has hardened.
- 4. Pressure test tubing to 500 psi for 15 minutes (or highest anticipated pressure of the job).
 5 N/I I and function test rod BOP.
- 6. Laydown rod string and pump.
- 7. N/U BOP and pressure test as per SOP.
 - a. 250 psi low, MASP or 500 psi, or highest expected pressure (whichever is greater) for the job for 5 minutes each.

Conditions of Approval

- 8. Stand back tubing.
 - a. If tubing failed a pressure test, test tubing back in the well after setting CIBP.
- 9. R/U wireline unit, pressure test lubricator t/ 500 psi for 10 minutes.
- 10. M/U and set CIBP at 6,000'.
 - a. Do not run a gauge ring if TAC pulled smoothly out of the well.

- 11.TIH with open ended tubing.
 - a. Fill well with freshwater while tripping.
- 12. Tag CIBP and pressure test casing to 500 psi for 15 minutes.
- a. If casing pressure test fails, contact the engineer to add cement or pump Jet-Seal depending on LC severity.
- 13. Spot MLF, subtracting cement volumes. Do not place MLF until casing pressure tests.
- 14. Spot 25 sx CL "C" cement f/ 6,000' t/ 5,754' (Perfs).
 - a. TOC must be at 5,900' or shallower.
 - b. Discuss with NMOCD on waiving WOC and tag if casing passed a pressure test.
- 15. Spot 40 sx CL "C" cement f/ 4,652' t/ 4,257' (San Andres, Grayburg).
 - a. TOC must be at 4,297' or shallower.
- 16. Spot 25 sx CL "C" cement f/ 3,095' t/ 2,849' (Yates).
 - a. TOC must be at 2,968' or shallower.
- 17. Spot 145 sx CL "C" cement f/ 1,385' t/ Surface (Shoe, FW).a. Deepest freshwater zone in the area is ~79'.
- 18. Cut all casings & anchors & remove 3' below grade. <u>Verify</u> cement to surface & weld on dry hole marker (4" diameter, 4' tall). Clean location.

Note: All cement plugs class "C" (<7,500') or "H" (>7,500') with closed loop system used, and MLF spotted between plugs.

 I hereby certify that the information above is true and complete to the best of my knowledge and belief.

 SIGNATURE
 IIILE

 P&A Engineer, Attorney in fact
 DATE


 05/26/2020

 Type or print name <u>Howie Lucas</u>
 E-mail address: <u>howie.lucas@chevron.com</u>
 PHONE: <u>(832)-588-4044</u>

 For State Use Only
 A

Jut TITLE COA DATE 5-29-20 APPROVED BY: Conditions of Approval (if ap

Wellbore Diagram



Wellbore Diagram

