
Office <u>District I</u> – (575) 393-6161	State of New Mexico	Form C-103		
	Energy, Minerals and Natural Resources	Revised July 18, 2013		
1625 N. French Dr., Hobbs, NM 88240 <u>District II</u> – (575) 748-1283	ı	WELL API NO.		
811 S. First St., Artesia, NM 88210	OIL CONSERVATION DIVISION	30-025-10548 5. Indicate Type of Lease		
District III - (505) 334-6178	1220 South St. Francis Dr.	STATE STATE		
1000 Rio Brazos Rd., Aztec, NM 8741 <u>District IV</u> – (505) 476-3460	Santa Fe, NM 87505	6. State Oil & Gas Lease No.		
1220 S. St. Francis Dr., Santa Fe, NM 87505				
SUNDRY N	OTICES AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name		
(DO NOT USE THIS FORM FOR PRO	OPOSALS TO DRILL OR TO DEEPEN OR PLUG ACK TO A	LANGLIE MATTIX PENROSE SAND		
PROPOSALS.)	OTICES AND REPORTS ON WELLS  POSALS TO DRILL OR TO DEEPEN OR PLUG TO A  PLICATION FOR PERMIT" (FORM C-101) FOR SUCCESS	UNIT		
1. Type of Well: Oil Well	Gas Well Cother INTECTION .	Well Number 301		
2. Name of Operator	$18_{20}$	9. OGRID Number		
3. Address of Operator	BOX 10848, MIDLAND, TX 79702	10. Pool name or Wildcat		
	. BOX 10848, MIDLAND, TX 79702	LANGLIE MATTIX;7RVRS-Q-GB		
4. Well Location				
Unit Letter A	: 330 feet from the NORTH line and	330 feet from the EAST line		
Section 32	Township 22S Range 37E	NMPM County LEA		
	11. Elevation (Show whether DR, RKB, RT, GR, etc.			
,	3834' GL			
12. Chec	k Appropriate Box to Indicate Nature of Notice	, Report or Other Data		
		-		
		BSEQUENT REPORT OF:		
PERFORM REMEDIAL WORK	<del>-</del> -	<del></del>		
	<del>-</del>	RILLING OPNS. P AND A		
	MULTIPLE COMPL   CASING/CEMEN	IL JOB		
CLOSED-LOOP SYSTEM OTHER:	□   OTHER:	п		
	mpleted operations. (Clearly state all pertinent details, ar	nd give pertinent dates, including estimated date		
	work). SEE RULE 19.15.7.14 NMAC. For Multiple Co			
proposed completion or	recompletion.			
proposed completion or	recompletion.			
proposed completion or				
	t well be placed in TA status for four years due to the cur	rent situation the oil industry is in.		
		rent situation the oil industry is in.		
We are requesting the subject		rent situation the oil industry is in.		
We are requesting the subject  Procedure:	t well be placed in TA status for four years due to the cur	·		
We are requesting the subject Procedure: POH with production equipm		5' of cement. Tag cement top. Circulate		
We are requesting the subject Procedure: POH with production equipm	t well be placed in TA status for four years due to the cur sent. RIH with CIBP. Set CIBP at 3,442' and cap with 35	5' of cement. Tag cement top. Circulate		
We are requesting the subject Procedure: POH with production equipm	t well be placed in TA status for four years due to the cur nent. RIH with CIBP. Set CIBP at 3,442' and cap with 3. rt fluid. Notify OCD for MIT and perform MIT on well.	5' of cement. Tag cement top. Circulate Wellbore diagram attached.		
We are requesting the subject Procedure: POH with production equipm	t well be placed in TA status for four years due to the cur nent. RIH with CIBP. Set CIBP at 3,442' and cap with 3. rt fluid. Notify OCD for MIT and perform MIT on well.	5' of cement. Tag cement top. Circulate Wellbore diagram attached.		
We are requesting the subject Procedure: POH with production equipm	t well be placed in TA status for four years due to the cur nent. RIH with CIBP. Set CIBP at 3,442' and cap with 33 rt fluid. Notify OCD for MIT and perform MIT on well.	of cement. Tag cement top. Circulate Wellbore diagram attached.		
We are requesting the subject Procedure: POH with production equipm	t well be placed in TA status for four years due to the cur tent. RIH with CIBP. Set CIBP at 3,442' and cap with 35 rt fluid. Notify OCD for MIT and perform MIT on well.	of cement. Tag cement top. Circulate. Wellbore diagram attached.  Ondition of Approval: notify		
We are requesting the subject Procedure: POH with production equipm	t well be placed in TA status for four years due to the cur tent. RIH with CIBP. Set CIBP at 3,442' and cap with 35 rt fluid. Notify OCD for MIT and perform MIT on well.	of cement. Tag cement top. Circulate. Wellbore diagram attached.  Ondition of Approval: notify		
We are requesting the subject Procedure: POH with production equipm	t well be placed in TA status for four years due to the cur tent. RIH with CIBP. Set CIBP at 3,442' and cap with 35 rt fluid. Notify OCD for MIT and perform MIT on well.	of cement. Tag cement top. Circulate. Wellbore diagram attached.  Ondition of Approval: notify		
We are requesting the subject Procedure: POH with production equipm well and load casing with ine	t well be placed in TA status for four years due to the cur tent. RIH with CIBP. Set CIBP at 3,442' and cap with 35 rt fluid. Notify OCD for MIT and perform MIT on well.	of cement. Tag cement top. Circulate Wellbore diagram attached.		
We are requesting the subject Procedure: POH with production equipm well and load casing with ine	t well be placed in TA status for four years due to the cur tent. RIH with CIBP. Set CIBP at 3,442' and cap with 35 rt fluid. Notify OCD for MIT and perform MIT on well.	of cement. Tag cement top. Circulate. Wellbore diagram attached.  Ondition of Approval: notify		
We are requesting the subject Procedure: POH with production equipm well and load casing with ine	t well be placed in TA status for four years due to the cur tent. RIH with CIBP. Set CIBP at 3,442' and cap with 35 rt fluid. Notify OCD for MIT and perform MIT on well.	o' of cement. Tag cement top. Circulate Wellbore diagram attached.  Ondition of Approval: notify  CD Hobbs office 24 hours  of running MIT Test & Chart		
We are requesting the subject Procedure: POH with production equipm well and load casing with ine	t well be placed in TA status for four years due to the cur nent. RIH with CIBP. Set CIBP at 3,442' and cap with 33 rt fluid. Notify OCD for MIT and perform MIT on well.  Co  Prior  Rig Release Date:	o' of cement. Tag cement top. Circulate Wellbore diagram attached.  Ondition of Approval: notify  CD Hobbs office 24 hours  of running MIT Test & Chart		
We are requesting the subject Procedure: POH with production equipm well and load casing with ine  Spud Date:  I hereby certify that the information	t well be placed in TA status for four years due to the current. RIH with CIBP. Set CIBP at 3,442' and cap with 33 rt fluid. Notify OCD for MIT and perform MIT on well.  Co  Prior  Rig Release Date:	of cement. Tag cement top. Circulate. Wellbore diagram attached.  Ondition of Approval: notify CD Hobbs office 24 hours of running MIT Test & Chart  ge and belief.		
We are requesting the subject Procedure: POH with production equipm well and load casing with ine	t well be placed in TA status for four years due to the cur nent. RIH with CIBP. Set CIBP at 3,442' and cap with 33 rt fluid. Notify OCD for MIT and perform MIT on well.  Co  Prior  Rig Release Date:	of cement. Tag cement top. Circulate. Wellbore diagram attached.  Ondition of Approval: notify CD Hobbs office 24 hours of running MIT Test & Chart  ge and belief.		
We are requesting the subject Procedure: POH with production equipm well and load casing with ine  Spud Date:  I hereby certify that the information such as the subject of	t well be placed in TA status for four years due to the current. RIH with CIBP. Set CIBP at 3,442' and cap with 32 rt fluid. Notify OCD for MIT and perform MIT on well.  Conception  Rig Release Date:  TITLE COMPLIANCE COOR	of cement. Tag cement top. Circulate Wellbore diagram attached.  Ondition of Approval: notify  CD Hobbs office 24 hours  of running MIT Test & Chart  ge and belief.  DINATOR DATE 05/21/2020		
We are requesting the subject  Procedure: POH with production equipm well and load casing with ine  Spud Date:  I hereby certify that the information of the subject of the	t well be placed in TA status for four years due to the current. RIH with CIBP. Set CIBP at 3,442' and cap with 33 rt fluid. Notify OCD for MIT and perform MIT on well.  Co  Prior  Rig Release Date:	of cement. Tag cement top. Circulate Wellbore diagram attached.  Ondition of Approval: notify  CD Hobbs office 24 hours  of running MIT Test & Chart  ge and belief.  DINATOR DATE 05/21/2020		
We are requesting the subject Procedure: POH with production equipm well and load casing with ine  Spud Date:  I hereby certify that the information such as the subject of	t well be placed in TA status for four years due to the current. RIH with CIBP. Set CIBP at 3,442' and cap with 32 rt fluid. Notify OCD for MIT and perform MIT on well.  Conception  Rig Release Date:  TITLE COMPLIANCE COOR	of cement. Tag cement top. Circulate Wellbore diagram attached.  Ondition of Approval: notify  CD Hobbs office 24 hours  of running MIT Test & Chart  ge and belief.  DINATOR DATE 05/21/2020		
We are requesting the subject  Procedure: POH with production equipm well and load casing with ine  Spud Date:  I hereby certify that the information of the subject of the	t well be placed in TA status for four years due to the current. RIH with CIBP. Set CIBP at 3,442' and cap with 32 rt fluid. Notify OCD for MIT and perform MIT on well.  Conception  Rig Release Date:  TITLE COMPLIANCE COOR	of cement. Tag cement top. Circulate Wellbore diagram attached.  Ondition of Approval: notify  CD Hobbs office 24 hours  of running MIT Test & Chart  ge and belief.  DINATOR DATE 05/21/2020		

Printed: 5/20/2020



## **Wellbore Schematic**

Printed: 5/20/2020

Page 2

LMPSU # 301 BOLO ID: 300029.30.01 API # 3002510548

Rods						Date Ran:	1/3/2012
Description	#	Diameter	Rod Box	Grade	Length	Top At	Btm At
Polish Rod	1	1.2500			22.00	0.00	22.00
Polish Rod Liner	1	1.5000			8.00	14.00	22.00
Pony Rods	4	0.8750	SH SM		18.00	22.00	40.00
Rods	48	0.8750	SH SM		1,200.00	40.00	1,240.00
Rods	96	0.7500	Full SM		2,400.00	1,240.00	3,640.00
Rods	1	0.8750	SH SM		1.00	3,640.00	3,641.00
Pump	1	1.5000			16.00	3,641.00	3,657.00