Submit 1 Copy To Appropriate District State of New Mexico Form C-103 Office Revised July 18, 2013 Energy, Minerals and Natural Resources District 1 - (575) 393-6161 WELL API NO. 1625 N. French Dr., Hobbs, NM 88240 30-025-31658 District II - (575) 748-1283 OIL CONSERVATION DIVISION 811 S. First St., Artesia, NM 88210 5. Indicate Type of Lease District III - (505) 334-6178 1220 South St. Francis Dr. \boxtimes STATE [FEE 1000 Rio Brazos Rd., Aztec, NM 87410 Santa Fe, NM 87505 6. State Oil & Gas Lease No. District IV - (505) 476-3460 1220 S. St. Francis Dr., Santa Fe, NM 87505 SUNDRY NOTICES AND REPORTS ON WELLS 7. Lease Name or Unit Agreement Name (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR PROPOSALS.) Langlie Mattix Penrose Sand Unit 8. Well Number 105 1. Type of Well: Oil Well Gas Well Gother LEGACY RESERVES OPERATING LAUL 3 0 2020 9. OGRID Number 2. Name of Operator 240974 3. Address of Operator 10. Pool name or Wildcat P.O. BOX 10848, MIDLAND, TX 797 RECEI Langlie Mattix;7 Rvrs-Queen-Grayburg 4. Well Location Unit Letter 1390 feet from the SOUTH line and 1339 feet from the EAST line Section 21 **Township 22S** Range 37E **NMPM** County LEA 11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3362' RKB 12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: ALTERING CASING [PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK П **TEMPORARILY ABANDON** 図 **CHANGE PLANS** COMMENCE DRILLING OPNS.□ P AND A PULL OR ALTER CASING Π **MULTIPLE COMPL** П **CASING/CEMENT JOB** DOWNHOLE COMMINGLE **CLOSED-LOOP SYSTEM** OTHER: OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion. We are requesting the subject well be placed in TA status for four years due to the current situation the oil industry is in. Procedure: POH with production equipment. RIH with CIBP. Set CIBP at 3,462' and cap with 35' of cement. Tag cement top. Circulate well and load easing with inert fluid. Notify OCD for MIT and perform MIT on well. Wellbore diagram attached. Condition of Approval: notify OCD Hobbs office 24 hours prior of running MIT Test & Chart Spud Date: Rig Release Date: I hereby certify that the information above is true and complete to the best of my knowledge and belief. **SIGNATURE** TITLE COMPLIANCE COORDINATOR DATE **MELANIE REYES** Type or print name E-mail address: mreyes@legacyreserves.com PHONE: 432-221-6358 For State Use Only APPROVED BY:

Conditions of Approval (if any